Rose, Charles

From: Sent: To: Cc: Subject: John Lee [John Lee@scottwilson.com] 04 January 2007 15:47 Rose, Charles Ivor Chandler; John Monoogian (E-mail) 4 - 5 Raymond buildings

Charlie

The form of the screen is to be a new element placed within the historic building touching the historic fabric and not cutting in to it. The glassed screens will be scribed around existing features such as cornices with a soft silicon joint approximately 10mm wide between the screen and the feature, if necessary a separation membrane adjacent to the historic fabric will be incorporated.

john lee

John Lee Principal Structural Engineer Scott Wilson incorporating Cameron Taylor - London T. 020 7298 0737 M. 07866 431 548 W. scottwilson.com

Cameron Taylor is now delighted to be part of UK and international consultancy Scott Wilson. Our existing contracts and agreements as Cameron Taylor will continue. New contracts and agreements will be with Scott Wilson. No transfer, or assignment, to a different company is implied.

Cameron Taylor is delighted to be now part of UK and international consultancy Scott Wilson and our email addresses have been transferred to scottwilson.com. Existing camerontaylor.co.uk addresses will continue to be serviced. Our existing contracts and agreements as Cameron Taylor will continue, new contracts and agreements will be with Scott Wilson. No transfer or assignment to a different trading company is implied. Please also see www.scottwilson.com.

This message (and any associated files) is intended only for the use of the individual or entity to which it is addressed and may contain information that is confidential, subject to copyright or constitutes a trade secret. If you are not the intended recipient you are hereby notified that any dissemination, copying or distribution of this message, or files associated with this message, is strictly prohibited. If you have received this message in error, please notify us immediately by replying to the message and deleting it from your computer. Messages sent to and from us may be monitored.

Internet communications cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. Therefore, we do not accept responsibility for any errors or omissions that are present in this message, or any attachment, that have arisen as a result of e-mail transmission. If verification is required, please request a hard-copy version. Any views or opinions presented are solely those of the author and do not necessarily represent those of the company.

1098t/ 9800/

20061 SOULAI