

revision: D

Proposed Site Plan job name: Belsize Crescent 782 1:100@A2 17 May 2013 782/P/100

architecture & design 342 old street: shoreditch london:ec1v:9ds t +44 (0)20 7729 7729 f +44 (0)20 7729 7791

Existing ridge height, front balustrade height and side elevation windows corrected as per existing drawings.

Proposal revised to retain original roof in response to

Revisions:

Revision A - 21.03.14


neighbours' objections.

Revision B - 25.04.14 Existing eaves and guttering corrected as per existing drawings.

Roof finished revised and rooflights added to rear elevations. Notes updated accordingly.

Revision C - 17.06.14 Alterations to front elevation and front roof slope omitted. Revision D - 18.06.14 Render removed from rear elevation and general corrections

www.splashofmilk.com



GENERAL NOTES:

COPYRIGHT TO THESE DRAWINGS AND THE DESIGNS SHOWN THEREIN ARE RETAINED BY MILK
THESE DRAWINGS ARE FOR INFORMATION ONLY (THEY SHOULD NOT BE SCALED FROM)
ALL DIMENSIONS SHOULD BE VERIFIED ON SITE
ANY DISCREPANCIES IN THE DRAWINGS SHOULD BE BROUGHT TO THE ATTENTION OF MILK
ANY VARIATIONS FROM THESE DRAWINGS SHOULD BE APPROVED BY MILK

Notes:

Survey:

These drawings have been based on survey drawings by others. All setting out to be checked on site before construction.

All gridlines centred on existing walls and/or structure at ground floor

Planning Key:

FRONT ELEVATION

REPAIR WORKS ONLY TO BE CARRIED OUT TO FRONT **ELEVATION:**

11

12

13

ROOF

TO BE REFURBISHED & RE-FINISHED UNDER PERMITTED DEVELOPMENT CLASS C COMPLYING WITH THE CONDITION C.1:

(a) the alteration would not protrude more than 150mm beyond the plane of the slope of the original roof when measured perpendicular with the external surface of the original roof.

Existing asphalt finish on rear roof slopes to be replaced with standing seam lead roof to match the leadwork on the front dormer of the main

Existing asphalt finish on front roof slope and ridge to be repaired or replaced like for like as necessary.

Two conservation style rooflights added to the rear slope of the roof.

The relationship between the existing roof and the neighbour's existing side stair window is unchanged.

The existing flashings to numbers 19 and 21 to be retained and repaired if necessary. Any repair that affects the party wall with number 19 to be dealt with via the party wall process.

Existing roof structure to be repaired or replaced as necessary. Any replacement that affects the party wall with number 19 to be dealt with via the party wall process.

Existing fascia boards to be refurbished or replaced like for like and new leadwork lapped into new gutters and downpipes to match

REAR ELEVATION

TO BE ALTERED AND REFURBISHED UNDER PERMITTED DEVELOPMENT CLASS A FOLLOWING THE CONDITION A.3:

(a) the materials used in any exterior work shall be of similar appearance to those used in the construction of the exterior of the existing dwellinghouse.

Existing brickwork to the rear elevation to be improved, infilled and repaired as necessary. Brickwork to be cleaned, repointed and left

The relationship between the rear wall of the side extension and neighbour's existing lower ground floor window is unchanged.

New opening to be created symmetrically in rear elevation for traditional timber framed concertina doors to be set into. Doors to be set back into the façade behind traditional half brick reveals.

Revisions:

Revision A - 21.03.14 Proposal revised to retain original roof in response to neighbours'

Existing ridge height, front balustrade height and side elevation windows corrected as per existing drawings.

Revision B - 25.04.14

Existing eaves and guttering corrected as per existing drawings.

Roof finished revised and rooflights added to rear elevations. Notes updated accordingly.


Revision C - 17.06.14 Alterations to front elevation and front roof slope omitted.

Revision D - 18.06.14
Render removed from rear elevation and general corrections to notes.

D

Proposed Lower GF Plan Belsize Crescent 782 1:50@A2 17 May 2013 782/P/109





GENERAL NOTES:

COPYRIGHT TO THESE DRAWINGS AND THE DESIGNS SHOWN THEREIN ARE RETAINED BY MILK
THESE DRAWINGS ARE FOR INFORMATION ONLY (THEY SHOULD NOT BE SCALED FROM)
ALL DIMENSIONS SHOULD BE VERIFIED ON SITE
ANY DISCREPANCIES IN THE DRAWINGS SHOULD BE BROUGHT TO THE ATTENTION OF MILK
ANY VARIATIONS FROM THESE DRAWINGS SHOULD BE APPROVED BY MILK

Notes:

Survey:

These drawings have been based on survey drawings by others. All setting out to be checked on site before construction.

All gridlines centred on existing walls and/or structure at ground floor

Planning Key:

FRONT ELEVATION

REPAIR WORKS ONLY TO BE CARRIED OUT TO FRONT **ELEVATION:**

11

12

13

ROOF

TO BE REFURBISHED & RE-FINISHED UNDER PERMITTED DEVELOPMENT CLASS C COMPLYING WITH THE CONDITION C.1:

(a) the alteration would not protrude more than 150mm beyond the plane of the slope of the original roof when measured perpendicular with the external surface of the original roof.

Existing asphalt finish on rear roof slopes to be replaced with standing seam lead roof to match the leadwork on the front dormer of the main

Existing asphalt finish on front roof slope and ridge to be repaired or replaced like for like as necessary.

Two conservation style rooflights added to the rear slope of the roof.

The relationship between the existing roof and the neighbour's existing side stair window is unchanged.

The existing flashings to numbers 19 and 21 to be retained and repaired if necessary. Any repair that affects the party wall with number 19 to be dealt with via the party wall process.

Existing roof structure to be repaired or replaced as necessary. Any replacement that affects the party wall with number 19 to be dealt with via the party wall process.

Existing fascia boards to be refurbished or replaced like for like and new leadwork lapped into new gutters and downpipes to match

REAR ELEVATION

TO BE ALTERED AND REFURBISHED UNDER PERMITTED DEVELOPMENT CLASS A FOLLOWING THE CONDITION A.3:

(a) the materials used in any exterior work shall be of similar appearance to those used in the construction of the exterior of the existing dwellinghouse.

Existing brickwork to the rear elevation to be improved, infilled and repaired as necessary. Brickwork to be cleaned, repointed and left

The relationship between the rear wall of the side extension and neighbour's existing lower ground floor window is unchanged.

New opening to be created symmetrically in rear elevation for traditional timber framed concertina doors to be set into. Doors to be set back into the façade behind traditional half brick reveals.

Revisions:

Revision A - 21.03.14

Proposal revised to retain original roof in response to neighbours'

Existing ridge height, front balustrade height and side elevation windows corrected as per existing drawings.

Revision B - 25.04.14

Existing eaves and guttering corrected as per existing drawings.

Roof finished revised and rooflights added to rear elevations. Notes updated accordingly.

Revision C - 17.06.14


Alterations to front elevation and front roof slope omitted.

Revision D - 18.06.14

Render removed from rear elevation and general corrections to notes.

Proposed Raised GF Plan Belsize Crescent 782 1:50@A2 17 May 2013 782/P/110 D





GENERAL NOTES:

COPYRIGHT TO THESE DRAWINGS AND THE DESIGNS SHOWN THEREIN ARE RETAINED BY MILK
THESE DRAWINGS ARE FOR INFORMATION ONLY (THEY SHOULD NOT BE SCALED FROM)
ALL DIMENSIONS SHOULD BE VERIFIED ON SITE
ANY DISCREPANCIES IN THE DRAWINGS SHOULD BE BROUGHT TO THE ATTENTION OF MILK
ANY VARIATIONS FROM THESE DRAWINGS SHOULD BE APPROVED BY MILK

Notes:

Survey:

These drawings have been based on survey drawings by others. All setting out to be checked on site before construction.

All gridlines centred on existing walls and/or structure at ground floor

Planning Key:

FRONT ELEVATION

REPAIR WORKS ONLY TO BE CARRIED OUT TO FRONT **ELEVATION:**

12

13

ROOF

TO BE REFURBISHED & RE-FINISHED UNDER PERMITTED DEVELOPMENT CLASS C COMPLYING WITH THE CONDITION C.1:

(a) the alteration would not protrude more than 150mm beyond the plane of the slope of the original roof when measured perpendicular with the external surface of the original roof.

Existing asphalt finish on rear roof slopes to be replaced with standing seam lead roof to match the leadwork on the front dormer of the main

Existing asphalt finish on front roof slope and ridge to be repaired or replaced like for like as necessary.

Two conservation style rooflights added to the rear slope of the roof.

The relationship between the existing roof and the neighbour's existing side stair window is unchanged.

The existing flashings to numbers 19 and 21 to be retained and repaired if necessary. Any repair that affects the party wall with number 19 to be dealt with via the party wall process.

Existing roof structure to be repaired or replaced as necessary. Any replacement that affects the party wall with number 19 to be dealt with via the party wall process.

Existing fascia boards to be refurbished or replaced like for like and new leadwork lapped into new gutters and downpipes to match

REAR ELEVATION


TO BE ALTERED AND REFURBISHED UNDER PERMITTED DEVELOPMENT CLASS A FOLLOWING THE CONDITION A.3:

(a) the materials used in any exterior work shall be of similar appearance to those used in the construction of the exterior of the existing dwellinghouse.

Existing brickwork to the rear elevation to be improved, infilled and repaired as necessary. Brickwork to be cleaned, repointed and left

The relationship between the rear wall of the side extension and neighbour's existing lower ground floor window is unchanged.

New opening to be created symmetrically in rear elevation for traditional timber framed concertina doors to be set into. Doors to be set back into the façade behind traditional half brick reveals.



Revisions:

Revision A - 21.03.14 Proposal revised to retain original roof in response to neighbours'

Existing ridge height, front balustrade height and side elevation windows corrected as per existing drawings.

Revision B - 25.04.14

Existing eaves and guttering corrected as per existing drawings.


Roof finished revised and rooflights added to rear elevations. Notes updated accordingly.

Revision C - 17.06.14 Alterations to front elevation and front roof slope omitted.


Revision D - 18.06.14
Render removed from rear elevation and general corrections to

Proposed First Floor Plan Belsize Crescent 782 1:50@A2 17 May 2013 782/P/111 D





Second Floor Plan



Third Floor Plan

GENERAL NOTES:

GENERAL NOTES:

COPYRIGHT TO THESE DRAWINGS AND THE DESIGNS SHOWN THEREIN ARE RETAINED BY MILK
THESE DRAWINGS ARE FOR INFORMATION ONLY (THEY SHOULD NOT BE SCALED FROM)
ALL DIMENSIONS SHOULD BE VERIFIED ON SITE
ANY DISCREPANCIES IN THE DRAWINGS SHOULD BE BROUGHT TO THE ATTENTION OF MILK
ANY VARIATIONS FROM THESE DRAWINGS SHOULD BE APPROVED BY MILK

Notes:

Survey:

These drawings have been based on survey drawings by others. All setting out to be checked on site before construction.

All gridlines centred on existing walls and/or structure at ground floor

Planning Key:

FRONT ELEVATION

REPAIR WORKS ONLY TO BE CARRIED OUT TO FRONT **ELEVATION:**

13

ROOF

TO BE REFURBISHED & RE-FINISHED UNDER PERMITTED DEVELOPMENT CLASS C COMPLYING WITH THE CONDITION C.1:

(a) the alteration would not protrude more than 150mm beyond the plane of the slope of the original roof when measured perpendicular with the external surface of the original roof.

Existing asphalt finish on rear roof slopes to be replaced with standing seam lead roof to match the leadwork on the front dormer of the main

Existing asphalt finish on front roof slope and ridge to be repaired or

replaced like for like as necessary.

Two conservation style rooflights added to the rear slope of the roof.

The relationship between the existing roof and the neighbour's existing side stair window is unchanged.

The existing flashings to numbers 19 and 21 to be retained and repaired if necessary. Any repair that affects the party wall with number 19 to be dealt with via the party wall process.

Existing roof structure to be repaired or replaced as necessary. Any replacement that affects the party wall with number 19 to be dealt with via the party wall process.

Existing fascia boards to be refurbished or replaced like for like and new leadwork lapped into new gutters and downpipes to match

REAR ELEVATION

TO BE ALTERED AND REFURBISHED UNDER PERMITTED DEVELOPMENT CLASS A FOLLOWING THE CONDITION A.3:

(a) the materials used in any exterior work shall be of similar appearance to those used in the construction of the exterior of the existing dwellinghouse.

Existing brickwork to the rear elevation to be improved, infilled and repaired as necessary. Brickwork to be cleaned, repointed and left

The relationship between the rear wall of the side extension and neighbour's existing lower ground floor window is unchanged.

New opening to be created symmetrically in rear elevation for traditional timber framed concertina doors to be set into. Doors to be set back into the façade behind traditional half brick reveals.

Revisions:

Revision A - 21.03.14 Proposal revised to retain original roof in response to neighbours'

Existing ridge height, front balustrade height and side elevation windows corrected as per existing drawings.

Revision B - 25.04.14

Existing eaves and guttering corrected as per existing drawings.

Roof finished revised and rooflights added to rear elevations. Notes updated accordingly.

Revision C - 17.06.14 Alterations to front elevation and front roof slope omitted.

Revision D - 18.06.14 Render removed from rear elevation and general corrections to notes.

Proposed 2F & 3F Plan Belsize Crescent 782 1:50@A2 17 May 2013 782/P/112 D







Rear Site Elevation

Front Site Elevation

Revisions:

Revision A - 21.03.14 Proposal revised to retain original roof in response to neighbours'

Existing ridge height, front balustrade height and side elevation windows corrected as per existing drawings.

Revision B - 25.04.14

Existing eaves and guttering corrected as per existing drawings.

Roof finished revised and rooflights added to rear elevations. Notes updated accordingly.

Revision C - 17.06.14 Alterations to front elevation and front roof slope omitted.

Revision D - 18.06.14
Render removed from rear elevation and general corrections to

drawing title: Proposed Site Elevations job name: Belsize Crescent job number: 782 1:100@A2 17 May 2013 782/P/210

GENERAL NOTES:

Notes: Survey:

Gridlines:

Planning Key: FRONT ELEVATION

ELEVATION:

13

ROOF

GENERAL NOTES:

OPPRIGHT TO THESE DRAWINGS AND THE DESIGNS SHOWN THEREIN ARE RETAINED BY MILK THESE DRAWINGS ARE FOR INFORMATION ONLY (THEY SHOULD NOT BE SCALED FROM) ALL DIMENSIONS SHOULD BE VERIFIED ON SITE

ANY DISCREPANCES IN THE DRAWINGS SHOULD BE BROUGHT TO THE ATTENTION OF MILK

These drawings have been based on survey drawings by others. All setting out to be checked on site before construction.

All gridlines centred on existing walls and/or structure at ground floor

REPAIR WORKS ONLY TO BE CARRIED OUT TO FRONT

TO BE REFURBISHED & RE-FINISHED UNDER PERMITTED DEVELOPMENT CLASS C COMPLYING WITH THE CONDITION C.1:

(a) the alteration would not protrude more than 150mm beyond the plane of the slope of the original roof when measured perpendicular with the external surface of the original roof.

Existing asphalt finish on rear roof slopes to be replaced with standing seam lead roof to match the leadwork on the front dormer of the main

Existing asphalt finish on front roof slope and ridge to be repaired or

Two conservation style rooflights added to the rear slope of the roof.

The relationship between the existing roof and the neighbour's existing

The existing flashings to numbers 19 and 21 to be retained and repaired if necessary. Any repair that affects the party wall with number 19 to be dealt with via the party wall process.

Existing roof structure to be repaired or replaced as necessary. Any replacement that affects the party wall with number 19 to be dealt with

Existing fascia boards to be refurbished or replaced like for like and new leadwork lapped into new gutters and downpipes to match

TO BE ALTERED AND REFURBISHED UNDER PERMITTED DEVELOPMENT CLASS A FOLLOWING THE CONDITION A.3: (a) the materials used in any exterior work shall be of similar appearance to those used in the construction of the exterior of the

Existing brickwork to the rear elevation to be improved, infilled and

repaired as necessary. Brickwork to be cleaned, repointed and left

The relationship between the rear wall of the side extension and neighbour's existing lower ground floor window is unchanged.

New opening to be created symmetrically in rear elevation for traditional timber framed concertina doors to be set into. Doors to be

set back into the façade behind traditional half brick reveals.

side stair window is unchanged.

via the party wall process.


existing.


REAR ELEVATION

ANY VARIATIONS FROM THESE DRAWINGS SHOULD BE APPROVED BY MILK



t +44 (0)20 7729 7729 f +44 (0)20 7729 7791





Front Elevation Rear Elevation GENERAL NOTES: GENERAL NOTES:

OPPRIGHT TO THESE DRAWINGS AND THE DESIGNS SHOWN THEREIN ARE RETAINED BY MILK THESE DRAWINGS ARE FOR INFORMATION ONLY (THEY SHOULD NOT BE SCALED FROM) ALL DIMENSIONS SHOULD BE VERIFIED ON SITE

ANY DISCREPANCES IN THE DRAWINGS SHOULD BE BROUGHT TO THE ATTENTION OF MILK ANY VARIATIONS FROM THESE DRAWINGS SHOULD BE APPROVED BY MILK

Notes:

Survey:

These drawings have been based on survey drawings by others. All setting out to be checked on site before construction.

Gridlines:

All gridlines centred on existing walls and/or structure at ground floor

Planning Key:

FRONT ELEVATION

REPAIR WORKS ONLY TO BE CARRIED OUT TO FRONT **ELEVATION:**

11

12

13

ROOF

TO BE REFURBISHED & RE-FINISHED UNDER PERMITTED DEVELOPMENT CLASS C COMPLYING WITH THE CONDITION C.1:

(a) the alteration would not protrude more than 150mm beyond the plane of the slope of the original roof when measured perpendicular with the external surface of the original roof.

Existing asphalt finish on rear roof slopes to be replaced with standing

seam lead roof to match the leadwork on the front dormer of the main

Existing asphalt finish on front roof slope and ridge to be repaired or

Two conservation style rooflights added to the rear slope of the roof.

The relationship between the existing roof and the neighbour's existing side stair window is unchanged.

The existing flashings to numbers 19 and 21 to be retained and repaired if necessary. Any repair that affects the party wall with number 19 to be dealt with via the party wall process.

Existing roof structure to be repaired or replaced as necessary. Any replacement that affects the party wall with number 19 to be dealt with via the party wall process.

25
Existing fascia boards to be refurbished or replaced like for like and new leadwork lapped into new gutters and downpipes to match existing.

REAR ELEVATION

TO BE ALTERED AND REFURBISHED UNDER PERMITTED DEVELOPMENT CLASS A FOLLOWING THE CONDITION A.3:

(a) the materials used in any exterior work shall be of similar appearance to those used in the construction of the exterior of the

Existing brickwork to the rear elevation to be improved, infilled and repaired as necessary. Brickwork to be cleaned, repointed and left

The relationship between the rear wall of the side extension and neighbour's existing lower ground floor window is unchanged.

New opening to be created symmetrically in rear elevation for traditional timber framed concertina doors to be set into. Doors to be set back into the façade behind traditional half brick reveals.

Revisions:

Revision A - 21.03.14 Proposal revised to retain original roof in response to neighbours'

Existing ridge height, front balustrade height and side elevation windows corrected as per existing drawings.

Revision B - 25.04.14

Existing eaves and guttering corrected as per existing drawings.

Roof finished revised and rooflights added to rear elevations. Notes updated accordingly.

Revision C - 17.06.14

Alterations to front elevation and front roof slope omitted.

Revision D - 18.06.14

Render removed from rear elevation and general corrections to

drawing number: 782/P/211

Proposed Front + Rear Elevation job name: Belsize Crescent job number: 782 1:50@A2 17 May 2013



t +44 (0)20 7729 7729 f +44 (0)20 7729 7791

www.splashofmilk.com



GENERAL NOTES:

COPYRIGHT TO THESE DRAWINGS AND THE DESIGNS SHOWN THEREIN ARE RETAINED BY MILK
THESE DRAWINGS ARE FOR INFORMATION ONLY (THEY SHOULD NOT BE SCALED FROM)
ALL DIMENSIONS SHOULD BE VERIFIED ON SITE
ANY DISCREPANCIES IN THE DRAWINGS SHOULD BE BROUGHT TO THE ATTENTION OF MILK
ANY VARIATIONS FROM THESE DRAWINGS SHOULD BE APPROVED BY MILK

Notes:

Survey:

These drawings have been based on survey drawings by others. All setting out to be checked on site before construction.

All gridlines centred on existing walls and/or structure at ground floor

Planning Key:

FRONT ELEVATION

REPAIR WORKS ONLY TO BE CARRIED OUT TO FRONT **ELEVATION:**

11

12

13

ROOF

TO BE REFURBISHED & RE-FINISHED UNDER PERMITTED DEVELOPMENT CLASS C COMPLYING WITH THE CONDITION C.1:

(a) the alteration would not protrude more than 150mm beyond the plane of the slope of the original roof when measured perpendicular with the external surface of the original roof.

Existing asphalt finish on rear roof slopes to be replaced with standing seam lead roof to match the leadwork on the front dormer of the main

Existing asphalt finish on front roof slope and ridge to be repaired or replaced like for like as necessary.

Two conservation style rooflights added to the rear slope of the roof.

The relationship between the existing roof and the neighbour's existing side stair window is unchanged.

The existing flashings to numbers 19 and 21 to be retained and repaired if necessary. Any repair that affects the party wall with number 19 to be dealt with via the party wall process.

24
Existing roof structure to be repaired or replaced as necessary. Any replacement that affects the party wall with number 19 to be dealt with via the party wall process.

Existing fascia boards to be refurbished or replaced like for like and new leadwork lapped into new gutters and downpipes to match

REAR ELEVATION

TO BE ALTERED AND REFURBISHED UNDER PERMITTED DEVELOPMENT CLASS A FOLLOWING THE CONDITION A.3:

(a) the materials used in any exterior work shall be of similar appearance to those used in the construction of the exterior of the existing dwellinghouse.

Existing brickwork to the rear elevation to be improved, infilled and repaired as necessary. Brickwork to be cleaned, repointed and left

The relationship between the rear wall of the side extension and neighbour's existing lower ground floor window is unchanged.

New opening to be created symmetrically in rear elevation for traditional timber framed concertina doors to be set into. Doors to be set back into the façade behind traditional half brick reveals.

Revisions:

Revision A - 21.03.14

Proposal revised to retain original roof in response to neighbours'

Existing ridge height, front balustrade height and side elevation windows corrected as per existing drawings.

Revision B - 25.04.14

Existing eaves and guttering corrected as per existing drawings.

Roof finished revised and rooflights added to rear elevations. Notes updated accordingly.

Revision C - 17.06.14 Alterations to front elevation and front roof slope omitted.


Revision D - 18.06.14 Render removed from rear elevation and general corrections to

drawing title: Proposed Long Section AA job name: Belsize Crescent job number: 782 1:50@A2 date: 17 May 2013 drawing number: 782/P/310

D



t +44 (0)20 7729 7729 f +44 (0)20 7729 7791



GENERAL NOTES:

COPYRIGHT TO THESE DRAWINGS AND THE DESIGNS SHOWN THEREIN ARE RETAINED BY MILK
THESE DRAWINGS ARE FOR INFORMATION ONLY (THEY SHOULD NOT BE SCALED FROM)
ALL DIMENSIONS SHOULD BE VERIFIED ON SITE
ANY DISCREPANCIES IN THE DRAWINGS SHOULD BE BROUGHT TO THE ATTENTION OF MILK
ANY VARIATIONS FROM THESE DRAWINGS SHOULD BE APPROVED BY MILK

Notes:

Survey:

These drawings have been based on survey drawings by others. All setting out to be checked on site before construction.

All gridlines centred on existing walls and/or structure at ground floor

Planning Key:

FRONT ELEVATION

REPAIR WORKS ONLY TO BE CARRIED OUT TO FRONT **ELEVATION:**

13

ROOF

TO BE REFURBISHED & RE-FINISHED UNDER PERMITTED DEVELOPMENT CLASS C COMPLYING WITH THE CONDITION C.1:

(a) the alteration would not protrude more than 150mm beyond the plane of the slope of the original roof when measured perpendicular with the external surface of the original roof.

Existing asphalt finish on rear roof slopes to be replaced with standing seam lead roof to match the leadwork on the front dormer of the main

Existing asphalt finish on front roof slope and ridge to be repaired or replaced like for like as necessary.

Two conservation style rooflights added to the rear slope of the roof.

The relationship between the existing roof and the neighbour's existing side stair window is unchanged.

The existing flashings to numbers 19 and 21 to be retained and repaired if necessary. Any repair that affects the party wall with number 19 to be dealt with via the party wall process.

Existing roof structure to be repaired or replaced as necessary. Any replacement that affects the party wall with number 19 to be dealt with via the party wall process.

Existing fascia boards to be refurbished or replaced like for like and new leadwork lapped into new gutters and downpipes to match

REAR ELEVATION

TO BE ALTERED AND REFURBISHED UNDER PERMITTED DEVELOPMENT CLASS A FOLLOWING THE CONDITION A.3:

(a) the materials used in any exterior work shall be of similar appearance to those used in the construction of the exterior of the existing dwellinghouse.

Existing brickwork to the rear elevation to be improved, infilled and repaired as necessary. Brickwork to be cleaned, repointed and left

The relationship between the rear wall of the side extension and neighbour's existing lower ground floor window is unchanged.

New opening to be created symmetrically in rear elevation for traditional timber framed concertina doors to be set into. Doors to be set back into the façade behind traditional half brick reveals.

Revisions:

Revision A - 21.03.14

Proposal revised to retain original roof in response to neighbours'

Existing ridge height, front balustrade height and side elevation windows corrected as per existing drawings.

Revision B - 25.04.14

Existing eaves and guttering corrected as per existing drawings.

Roof finished revised and rooflights added to rear elevations. Notes updated accordingly.

Revision C - 17.06.14 Alterations to front elevation and front roof slope omitted.

Revision D - 18.06.14 Render removed from rear elevation and general corrections to

revision: D

drawing title: Proposed Long Section BB job name: Belsize Crescent job number: 782 1:50@A2 date: 17 May 2013 drawing number: 782/P/311



t +44 (0)20 7729 7729 f +44 (0)20 7729 7791