



EW/G.19 (O'Shea Window 13)



Missing timber

Existing timber requiring refurbishment

Timber recommended to be replaced



The shade, and the outer sections of the return liners exist, though in bad condition and will require replacing in large part.

Luard Conservation 67 Selloms Avenue London NW10 4HJ +44 (0)20 8961 7544 +44 (0)7963 741 117 info@luardconservation.com	The Elms, Fitzroy Park		
	EW/G.19		
	NOT TO SCALE		