



Ref: 2014 / 2318

Section of proposed gutter.

The existing gutter does not carry the amount of rainwater from the roof, like it leaks to the brick on the wall and has damaged all the bricks around the gutter.