Delegated Report		Analysis sheet		et	Expiry Date:		30/10/2014			
		N/A / attached			Consu Expiry	Date:	23/10/	14		
Officer Nick Baxter			Application Nu 2014/6028/L	mber(s						
Application Address				Drawing Numb	ors					
Maria Montessori Training Organisation 26 Lyndhurst Gardens London NW3 5NW				Photos 2813, 2816, 2817 and 2819						
PO 3/4 Area Te	am Signatur	re C&U	ID	Authorised Off	icer Si	nature				
Alcu I	am Oignatai	o oac	,,,	Authorised on		gnataro				
Proposal(s)										
Details of condition 3 (facing materials) granted under reference 2013/3955/L dated 22/08/13.										
Recommendation(s): Grant approval of details										
Application Type:	Approval of Details (Listed Building)									
Conditions or Reasons for Refusal:	n Notice									
Informatives:	iormatives:									
Consultations										
Adjoining Occupiers:	No. notifie	d 0 0		of responses	00	No. of o	bjections	00		
	I lava O I lia	-		electronic	00	0/40/44				
Summary of consultation responses:		yıı <i>21</i> 10/1	4 -23/10	/14, site notice 1/	10/14-2	.2110/14	, по сотпте	:IIIS		
	Fitzjohns/N	Netherhal	II CAAC	was consulted. N	No reply	was red	ceived.			
CAAC/Local groups* comments: *Please Specify										

Site Description

The site is a grade-II-listed red-brick detached house of 1886 by Harry Measures. The proposal affects a 20th-century coach house, detached from the main building, which is being converted into a teaching space and extended to the rear in a modern idiom.

Relevant History

NA

Relevant policies

LDF Core Strategy and Development Policies

DP24 (Securing High-Quality Design)

DP25 (Conserving Camden's Heritage)

CS14 (Promoting High-Quality Places and Conserving our Heritage)

NPPF

Assessment

The structure is mostly made up of wooden shuttering. The applicant displayed planks of timber which appeared to be of high quality. He explained that they would weather to a muted grey over time. Also visible were parapet walls of good-quality London stock brickwork, which appeared appropriate to the surroundings, and high-quality rolled-seam leadwork on the roof. Finally, a plain grey powder-coated metal window frame was viewed.

Although the house itself is red brick, given that the new structure is not directly connected to the historic house and that it abuts a modern housing development in dark brown brickwork, it is felt that the brickwork, along with the rest of the materials, is appropriate and will not harm the special interest of the listed building.