

**From:** [Adrian Jonson](#)  
**To:** [Felix Finkernagel \(Felix@finkernagelross.com\)](mailto:Felix.Finkernagel@finkernagelross.com)  
**Date:** Mon, 10 Nov 2014 14:36:23 +0000  
**Subject:** 8 Elsworthy Road Monitoring

Felix,

Further to our discussion, I can confirm from analysing the monitoring data, particularly from April 2014 until September 2014 (when we conducted our last set of measurements), there has been no movement of any significance on any of the targets that fall outside of our specified survey accuracy ( $\pm 2\text{mm}$ ).

No movement trends are immediately discernible in the data and we would conclude that the monitoring points remained stable during this period.

We however are not in a position to state that the structure is therefore stable and not prone to any movement, this confirmation would need to be provided by the structural engineers.

I trust this is helpful, please contact me if you require any further clarity.

Regards,

Adrian Jonson  
Monitoring

Site Engineering Surveys Ltd.

Email: [adrian.jonson@sesltd.uk.com](mailto:adrian.jonson@sesltd.uk.com)  
Tel: +44 207 538 0870 Fax: +44 207 537 4355  
16 Tiller Court, Tiller Road, London, E14 8PX

[www.sesltd.uk.com](http://www.sesltd.uk.com)

---

Site Engineering Surveys Ltd, Registered Offices: Enterprise House,  
Beesons Yard, Bury Lane, Rickmansworth, Hertfordshire WD3 1DS Registered  
in England, Registered Number: 02568539 [www.sesltd.uk.com](http://www.sesltd.uk.com)

---