

Photographic Record
Passfield Hall Annex Buildings, London WC1

13 Endsleigh Street
11-12 Taviton Street

Molyneux Kerr Architects
February 2015



Photo 1: Endsleigh Street elevation.



Photo 2: Endsleigh Street elevation.



Photo 3: Endsleigh Street - gable end.



Photo 4: Endsleigh Street - rear return.



Photo 5: Endsleigh Street - gable end detail.



Photo 6: Endsleigh Street - main cornice band.



Photo 7: Endsleigh Street - parapet.



Photo 8: Endsleigh Street - side return.



Photo 9: Endsleigh Street - front dormer windows as existing.



Photo 10: Endsleigh Street - roof dormers.



Photo 11: Endsleigh Street - main cornice band.



Photo 12: Endsleigh Annex: rear elevation



Photo 13: Endsleigh Annex front elevation: Metal balusters from previous guardrail are still evident.



Photo 14: Taviton elevation.



Photo 15: Taviton Annex: Existing guardrails to front elevation (to be removed).




Photo 16: Taviton Annex: Existing broken section of guardrail to front elevation (to be removed).



Photo 17: *Taviton Annex: rear elevation*




Photo 18: *Taviton Annex (No. 11 Taviton Street) rear coping.*



Photo 19: Taviton Annex - gable end.



Photo 20: Taviton Annex - roof dormer windows.



Photo 21: Taviton Annex - parapet and guardrail. (Guardrail to be removed).



Photo 22: Taviton Annex - asphalt over parapet.



Photo 23: Taviton Annex - parapet.



Photo 24: Taviton Annex - 3rd floor sash windows.



Photo 25: Taviton Annex - main cornice cill.



Photo 26: Taviton Annex - Non-original existing moulded window surrounds.



Photo 27: Taviton Annex - Regency balcony window blind box.



Photo 28: Taviton Annex - window surround.



Photo 29: Taviton Annex - balcony doors.



Photo 30: Taviton Annex - 1st floor balcony elevation.



Photo 31: Taviton Annex - balcony railings - typical defects.



Photo 32: Taviton Annex - main cornice at neighbouring building.