

Victoria Peachy

From: claims@gabrobins.co.uk
Sent: 29 December 2014 16:13
To: Jessica Leather
Subject: RE: your Ref B1330768 korine

Hi Jess,

BRE Digest 251, Category 3 [Moderate] cracking in order of 15 mm in width

The rear elevation of the brick built double garage has moved downwards.

The mechanism of the movement is clay shrinkage subsidence from the effects of vegetation. In accordance with the direction of the movement the most obvious cause is a group of Third Party Cypress trees sited at the rear of the garages.

I trust this assists.

Many thanks

Stephen Reynolds
Project Manager

GAB Robins UK Ltd
First Floor, Regent House, Hubert Road, Brentwood, CM14 4JE

Direct Dial: 07711 378049
Fax: 0870 242 5159

Please refer any urgent queries to our Building Services Centre
Tel 0870 950 6921
Fax 0870 242 5159
E-mail gabr_gb_building_services@gabrobins.co.uk