



Schedule of External Repairs : Chenies Mews Elevation

- Existing main entrance door; Site office sign to be removed and door and frame to be redecorated (to match existing finish). Existing damaged basement entrance door to be replaced with new to match existing.
- Existing windows: Redundant ventilation grilles to be removed, damaged glass / glass with holes in it to be replaced and windows redecorated (colour to match existing).

- Existing window and louvre frames to be redecorated. (colour to match existing)
- Plywood board to be removed, damaged glass in existing window to be replaced, window and louvre frames to be redecorated (colour to match existing). Existing painted masonry and render to be redecorated. (colour to match existing).
- Existing redundant mechanical ventilation plant on roof (not visible from street level) to be removed.

				Revision
			10.06 2015	Revision Date
		2	10.06.2015 Issued for planning change of use	Amendment
				Notes
And the state of t				
HODD HIND FORM MET GOOD 44 - IDAH DOOR YE FOUND FOUND FORM INDICED HOUSE OF TO STOCK TO THE VIOLET OF THE VIOLET O				
Project N°	Scale N Date Ju	Drawing	Project	Client
Drawing N° Revision 681-G-140 A	N.T.S. Drawn CI June 2015	External Repairs: Chenies Mews Elevation	Chenies Mews Welfare	University College London
t 020 83/5 6510 f 020 83/5 6520 e n/6(§bruedistrottscum a avalonedistrottscum a uni 001 calonus bulding de ás jateany oncos 513 75		burwell deakins: architects		