

LEGEND

Built Features Roads & Road Markings Internal Survey Features

BH 3.67 Beam Height DH 2.22 Door Height D.27 Floor to Cill 3.34 Cill to Head h 0.9 Height FD Fire Door PARAPET Parapet Height SOFF Underside of Soffit

5.12 Railway *STPL 5.12 Step Level Line of Fence LD Land Drain CONCB Concrete Base ** Tree Coniferous 5.12 Surface Change (a) Tree Deciduous

> Door Floor Level Ceiling Height Wardrobe Door Sliding Door Ceiling Slope Arrows point up unless on roofs Sink / Bath Toilets Roof Access Sash Window

Radiators

Description of Features

Floor to Cill Height height Handrail Arch Height

Arch Height
Arch Level
Arch Spring Height
Arch Spring Level
Bollard
Break Glass Point
Beam Height
Beam Soffit Level
Cill to Head Height
Concrete
Cupboard
Door Height
Down Pipe
Drainage Channel
Electrical Switchgear
Fire Alarm
Fire Extinguisher
Fire Hydrant

Fire Hydrant Fire Hose Reel

Inspection Cover
Light
Maximum
Minimum
Overhead
Ordnance Survey Bench Mark
Radiator
Recessed Door Mat
Rolled Steel Joist
Rain Water Pipe
Site Bench Mark
Spring Height
Skylight
Vent
Vent Pipe Vent Pipe Water Heater

Murphy Surveys Ltd. Disclaimer


The user or recipient of this survey data understands and acknowledges this data may be inaccurate or contain errors or omissions and the user or recipient assumes full responsibility for any risks or damages resulting from, arising from, or in connection with any use of or reliance upon data displayed herein. Although significant care has been exercised to produce surveys that satisfy survey accuracy standards, these surveys are only as accurate as the source data from which they were compiled. Although all reasonable steps have been taken to locate all features visible at the time of the survey, there is no guarantee that all will be shown on the drawing, as some above ground features may have obstructed the survey. Wherever possible, areas unable to be surveyed

will be labelled as "UTS". The Company shall not be liable for any inaccuracy of the data provided beyond the specified scale or accuracy, or for any matters resulting from their use for purposes other than that stated in the Contract. No liability shall attach to the Surveyor in respect of any consequential loss or damages suffered by the Client. The Client must promptly notify the Company of any errors in mapping of which it becomes aware. If misleading, inaccurate or otherwise

inappropriate information is brought to the Company's attention or the Company itself identifies any such imprecision or error in a survey, it shall use its reasonable endeavours to fix or remove it and if necessary in certain instances, the Company being on notice of any such misleading, inaccurate or otherwise inappropriate information, it will re-conduct the survey and reproduce the data to within the specified scale or accuracy.







	Revisions	
No. Date	Description	
A 18/09/2014	First Issue	
_		









London Glasgow Belfast Cork Kildare **UK Head Office**

9 Devonshire Square Phone: (+44) 020 3178 6644 London EC2M 4YF Email:london@murphysurveys.co.uk

www.murphysurveys.co.uk

Mount Anvil King's College London Lord Cameron Hall

18/09/2014 Scale: 1:50@A1 Floor Plan - First Floor

MSL9992-LCH-FP1-01

© Copyright 2014 MURPHY SURVEYS LTD