A 11 (1 N	C II N		D	<b>G</b>	Printed on:	22/10/2015	09:05:19
Application No: 2015/4373/P	Consultees Name: oliver froment	Consultees Addr: 10 Pilgrim's Lane nw31sl nw31sl nw31sl	Received: 14/10/2015 17:25:19	Comment: OBJ	Response: application:2015/4373/P 13 Kemplay road  Dear Mr Tulloch,  I fully agree with the objections of the Heath and Hampstead Society and the Residen addition to their comments, I would like to object on the following ground:  1- Trees There are two trees of very significant amenities that would be disappear as a application. There are two a very tall and large trees ( more than 15 meters high) and a of similar amenity could be replanted. DP 24, DP 25  2-the BIA is faulty and therefore CPG4 and DP 27, 23 are not complied with.  Some examples: 1b this is a desk top survey. No boreholes have been conducted. This page 10 of the BIA, there are no information on the water table on the same page of the point 2 is faulty: there are maps that shows there was a water pump near the site. Fur maps show the presence of a pound in that area. The aquifer is also unknown as a result of how can the BIA states in point 6 that no trees will be felt and any work proposed we protection zones when all indications show that this will definitely be the case?!  -7 contrary to what the BIA states there is a history of subsidence near by (e.g. 11 Pilgue) page 12- point 6 is faulty: we have reports from homecheck that shows that the area surface water flooding  Considering the documented surface risk documents that we have from home check, the presence of clay gate, the major subsidence and heave problems that have happene properties (e.g. 11 Pilgrim"s Lane) boreholes work need to be conducted before determined to the surface and heave problems that have happened properties (e.g. 11 Pilgrim"s Lane) boreholes work need to be conducted before determined to the surface and heave problems that have happened properties (e.g. 11 Pilgrim"s Lane) boreholes work need to be conducted before determined to the surface and the surface and heave problems that have happened properties (e.g. 11 Pilgrim"s Lane) boreholes work need to be conducted	a result of this as such no trees sexplains why on the BIA, rthermore all alt within any tree grim"s Lane) is at risk of the sloppy terrained to nearby mination.	n
					Please refuse Therels you		
					Thank you		

Application No:	Consultees Name:	Consultees Addr:	Received:	Comment:	Response: Regards Oliver R Froment	Printed on:	22/10/2015	09:05:19
2015/4373/P	oliver froment	10 Pilgrim's Lane nw31sl nw31sl nw31sl	14/10/2015 17:25:01	OBJ				
2015/4373/P	oliver froment	10 Pilgrim's Lane nw31sl nw31sl nw31sl	14/10/2015 17:24:57	′ ОВЈ				
2015/4373/P	oliver froment	10 Pilgrim's Lane nw31sl nw31sl nw31sl	14/10/2015 17:24:53	ОВЈ				

			<b>.</b>			22/10/2015	09:05:19
Application No: 2015/4373/P	Consultees Name: oliver froment	Consultees Addr: 10 Pilgrim's Lane nw31sl nw31sl nw31sl	Received: 14/10/2015 16:45:34	Comment: OBJ	Response: application:2015/4373/P 13 Kemplay road  Dear Mr Tulloch,  I fully agree with the objections of the Heath and Hampstead Society and the Resident addition to their comments, I would like to object on the following ground: 1- Trees There are two trees of very significant amenities that would be disappear as a application. These are very tall and large trees ( more than 15 meters high) and as such similar amenity could be replanted. DP 24, DP 25 2-the BIA is faulty and therefore CPG4 and DP 27, 23 are not complied with.  Some examples: 1b this is a desk top survey. No boreholes have been conducted. This page 10 of the BIA, there are no information on the water table on the same page of the BIA, point 2 is faulty: there are maps that shows there was a way the site. Furthermore all maps show the presence of a pound in that area. The aquifer is a resut  6 how can the BIA states in point 6 that no trees will be feltand any work proposed with protection zones when all indications show that this will definitely not be the case?!	Association. In result of this no trees of explains why on water pump nears also unknow as	
					7 contrary to what the BIA states there is a history of subsidence near by (e.g. 11 Pilgri page 12- point 6 is faulty: we have reports from homecheck that shows that the area is surface water flooding  Considering the documented surface risk documents that we have from home check, the presence of clay gate, the major subsidence and heave problems that have happened properties (e.g. 11 Pilgrim's Lane) boreholes work need to be conducted before determed on a separate note, the view of the church would be compromised from the street and architecture of the house should be upgraded to much higher external visual standard in conservation area. DP 24 has been breached.  We wished that Camden had advised at least that both the BIA is obviously faulty.  Please refuse  Thank you  Regards	at risk of  he sloppy terrain d to nearby nination.  the proposed	1,

				<b>G</b>	Printed on: 22/10/2015 09:05:19
Application No:	Consultees Name:	Consultees Addr:	Received:	Comment:	Response: Oliver R Froment
2015/4373/P	Miranda Hall	18A Kemplay Road London NW3 1SY	14/10/2015 19:47:15	OBJEMPER	Objection to 2015/4373/P, 13 Kemplay Road  This seems a poorly designed attempt to create a new house approximately 4 times the size of the existing one, with no thought given to the existing look and character of Kemplay Road and the
					wider Hampstead conservation area.  The proposal for a large basement excavation is particularly concerning, including the prolonged disruption and noise while it is being built and the possibility, due to the entirely inadequate Basement Impact Assement, of damage to surrounding properties. The loss of green space, mature trees and the impact on the building and grounds of the Grade 2 listed Rosslyn Chapel is also highly objectionable.
					I was only recently made aware of this application by concerned neighbours as it appears the single notice posted by the council was repeatedly removed or hidden from view during the earlier part of the consultation period. I believe the consultation period should therefore be extended to allow chance for comments by other local residents who were also unaware of the plans.
					Regards Miranda Hall
2015/4373/P	Sonia Daniels	4c Kemplay Road Hampstead London NW3 1SY	14/10/2015 13:40:35	COMMNT	I have the following serious concerns about this project:
					1. Excavation to create a basement could damage the foundations of other houses in the street. On that side of the road at least one house had to be demolished some years ago.
					2. The proposal is to build a house that does not visually match the neighbourhood where currently there is a row of similar houses. The neighbourhood is an attractive area, but this is now under threat.
					3. Despite being a conservation area another house in the street recently developed a basement and built a structure that is not in keeping with the neighbourhood, again putting the character of a unique part of London under threat.
					4. The proposal will create more building and less space, which is damaging to the environment.
					5. Cutting down a tree is damaging to the environment.
2015/4373/P	Sonia Daniels	4c Kemplay Road	14/10/2015 13:39:59	COMMNT	