



Option 1:  
Reconstituted stone cills and brick soldier course added to windows.  
Reconstituted stone coping added to roof to front and side faces.