

[REDACTED]

From: [REDACTED]
Sent: 23 December 2015 08:51
To: Enirayetan, Oluwaseyi
Subject: 2015/6581/P, 134 Charing Cross Road

Categories: Yellow Category

Hello,

My advice regarding ATM installation is;

Mirrors: The Diebold ATM is installed with two mirrors installed within the top of the ATM external frame, allowing customers to view activity behind them.

CCTV: Should be installed and comply with the Information commissioners guidelines.

Lighting: Lighting should compliment cctv recorded images.

PIN Shields : Installed as standard.

Pavement Privacy Areas: .

Other security options are below.

Anchoring systems – Installed as standard, to mitigate the risk of a ram raid attack

Alarm Systems

Fogging Systems

Tracking Systems

Cash Degradation Systems

Gas Attacks – ATM Gas EX Safe to be installed, adding protection against internal gas explosions

Regards Adam Lindsay

Designing Out Crime Officer

Ruislip Police Station

The Oaks, Ruislip,

TP C&S North West

0208 733 3703

07825103933

Office Email: DOCOMailbox.NW@met.police.uk

www.immobilise.com

The Primary Objective of an Efficient Police Force is the Prevention of Crime

[MPS Crime Prevention Advice](#) | [Internal Advice for Staff](#)

"Secured by Design... placing design between crime & the community" www.securedbydesign.com MetSec
Code: **RESTRICTED** (Unless otherwise marked)

Total Policing is the Met's commitment to be on the streets and in your communities to catch offenders, prevent crime and support victims. We are here for London, working with you to make our capital safer.

Consider our environment - please do not print this email unless absolutely necessary.

NOTICE - This email and any attachments may be confidential, subject to copyright and/or legal privilege and are intended solely for the use of the intended recipient. If you have received this email in error, please notify the sender and delete it from your system. To avoid incurring legal liabilities, you must not distribute or copy the information in this email without the permission of the sender. MPS communication systems are monitored to the extent permitted by law. Consequently, any email and/or attachments may be read by monitoring staff. Only specified personnel are authorised to conclude any binding agreement on behalf of the MPS by email. The MPS accepts no responsibility for unauthorised agreements reached with other employees or agents. The security of this email and any attachments cannot be guaranteed. Email messages are routinely scanned but malicious software infection and corruption of content can still occur during transmission over the Internet. Any views or opinions expressed in this communication are solely those of the author and do not necessarily represent those of the Metropolitan Police Service (MPS).

Find us at:

Facebook: [Facebook.com/metpoliceuk](https://www.facebook.com/metpoliceuk)
Twitter: [@metpoliceuk](https://twitter.com/metpoliceuk)