

PROVISIONAL ISSUE FIRST FLOOR

TRAPPED GULLY.

2. BOILER CONDENSATE DRAINS TO DISCHARGE INTERNALLY

2. BOILER CONDENSATE DRAINS TO DISCHARGE INTERNALLY

TO TRAPPED GULLY.


3. ALL UNDERFLOOR HEATING ZONES TO BE INDIVIDUALLY
ROOM CONTROLLED VIA A HEATMISER (LUXURY) SYSTEM
WITH HIDDEN WALL SENSORS IN ALL ROOMS APART FROM
WC'S, SHOWER & BATHROOMS, WHICH WILL BE PROVIDED
WITH FLOOR SENSORS AND REMOTE CONTROL ADJUSTMENT

4. UNDERFLOOR HEATING ROOM THERMOSTATS TO BE
LOCATED REMOTELY ON EACH FLOOR.

BOILER SAFETY DRAINS TO DISCHARGE INTERNALLY TO



DESIGNERS DRAWINGS AND SPECIFICATIONS.
5.) ALL VALVES ARE NOT SHOWN, REFER TO SPECIFICATION & SCHEMATICS FOR GUIDANCE.





o 3

NOTES:

1.)THIS DRAWING IS COPYRIGHT OF BARRY GRIFFIN ASSOCIATES.


2.)DO NOT SCALE FROM THIS DRAWING.

3.)THE CONTRACTOR IS TO VERIFY ALL DIMENSIONS ON SITE BEFORE COMMENCING WORK. ALL ERRORS AND OMISSIONS ARE TO BE REPORTED TO THE ENGINEER.

4.)THIS DRAWING IS TO BE READ IN CONJUNCTION WITH ALL RELEVANT ARCHITECTS, STRUCTURE ENGINEERS, KITCHEN DESIGNER & INTERIOR KITCHEN DESIGNER & INTERIOR


NOV 2015 FIRST FLOOR MECHANICAL SERVICES, OUTLINE & INDICATIVE LAYOUT 55 LANCASTER GROVE Barry Griffin Associates BG cale: 1:50 @ A1 1:100 @ A3 necked:

Building Services and Public Health Consultants












RADIATOR + TRV

BATHROOM EXTRACT VENTILATION SHALL BE VIA CEILING SLOT DETAILS BY INTERIOR DESIGNER.

NOTE






MECHANICAL SERVICES,
OUTLINE & INDICATIVE
LAYOUT

BG

PROVISIONAL ISSUE ROOF





NOTES:

1.)THIS DRAWING IS COPYRIGHT OF BARRY GRIFFIN ASSOCIATES.

2.)DO NOT SCALE FROM THIS DRAWING.

3.)THE CONTRACTOR IS TO VERIFY ALL DIMENSIONS ON SITE BEFORE COMMENCING WORK. ALL ERRORS AND OMISSIONS ARE TO BE REPORTED TO THE ENGINEER.

4.)THIS DRAWING IS TO BE READ IN CONJUNCTION WITH ALL RELEVANT ARCHITECTS, STRUCTURE ENGINEERS, KITCHEN DESIGNER & INTERIOR DESIGNERS DRAWINGS AND

SPECIFICATIONS.
5.) ALL VALVES ARE NOT SHOWN, REFER TO SPECIFICATION & SCHEMATICS FOR

ROOF MECHANICAL SERVICES, OUTLINE & INDICATIVE LAYOUT 55 LANCASTER GROVE Barry Griffin Associates BG

Telephono 20 8566 ...
Fax 020 8566 ...
Drg. No. 749/M/06

Building Services and Public Health Consultants ue 020 8866 7685 020 8866 7685



UNDERFLOOR HEATING MANIFOLD, PUMP & CONTROLS ELECTRIC TOWEL RAIL RADIATOR + TRV

REMOTE CEILING OR WALL MOUNTED EXTRACT FAN