

RC Church of  
St Thomas More

Presby

PLY HOARDING, EDGE OF  
CONSTRUCTION SITE.

TREE PROTECTION AS  
PER THE STANDARDS  
SET OUT IN  
BS 5837:2012  
"TREES IN RELATION  
TO CONSTRUCTION"

EXISTING TREE  
TRIMMED BACK  
BY CAMDEN  
COUNCIL.

THIS TREE'S CROWN DOES  
NOT EXTEND PAST PLY HOARDING.

2 x 2 m from EDGE OF  
HOARDING TO TREE  
TRUNK.

CDM DESIGN REVIEW  
Date Held: to be assessed  
Significant risks identified which are either:

- 1 Not likely to be obvious to a competent Contractor:  
None
- 2 Unusual risks:  
None
- 3 Likely to be difficult to manage effectively:  
CDM, RISK 1 - Gas pipe has to stay alive throughout construction

PRELIMINARY

**Kyle Smart Associates**  
Chartered Architects & Building Consultants  
The Barn, Betchen Wick, Sewell, Nr Dunstable, Bedfordshire LU5 1PP  
e-mail: KyleSmart@kylesmartassociates.co.uk  
Tel: 01582 690222

Project Title  
St Thomas More Church

Drawing Title  
Existing Site Plan

Drawing No	13020 SU1.02	Rev	
Date	1:100@A1	Date	Mar-16
Drawn By	SG	Checked By	CS