

WINDOW SURVEY FOR 40 ARLINGTON ROAD, LONDON, NW1 7HU


The Existing Front Windows



Arlington Road front view



Second floor existing front windows are not original- replaced in the 1970's with the refurbishment of the roof
PROPOSAL- replace both to match original windows



First floor existing original single glazed sash front windows
PROPOSAL- repair and refurbish both



Ground floor existing original front window
PROPOSAL- repair and refurbish





Second floor existing rear window not original-
replaced in the 1970's with the refurbishment of
the roof
PROPOSAL- replace window to match original



40 Arlington Road rear view



First floor landing rear window
showing existing original single
glazed sash window in poor
condition
PROPOSAL- replace window to
match original



First floor existing original rear window showing
single glazed sash window in poor condition
PROPOSAL- replace window to match original



Ground floor rear window showing existing original single glazed sash
window in poor condition
PROPOSAL- replace window to match original



Ground floor landing rear door not original-
PROPOSAL- replace door to match existing

Our intension is to renovate all the original windows at front except the 2 windows on the second floor which are not original and replace all the windows at the rear to match existing single glazed original windows including the two windows at the front.



PREPARED BY

BRIAN OREILLY ARCHITECTS

THE STUDIO

31 OVAL ROAD

LONDON NW1 7EA

T. 020 7267 1184

www.brianoreillyarchitects.com