



LEGEND

-  Proposed new timber floor joists to replace existing, removed joists to be set aside for re-use in retained floors where possible
-  Proposed new ground bearing concrete slab, FFL to be approx. 100mm below existing




Vault in poor condition with failing arches, to be repaired with spray applied concrete liner, refer to Structural Engineers' report for further information

NOTES

KEY

KEY



**OOK ARCHITECTS**  
119 Farringdon Road  
London EC1R 3DA  
studio@ookarchitects.com  
www.ookarchitects.com

REVISION / DESCRIPTION	DRAWN	CHECKED	DATE
P01 - PLANNING SUBMISSION (FIRST ISSUE)	OOK	OOK	28.10.15
P02 - CLOSET WING FENESTRATION REVISED	OOK	OOK	08.02.16
P03 - CLOSET WING FENESTRATION REVISED	OOK	OOK	08.02.16
P04 - Window references & new floor proposals added (Updated by Module Studio)	MS	MS	28.11.16
P05 - (Updated by Module Studio)	MS	MS	02.12.16

OOK ARCHITECTS SHALL HAVE NO RESPONSIBILITY FOR ANY USE MADE OF THIS DOCUMENT OTHER THAN FOR THAT WHICH IT WAS PREPARED AND ISSUED. ALL DIMENSIONS SHOULD BE CHECKED ON SITE. DO NOT SCALE FROM THIS DRAWING. ANY DRAWING ERRORS OR DIVERGENCES SHOULD BE BROUGHT TO THE ATTENTION OF OOK ARCHITECTS.

PROJECT NUMBER	PROJECT TITLE	DATE
518A	66 GUILFORD STREET	28.10.15
DRAWING TITLE		SCALE
Section B Proposed		1:100
STATUS	DRAWING No.	REVISION
PLANNING	518A-SE-211	P05