VO 23 - COURTYARD ELEVATION REPAIRS

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
	ing Russell Square												
,		Repoint under parapet full length											
1		of elevation				Repoint	RR	R					38.000
		Repoint lead flashing to full length				·							
2		of elevation				Repoint	RR	R					38.000
3		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
		Replace damaged brick and repoint											
4		around it.				Replace brick	B:ID	R					1.000
		Replace coping section with new											
5		Portland Stone Coping				Replace coping	ID	R					0.000
		Replace coping section with new											
6		Portland Stone Coping				Replace coping	ID	R					0.000
		Replace coping section with new											
		Portland Stone Coping also repair											
7		dislodged brick under coping				Replace coping and brick repair	ID, MR	R					0.000
		Replace coping section with new											
		Portland Stone Coping also replace											
8		1 no damaged brick under coping				Replace coping and brick repair	ID, MR	R					0.000
		Replace coping section with new											
9		Portland Stone Coping				Replace coping	ID	R				1	1.000
10		Repoint approx. 5 m2 of wall				Repoint	RR	R	5.000		1.000	1	5.000
11		Repoint approx. 2 m2 of wall				Repoint	RR	R	2.000		1.000	1	2.000
12		Repoint perpends				Repoint	RR	R					4.000
13		Repair stone and point around.				Mortar repair and repoint	MR, RR	R	0.400	0.200	0.500		0.040
14		Repoint approx. 4 m2 of wall				Repoint	RR	R	4.000		1.000	1	4.000
		Remove redundant cables											
		complete and make good all fixing				Remove cables and fixings,							
15		holes to all levels.				mortar repair	RF, MR	R					18.000
16		Repoint approx. 2 m2 of wall				Repoint	RR	R	2.000		1.000	1	2.000
		Replace coping section with new											
17		Portland Stone Coping				Replace coping	ID	R					0.000
		Repoint approx. 10 m2 of wall. Top											
18		five courses of parapet.				Repoint	RR	R	10.000		1.000	1	10.000
		Replace coping section with new						_					
19		Portland Stone Coping				Replace coping	ID	R					0.000
		Replace failed brick with new											
30		· ·				Donlars beist	חיים	_					1,000
20		glazed brick to match existing.				Replace brick	B:ID	R					1.000
21		Replace coping section with new				Ponlace coning	ID	R					0.000
21		Portland Stone Coping				Replace coping	טו	K					0.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
		Replace coping section with new											
		Portland Stone Coping to masard						_					
22		coping.				Replace coping	ID	R	0.5	0.9	0.2		0.090
		Abrasive clean Portland Stone				Abrasive clean portland detail, 5"							
23		detail full length of elevation.				spinner variable speed							1.000
23		detail full length of elevation.				spiriter variable speed							1.000
24		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF	R	0.050		0.050		2.000
											2.252		
25		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R	0.050		0.050		4.000
26		Repoint Arch over window.				Repoint	RR	R					1.000
		Replace rendered bricks with new											
		glazed bricks to match main											
27		elevation brickwork.				Replace brick	B:ID	R					1.000
						.,							
		Remove redundant air grille and											
		patch hole with new glazed bricks											
		to match existing main elevation				Remove grille and indent with							
28		brickwork.				brick	B:ID	R					1.000
29		Remove fixings and make good.				Changed to:Replace 1 No brick	В	R					1.000
_						S S S S S S S S S S S S S S S S S S S							
		Replace rendered bricks with new											
		glazed bricks to match main											
		elevation brickwork. Also repair				Replace bricks, remove fixing and	B:ID, RF and						
30		scaffold fixing.				mortar repair	MR	R					1.000
		Replace rendered bricks with new											
		glazed bricks to match main											
31		elevation brickwork.				Replace brick	B:ID	R					1.000
32		Repoint Arch over window.				Repoint	RR	R					1.000
32		Repolite/Well over Willdow.				Керопте	III	.,					1.000
33		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
34		Repoint approx. 1 m2 of wall				Repoint	RR	R	1.000		1.000	1	1.000
35		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
36		Repair redundant scaffold fixings.				Remove fixings and mortar repair	RF, MR	R					2.000
							,						
37		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
38		Repoint approx. 4 m2 of wall				Repoint	RR	R					4.000
39		Repoint Arch over window.				Repoint	RR	R					1.000
40		Repair redundant scaffold fixing.			1	Remove fixings and mortar repair	RF, MR	R					1.000
40		repair redundant scarroid fixing.				nemove fixings and mortal repair	111 , 19111	IV.					1.000
41		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
42		Repoint Arch over window.				Repoint	RR	R					1.000
		Common and an arrive to a site of the											
43		Carry out repairs to split window				Din and racin and Martar Danais	DD MD						1 000
43		cill, return cill to original profile.			I	Pin and resin and Mortar Repair	PR, MR	R	1		1		1.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
44		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R	0.500		,50		1.000
		Repair redundant scaffold fixing.				·	,						
		Also remove and make good timber											
45		plug.				Remove fixings and mortar repair	RF, MR	R					5.000
		Repair redundant scaffold fixings.											
		Also remove and make good timber											
46		plug.				Remove fixings and mortar repair	RF, MR	R					7.000
47		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
48		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
49		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
		Replace rendered bricks with new											
		glazed bricks to match main											
50		elevation brickwork.				Replace brick	B:ID	R					4.000
		Remove redundant air grille and											j l
		patch hole with new glazed bricks											
		to match existing main elevation				Remove grille and indent with							
51		brickwork.				brick	B:ID	R					4.000
		Replace rendered brick with new											
		glazed brick to match main											
52		elevation brickwork.				Replace brick	B:ID	R					1.000
53		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
33		Repoint Arch over window and 1				Remove fixings and mortal repair	1(1 , 1011)	I.					1.000
54		m2 of brickwork above.				Repoint	RR	R					1.000
J.		Repoint Arch over window and 1				переше							1.000
55		m2 of brickwork above.				Repoint	RR	R					1.000
													1 000
56		Repair redundant scaffold fixing. Repoint Arch over window and 1				Remove fixings and mortar repair	RF, MR	R					1.000
57		m2 of brickwork above.				Donaint	RR	R					1.000
37		Repoint Arch over window and 1				Repoint	NN	N.					1.000
58		m2 of brickwork above.				Repoint	RR	R					1.000
30		III2 OF BITCKWOTK GBOVE.				Перопіс	1111						1.000
59		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
		Repoint Arch over window and 1					,						
60		m2 of brickwork above.				Repoint	RR	R					1.000
		Repoint Arch over window and 1											
61		m2 of brickwork above.				Repoint	RR	R					1.000
62		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
		Repoint entire pier between				<u> </u>							
63		adjacent windows.				Repoint	RR	R					1.000
64		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
65		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					17.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
66		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
		Repoint Arch over window and 1				ge and a specific	,						
67		m2 of brickwork above.				Repoint	RR	R					1.000
		Repoint Arch over window and 2				·							
68		m2 of brickwork above.				Repoint	RR	R					2.000
69		Repair redundant scaffold fixings.				Remove fixings and mortar repair	RF, MR	R					2.000
70		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
70		Repoint Arch over window and 2				керопі	NN	N.	3.000		1.000		3.000
71		m2 of brickwork above.				Repoint	RR	R					2.000
/1		Repoint Arch over window and 2				Керопії	IXIX	IX.					2.000
72		m2 of brickwork above.				Repoint	RR	R					2.000
70		D					DE 14D						4.000
73		Repair redundant scaffold fixing. Repoint Arch over window and 1				Remove fixings and mortar repair	RF, MR	R					1.000
74		m2 of brickwork above.				Donaint	RR	R					1.000
74		Repoint Arch over window and 1				Repoint	KK	K					1.000
75		m2 of brickwork above.				Repoint	RR	R					1.000
/3		III2 OI BIICKWOIK ABOVE.				керопт	INIX	IX.					1.000
76		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
77		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
- ''		Repair redundant scarroid fixing.				Remove fixings and mortal repair	111, 14111						1.000
78		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
79		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					3.000
80		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					3.000
00		Repoint Arch over window and 1				Remove fixings and mortal repair	111, 14111	IV.					3.000
81		m2 of brickwork above.				Repoint	RR	R					1.000
		Remove redundant air grille and											
		patch hole with new glazed bricks											
		to match existing main elevation				Remove grille and indent with							
82		brickwork.				brick	B:ID	R					4.000
83		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
84		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	1	1.000
85		Repoint Arch over window.				Repoint	RR	R					1.000
		Repoint Arch over window and 2				·							
86		m2 of brickwork above.				Repoint	RR	R					2.000
		Repoint Arch over window and 1				·							
87		m2 of brickwork above.				Repoint	RR	R					1.000
		Repoint Arch over window and 1											
88		m2 of brickwork above.				Repoint	RR	R					1.000
89		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					16.000
90		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
91							·	P					1.000
91		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
		Remove cable clips and make											
92		mortar good.				Remove fixings and repoint	RF, RR	R					2.000
		Repoint Arch over window and 1											
93		m2 of brickwork above.				Repoint	RR	R					1.000
		Repoint Arch over window and 2											
94		m2 of brickwork above.				Repoint	RR	R					2.000
		Remove cable clips and make						_					
95		mortar good.				Remove fixings and repoint	RF, RR	R					4.000
0.5		Repoint Arch over window and 2											
96		m2 of brickwork above.				Repoint	RR	R					2.000
07		Repoint Arch over window and 2				D i . i							2.000
97		m2 of brickwork above.				Repoint	RR	R					2.000
98		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
		Replace rendered brick with new											
		glazed brick to match main						_					
99		elevation brickwork.				Replace brick	B:ID	R					1.000
100		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
100		nemore mange and make good.				nemove mango and morea repair	,						
101		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
102		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
103		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
104		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
104		Replace rendered brick with new				перинг	1111		0.000		1.000	-	0.000
		glazed brick to match main											
105		elevation brickwork.				Replace brick	B:ID	R					12.000
106		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					8.000
107		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
108		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
109		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
105		Repoint entire pier between				Керопт	IXIX	I.	0.000		1.000		0.000
110		adjacent windows.				Repoint	RR	R					2.000
111		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
112		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
		Repoint entire pier between				1							
113		adjacent windows.				Repoint	RR	R					2.000
114		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
		Repoint Arch over window and 3					****	<u> </u>			2.000		
115		m2 of brickwork above.				Repoint	RR	R					3.000
-		Repoint Arch over window and 2											
116		m2 of brickwork above.				Repoint	RR	R					2.000
	ng Herbrand Street										. '		
117		Poppir redundant scaffold fiving				Romovo fivings and mostor re	DE MAD						2 000
117		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					2.000
118		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					12.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
119		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
120		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	1	1.000
121		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
						i i							
122		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
122		Repoint entire pier between				Donaint	D.D.	R					1 200
123 124		adjacent windows.				Repoint	RR RR	R R	F 000		1 000	1	1.200 5.000
124		Repoint wall approx 5 m2.				Repoint	KK	K	5.000		1.000	1	5.000
125		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
		Repoint entire pier between					•						
126		adjacent windows.				Repoint	RR	R					1.200
127		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
128		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					2.000
129		Pamaya fivings and make good				Romovo fivings and mortar ropair	DE MD	R					2.000
129		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	K					2.000
		Carry out repairs to split window											
130		cill, return cill to original profile.				Pin and resin and Mortar Repair	PR, MR	R					1.000
131		Carry out repairs to split window cill, return cill to original profile.				Pin and resin and Mortar Repair	PR, MR	R					1.000
131		ciii, return ciii to originai profile.				Pili and resili and Mortal Repair	PK, IVIK	K					1.000
		Carry out repairs to stone blocks,											
		return to original profile. Repoint											
132		around stone detail.				Mortar Repair, repoint	MR, RR	R					1.000
133		Repoint entire gable down to scafffold level.				Donaint	RR	R					2.000
155		scarroid level.				Repoint	KK	K					2.000
		Carry out repairs to stone blocks,											
		return to original profile. Repoint											
134		around stone detail.				Mortar Repair, repoint	MR, RR	R					1.000
		Carry out further abrasive cleaning				Abrasive clean surround, 5"							
		to window surround. Paint grille				spinner variable speed, paint							
135		with new gloss paint finish.				grille		R					1.000
136		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
		Remove redundant pipework and make good wall with replacement				Remove pipe and indent with							
425		bricks.				brick	B:ID	R					4.000
						2.100							
426		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R	0.100		0.100		2.000
		Community from the control of the co				Alemania alemania de Eu							
		Carry out further abrasive cleaning to window surround. Paint grille				Abrasive clean surround, 5" spinner variable speed, paint							
427		with new gloss paint finish.				grille		R					1.000
721		Repoint under coping stones for full				Princ		- 11					1.000
428		length of elevation.				Repoint	RR	R					6.000
429	<u> </u>	Repoint Arch over window.				Repoint	RR	R					1.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
420		Repoint wall approx 2 m2. Refix				Barrier of arts at a second			2.000		4.000	4	2 000
430		rainwater goods.				Repoint, refix rainwater goods	RR	R	2.000		1.000	1	2.000
431		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
432		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
433		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
434		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
449		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
450		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
		Repoint flashing for the entire											
451		length of elevation.				Repoint	RR	R					0.000
452		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
453		Repoint Arch over window.				Repoint	RR	R					1.000
454		Repoint Arch over window.				Repoint	RR	R				_	1.000
455		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
456		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
457		Repoint Arch over window.				Repoint	RR	R					1.000
458		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
459		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
460		Refix existing pipework				Refix existing pipework		R					0.000
461		Refix existing pipework				Refix existing pipework		R				_	0.000
462		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
463		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	1	1.000
464		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	11	1.000
465		Refix existing pipework				Refix existing pipework		R					0.000
466		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
467		Repoint Arch over window.				Repoint	RR	R					1.000
468		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
469		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
470		Repoint Arch over window.				Repoint	RR	R	2.000		1.000	1	1.000
471		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
472		Repoint Arch over window.				Repoint	RR	R	2.000		1.000		1.000
473		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
474		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
475		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
476		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
						·							
477 478		Repoint wall approx 3 m2.				Repoint	RR	R R	3.000		1.000	1	3.000
-		Repoint wall approx 3 m2.				Repoint	RR					_	3.000
479		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
480		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
481		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
482		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
483		Rebed and repoint copings plus repoint top two courses for entire length of elevation.				Rebed and repoint copings plus repoint top two courses for entire length of elevation.	RR	R					2.600

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
		Remove redundant insulator and				Remove insulator and mortar							
484		make good.				repair	RF, MR	R					8.000
		Remove redundant insulator and				Remove insulator and mortar							
485		make good.				repair	RF, MR	R					1.000
		Remove redundant insulator and				Remove insulator and mortar							
486		make good.				repair	RF, MR	R					1.000
		Rebed and repoint copings plus				Rebed and repoint copings plus							
		repoint top two courses for entire				repoint top two courses for							
487		length of elevation.				entire length of elevation.	RR	R					3.000
		Remove redundant insulator and				Remove insulator and mortar							
488		make good.				repair	RF, MR	R					1.000
		Remove redundant insulator and				Remove insulator and mortar							
489		make good.				repair	RF, MR	R					2.000
		Remove redundant insulator and				Remove insulator and mortar							
490		make good.				repair	RF, MR	R					2.000
491		Refix existing pipework				Refix existing pipework		R					
492		Repoint Arch over window.				Repoint	RR	R					1.000
		Rebuild small parapet using new				Rebuild small parapet using new							
		bricks and using existing coping				bricks and using existing coping							
493		stones.				stones.	B:ID, RR	R					1.000
494		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
494A		Broken cill repair Pin & Resin				Pin & resin repair	PR, MR	PR					1.000
495		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
496		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
		Repoint entire parapet including				Repoint entire parapet including							
497		rebedding of coping stones.				rebedding of coping stones.	RR	R					1.000
498		Repoint entire end of gable wall.				Repoint	RR	R					2.000
		Rebed and repoint copings plus				Rebed and repoint copings plus							
		repoint top two courses for entire				repoint top two courses for							
499		length of elevation.				entire length of elevation.	RR	R					1.400
500		Repoint wall approx 0.5 m2.				Repoint	RR	R	0.500		1.000	1	0.500
508		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
509		Repoint Arch over window.				Repoint	RR	R					1.000
						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							
510		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
							,						
511		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
512		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
513		Repoint Arch over window.				Repoint	RR	R	2.500		2.500	•	1.000
514		Repoint Arch over window.				Repoint	RR	R					1.000
J17		Remove fixings and make good.				Remove fixings and mortar		.,					2.500
515		Repoint wall 1 m2				repair, repoint	RF, MR & RR	R	1.000		1.000	2	2.000
513		Remove fixings and make good.				Remove fixings and mortar	, 🗴 וווי	.,	2.500		2.500	-	2.300
516		Repoint wall 1 m2				repair, repoint	RF, MR & RR	R	1.000		1.000	2	2.000
510		poc	l		<u> </u>	. cpa, reponie	,	.,,	2.500		1.000	-	2.300

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
517		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
317		Remove fixings and make good.				Remove fixings and mortar	1(1,1011(IX.					1.000
518		Repoint wall 1 m2				repair, repoint	RF, MR & RR	R	1.000		1.000	2	2.000
510		Remove fixings and make good.				Remove fixings and mortar	, 😅		2.000		1.000		2.000
519		Repoint wall 1 m2				repair, repoint	RF, MR & RR	R	1.000		1.000	2	2.000
520		Refix existing pipework				Refix existing pipework	,	R					
521		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
						·							
522		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R				<u> </u>	1.000
523		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
524		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	1	1.000
525		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
526		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
527		Repoint Arch over window.				Repoint	RR	R	3.000		1.000		1.000
528		Repoint wall approx 4 m2.				Repoint	RR	R	3.000		1.000	1	4.000
328		Repolite wall approx 4 III2.				Керопі	IXIX	IN.	3.000		1.000		4.000
529		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R				i '	1.000
530		Repoint Arch over window.				Repoint	RR	R					1.000
531		Repoint Arch over window.				Repoint	RR	R					1.000
532		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
						,							
533		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R				<u> </u>	1.000
534		Repoint Arch over window.				Repoint	RR	R					1.000
535		Refix existing pipework				Refix existing pipework		R					0.000
536		Repoint Arch over window.				Repoint	RR	R					1.000
537		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
538		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
546		Repoint Arch over window.				Repoint	RR	R					1.000
547		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
548		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
548A		M/R to Cill				Mortar repair to cill	MR		0.100		0.100		1.000
		Remove existing plugs and make											
549		good				Remove fixings and mortar repair	RF, MR	R					1.000
550		Repoint Arch over window.				Repoint	RR	R				ļ	1.000
551		Repoint wall approx 3 m2.				Repoint	RR	R	2.000		1.000	1	3.000
552		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
553		Repoint Arch over window.				Repoint	RR	R					1.000
554		Refix existing pipework				Refix existing pipework		R					
		Remove fixings and make good.				Remove fixings and mortar	DE ME 0 0-	-	4.000		4.000	-	2 600
555		Repoint wall 1 m2				repair, repoint	RF, MR & RR	R R	1.000		1.000	2	2.000
556		Repoint Arch over window. Remove fixings and make good.				Repoint Remove fixings and mortar	RR	К				<u> </u>	1.000
557		Repoint wall 1 m2				repair, repoint	RF, MR & RR	R	1.000		1.000	4	4.000
558		Repoint Arch over window.				Repoint	RR	R	1.000		1.000		1.000
559		Refix existing pipework				Refix existing pipework	IXIX	R					1.000
560		Refix existing pipework				Refix existing pipework		R					
						0,1							
561		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
562		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
563		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
564		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
565		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
566		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
567		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
568		Repoint Arch over window.				Repoint	RR	R					1.000
569		Repoint wall approx 8 m2.				Repoint	RR	R	8.000		1.000	1	8.000
570		Repoint Arch over window.				Repoint	RR	R					1.000
571		Repoint wall approx 4m2.				Repoint	RR	R	4.000		1.000	1	4.000
F72		Denair redundant scoffold fiving				Domovo fivings and mortar rangin	DE MD	D.					1 000
572		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
573		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
574		Repoint wall approx 25m2.				Repoint	RR	R	25.000		1.000	1	25.000
575		Repoint wall approx 4m2.				Repoint	RR	R	4.000		1.000	1	4.000
						113					2.000	_	
		Carry out repairs to split window											
576		cill, return cill to original profile.				Pin and resin and Mortar Repair	PR, MR	R					1.000
577		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
578		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					2.000
579		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
379		Repair redundant scarrold fixing.				Remove fixings and mortal repair	IXI , IVIIX	IX.					1.000
580		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					2.000
581		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
582		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
593		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
594		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
595		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
596		Refix existing pipework				Refix existing pipework	Tur	R	3.000		1.000	-	3.000
597		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
598		Refix existing pipework				Refix existing pipework		R					
599		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
600		Repoint wall approx 2 m2.				Repoint	RR	R	3.000		1.000	1	2.000
601		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
		Remove fixings and make good.				Remove fixings and mortar							
		Repoint wall 1 m2. Replace spalled				repair, repoint. Replace spalled	RF, MR, RR &						
602		brickwork.				bricks	B:ID	R	1.000		1.000	3	4.000
603		Refix existing pipework				Refix existing pipework		R					0.000
604		Repair redundant scaffold fixing.				Romovo fivings and mortar renair	DE MD	R					1.000
		<u>'</u>				Remove fixings and mortar repair	RF, MR	1	10.000		1 000	1	
605		Repoint wall approx 10m2.			-	Repoint	RR	R	10.000		1.000	1	10.000
613 614		Repoint wall approx 4m2.				Repoint	RR RR	R	4.000	1	1.000	1	4.000 1.000
		Repoint Arch over window.				Repoint		R	C 000		1.000		
615		Repoint wall approx 6m2.			-	Repoint	RR	R	6.000		1.000	1	6.000
616		Repoint wall approx 6m2.				Repoint	RR	R	6.000		1.000	1	6.000
617		Repoint Arch over window.				Repoint	RR	R					1.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
618		Refix existing pipework				Refix existing pipework		R					
619		Repoint wall approx 4m2.				Repoint	RR	R	4.000		1.000	1	4.000
		Remove fixings and make good.				Remove fixings and mortar							
620		Repoint wall 1 m2				repair, repoint	RF, MR & RR	R					2.000
621		Repoint Arch over window.				Repoint	RR	R					1.000
622		Repoint Arch over window.				Repoint	RR	R					1.000
623		Refix existing pipework				Refix existing pipework		R					
		Repoint entire wall including				Repoint entire wall including							
624		rebeding coping stones.				rebeding coping stones.	RR	R					7.000
		Repoint entire wall including				Repoint entire wall including							
625		rebeding coping stones.				rebeding coping stones.	RR	R					12.000
		Remove fixings conduits and											
626		battens, make good wall behind.				Remove fixings and mortar repair	RF, MR	R					12.000
627		Replace coping stone and rebed.				Replace coping stone and rebed.	ID, RR	R					0.000
628		Replace coping stone and rebed.				Replace coping stone and rebed.	ID, RR	R					0.000
Courtyard fac	ing Bernard Street				1				1				
137		Repoint entire wall around duct.				Repoint	RR	R					5.000
		Repoint entire parapet on this											
138		stretch of the elevation.				Repoint	RR	R					5.000
						l., . , . , . ,							
		Abrasive clean stone corbel along				Abrasive clean corbel, 5" spinner		_					
139		full length of elevation.				variable speed		R					1.000
139A		Damage to copings				Pin and resin and Mortar Repair	PR, MR						2.000
140		Repoint entire chimney side.				Repoint	RR	R					1.000
		Repoint entire chimney side. Also											
		attempt to clean these particularly											
141		discoloured bricks.				Repoint, clean discoloured bricks	RR	R					1.500
142		Repoint entire chimney side.				Repoint	RR	R					1.500
		, ,				,							
143		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
		l l l l l l l l l l l l l l l l l l l				В	,						
		Remove existing failing coating to				Remove existing failing coating to							
		parapet, once stripped, access what				parapet, once stripped, access							
		options we have to clean up and				what options we have to clean up							
		point brickwork or reapply new				and point brickwork or reapply							
144		coating system.					INV	R					1.000
144		coatilig system.				new coating system.	IINV	п					1.000
145		Pengint entire wall around dust				Repoint	RR	R					4.000
143		Repoint entire wall around duct. Repoint entire pier between				керопп	NN	n					4.000
146		adjacent windows.				Repoint	RR	R					2.000
146		Repoint entire chimney side.				Repoint	RR	R R					3.000
147		Repoint entire chimney side.				Repoint	RR	R R					3.000
148		· · · · · · · · · · · · · · · · · · ·					RR	R R					2.000
		Repoint entire chimney side.				Repoint							
150		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
151		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
152		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
-		' ''				'							+
153		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
		Remove fixings and make good.				Remove fixings and mortar							
		Also repair/replace 3 no bricks. Also				repair, repair/replace 3 no bricks.	RE MR BID						
154		remove paint streaks.				Also remove paint streaks.	ST	R					4.000
154		Replace 3 no damaged bricks with				7 130 Terriove paint streaks.	31						4.000
		glazed bricks that match existing											
155		wall.				Replace brick	B:ID	R				3	3.000
		Remove fixings and make good.											
156		Replace brick				Remove fixings and mortar repair	RF, MR	R					1.000
		Remove fixings and make good.				Remove fixings and mortar	RF, MR &						
157		Also repair replace 3 no bricks.				repair. Replace brick	B:ID	R					5.000
		86				B							
		Remove fixings and make good.				Remove fixings and mortar	DE 140 D ID						
450		Also repair/replace 3 no bricks. Also				repair, repair/replace 3 no bricks.							4.000
158		remove paint streaks. Replace 3 no damaged bricks with				Also remove paint streaks.	ST	R					4.000
		glazed bricks that match existing											
159		wall.				Remove fixings and mortar repair	RF, MR	R					5.000
139		waii.				Remove fixings and mortal repair	IXI , IVIIX	IV.					3.000
160		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
161		Repoint entire wall around duct.				Repoint	RR	R					2.000
162		Repoint Arch over window.				Repoint	RR	R					1.000
163		Repoint entire pier between adjacent windows.				Repoint	RR	R					2.000
103		Repoint entire pier between				Керопте	IXIX						2.000
164		adjacent windows.				Repoint	RR	R					2.000
165		Repoint entire chimney side.				Repoint	RR	R					2.000
166		Repoint entire chimney side.				Repoint	RR	R					3.000
167		Repoint entire chimney side.				Repoint	RR	R					2.000
168		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					14.000
		Replace 2 no damaged bricks with											
169		glazed bricks that match existing wall.				Replace brick	B:ID	R				2	2.000
109		Repoint Arch over window and 1				Replace brick	טו.ט	ĸ					2.000
170		m2 of brickwork above.				Repoint	RR	R					1.000
171		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
172		Repoint Arch over window.				Repoint	RR	R	7.000		1.000		1.000
173		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
174		Remove paint splashes				Repoint	RR	R	7.000		1.000		0.000
175		Repoint wall approx 7 m2.				Repoint	RR	R	7.000		1.000	1	7.000
176		Remove paint splashes				Remove paint splashes	ST	R	7.000	1	1.000	1	0.000
177		Repoint Arch over window.				Repoint	RR	R					1.000
						перет							1.000
178		Repoint entire wall around duct.				Repoint	RR	R					2.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
		Repoint Arch over window and 2											
179		m2 of brickwork above.				Repoint	RR	R	2.000		1.000	1	2.000
400		Repoint Arch over window and 2				D i . i			2 000		4.000		2 000
180		m2 of brickwork above.				Repoint	RR	R	2.000		1.000	1	2.000
181 182		Repoint entire chimney side.				Repoint	RR RR	R R	-				2.000 3.000
		Repoint entire chimney side.				Repoint							2.000
183		Repoint entire chimney side.				Repoint	RR	R					2.000
184		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					6.000
185		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					6.000
		Replace 8 no damaged bricks with glazed bricks that match existing											
186		wall.				Replace brick	B:ID	R				8	8.000
						·							
187		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
188		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
189		Repoint Arch over window.				Repoint	RR	R					1.000
190		Remove paint splashes				Remove paint splashes	ST	R					
		Repoint Arch over window. Remove											
191		paint splashes				Repoint, remove paint splashes	RR, ST	R					1.000
		Repoint Arch over window. Remove											
192		paint splashes				Repoint, remove paint splashes	RR, ST	R					1.000
193		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
194		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					22.000
		Replace 10 no damaged bricks with											
		glazed bricks that match existing											
195		wall.				Replace brick	B:ID	R				10	10.000
105													
196		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
197		Repoint entire wall around duct.				Repoint	RR	R					2.000
198		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
		Remove cable clips and make											
199		mortar good.				Remove fixings and repoint	RF, RR	R					8.000
200		Repoint entire chimney side.				Repoint	RR	R					2.000
201		Repoint entire chimney side.				Repoint	RR	R					3.000
202		Repoint entire chimney side.				Repoint	RR	R					2.000
		Replace 5 no damaged bricks with							Remove			Remove	
		glazed bricks that match existing							fixings and			fixings and	
203		wall.				Remove fixings and repoint	RF, RR	R	repoint	RF, RR	R	repoint	5
204		Remove paint splashes				Remove paint splashes	ST	R					0.000
205		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
		Corm, out renaire to calit wind											
200		Carry out repairs to split window				Bis and an investment of the	DD 148						4 000
206		cill, return cill to original profile.				Pin and resin and Mortar Repair	PR, MR	R					1.000
207		Repoint entire pier between				Dan 1111	D.D.						6.000
207		adjacent windows. Repoint entire pier between				Repoint	RR	R	-			-	6.000
200		· ·				Panaint	DD	D					2 000
208		adjacent windows.		<u> </u>	<u> </u>	Repoint	RR	R	ļ	ļ			2.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
		Repoint entire pier between											
209		adjacent windows.				Repoint	RR	R					2.000
210		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
211		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
211		Replace 5 no damaged bricks with				Remove fixings and mortal repair	IXI, IVIIX	I.					2.000
		glazed bricks that match existing											
212		wall.				Replace brick	B:ID	R				5	5.000
213		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
213		Remove cable clips and make				nemore mango ana mortan repan	,	.,					2.000
214		mortar good.				Remove fixings and mortar repair	RF, MR	R					2.000
		Remove cable clips and make				g	,						
215		mortar good.				Remove fixings and mortar repair	RF, MR	R					4.000
216		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					8.000
217		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
218		Repoint wall approx 10 m2.				Repoint	RR	R	10.000		1.000	1	10.000
210		перопте мап арргох 10 птг.				керопп	NN	N.	10.000		1.000	1	10.000
219		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					2.000
220		Repoint Arch over window.				Repoint	RR	R					1.000
221		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
222		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
223		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
224		Repoint entire chimney side.				Repoint	RR	R					2.000
225		Repoint entire chimney side.				Repoint	RR	R					3.000
226		Repoint entire chimney side.				Repoint	RR	R					2.000
		Replace 5 no damaged bricks with				· ·							
		glazed bricks that match existing											
		wall. Also redundant fixings in				Replace 5 No brick, remove 4 No	B:ID, RF and						
227		locality.				fixings and mortar repair	MR	R					5.000
228		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
220		nepair reduitable scarroid fixing.				nemove names and mortal repair	111 , 19111	17					1.000
229		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
230		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
231		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	1	1.000
232		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
		Replace 5 no damaged bricks with]
		glazed bricks that match existing				Replace brick and remove paint							
233		wall. Also remove paint spalshes				splashes	B:ID & ST	R					5.000
234		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					6.000
419		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
		Repoint flashing full length of											
420		elevation.				Repoint	RR	R					

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
421		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	1	1.000
422		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
		Carry out further abrasive cleaning				Abrasive clean surround, 5"							
		to window surround. Paint grille				spinner variable speed, paint							
423		with new gloss paint finish.				grille		R					1.000
.23		With the W Bress Painte Illinois				Bc							1.000
424		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
501		Remove old clips and make good.				Remove fixings and mortar repair	RF, MR	R					20.000
502		Davida sa with 5 Na year bridge				Dania as with E Name which	D	В					5.000
503		Replace with 5 No new bricks Repoint Arch over window.				Replace with 5 No new bricks Repoint	B RR	R					1.000
303		Repolit Archiover Wildow.				Керопіс	IM	IX.					1.000
504		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
							·						
505		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
=06													2 000
506		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
507		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
539		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
		Remove existing plugs and make good 1 no brick & 4no mortar											
540		repairs				1 No brick 4 No mortar repairs	RF, MR	В					4.000
340		Remove old pipe clips and make				1 No brick 4 No mortal repairs	111 , 19111	В					4.000
541		good.				Remove fixings and mortar repair	RF, MR	R					22.000
542		Remove old clips and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
542		Damas a fining and make and				Danasa fining a sad as artes as as is	DE MD	D.					F 000
543		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
544		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
311		Nemore issuigs and make good.				nemove mange and mertal repair	,						3.000
545		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
583		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
584		Repoint Arch over window.				Repoint	RR	R					1.000
		Remove cable clips and make											
585		mortar good.				Remove fixings and mortar repair	RF, MR	R					2.000
506		Barra and discount and a second				5	DE 140						2.000
586		Remove old clips and make good. Remove cable clips and make				Remove fixings and mortar repair	RF, MR	R					3.000
587		mortar good.				Remove fixings and mortar repair	RF, MR	R					6.000
307		Seal up redundant services hole				nemove names and mortal repair	111 , 14111						0.000
588		with new brickwork.				Brick indents	B:ID	R					2.000
589		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
590		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
591		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
JJI		memove manigo and make good.		l .	l .	nemove namgs and mortal repair	INI , IVIN		l	ı	ı		4.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
592		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
606		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
000		Repoint wan approx 4 mz.				Керопте	IXIX	- 1	4.000		1.000		4.000
607		Remove old clips and make good.				Remove fixings and mortar repair	RF, MR	R					10.000
608		Reinstate cut service pipe.				Reinstate cut service pipe.	<u>, </u>	R					
609		Repoint Arch over window.				Repoint	RR	R					1.000
610		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
611		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
643							DE 14D						4.000
612	ing Haubuand Stuagt	Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
Courtyard lac	ing Herbrand Street							1	I				
235		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					4.000
233		Contractor to reinstate lead				Reinstate lead pipework to	111,11111	1,					4.000
		pipework to original condition.				original condition. (bent over to							
236		(bent over to clear scaffold)				clear scaffold)		R					
		Provide and fix new lead flashing to				Provide and fix new lead flashing							
		entire length of elevation. Point				to entire length of elevation.							
237		joint above flashing.				Point joint above flashing.	RR	R					7.000
		Repoint parapet wall under coping											
		including the top 3 no. courses,											
238		entire length of elevation.				Repoint	RR	R					2.100
		Refix rainwater goods after				Defrass brickwork and refix							
239		correcting spalled brickwork.				rainwater goods	DF	R					1.000
		Repoint Arch over window plus 1											
261		m2 above.				Repoint	RR	R					1.000
		Repoint Arch over window plus 1											
262		m2 above.				Repoint	RR	R					1.000
		Repoint Arch over window plus 1											
263		m2 above.				Repoint	RR	R					1.000
254		Abrasive clean stone corbel along				Abrasive clean corbel, 5" spinner		_					4 000
264		full length of elevation.				variable speed		R					1.000
265		Repoint Arch over window plus 1 m2 above.				Donaint	DD	R					1.000
205		III2 above.				Repoint	RR	K					1.000
266		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
		3 1 1 0 1 0 1				J 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	•						
267		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					3.000
268		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
		Remove cable clips and make				·							
269		mortar good.				Remove fixings and mortar repair	RF, MR	R					4.000
290		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
		Repoint Arch over window plus 1											4 000
291		m2 above.				Repoint	RR	R					1.000
292		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
292		nemove fixings and make good.				ivemove fixings and mortal repair	nr, IVIK	ĸ	<u> </u>				4.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
294		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
295		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
		Repoint entire pier between											
296		adjacent windows.				Repoint	RR	R					1.000
		Repoint Arch over window plus 2											
297		m2 above.				Repoint	RR	R					2.000
315		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					6.000
316		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
317		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
318		Repoint Arch over window.				Repoint	RR	R					1.000
		Replace 3 no damaged bricks with											
		glazed bricks that match existing											
319		wall.				Replace brick	B:ID	R				3	3.000
320		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					2.000
		Repoint Arch over window plus 2											
321		m2 above.				Repoint	RR	R					2.000
322		Repoint Arch over window plus 1 m2 above.				Repoint	RR	R					1.000
322		IIIZ above.				керопт	nn	K					1.000
351		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
352		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					1.000
353		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
						·							
354		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					3.000
255		Replace window cill to original				Market Breede	1.40						4.000
355		profile.				Mortar Repair	MR	R					1.000
356		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
		Return period lead pipe to pristine				Return period lead pipe to	,						
357		condition.				pristine condition.		R					
384		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
		Replace damaged bricks with											
		glazed bricks that match existing											
385		wall.				Replace brick	B:ID	R					2.000
386		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
387		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
388		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
389		, ,				, i	RR	R	2.000		1.000	1	2.000
389		Repoint wall approx 2 m2. Return period lead pipe to pristine				Repoint Return period lead pipe to	ĸĸ	K	2.000		1.000	1	2.000
390		condition.				pristine condition.		R					
391		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	1	1.000
392		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
393		Repoint Arch over window.	_			Repoint	RR	R					1.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
		Remove cable clips and make										1	1
394		mortar good.				Remove fixings and mortar repair	RF, MR	R	<u> </u>				4.000
Courtyard fac	ing Guilford Street			ı	ı		ı			ı	1		
		Barrier and the day of the										1	
		Repoint parapet wall under coping										1	1
		including the top 3 no. courses,						_				1	
240		entire length of elevation.				Repoint	RR	R					2.400
244		Repoint above lead flashing full				D	20					1	2 400
241		length of elevation.				Repoint Provide 6 no lead patches on	RR	R					2.400
		Dravida 6 na land natabas an				-							
		Provide 6 no lead patches on				existing flashing to prevent water							
242		existing flashing to prevent water				ingress into projecting							
242		ingress into projecting stonework.				stonework.	DD	R					2.000
243		Repoint entire chimney side.				Repoint	RR	R					2.000
244		Repoint entire chimney side. Repoint above lead flashing full				Repoint	RR	R					1.500
245		_				Domeint	D.D.	D					
245		length of elevation.				Repoint	RR	R					2.000
246		Repoint entire chimney side.				Repoint	RR	R					2.000
		Danair nortland stone coning also				Martar Danair, and ramous						I	1
247		Repair portland stone coping, also				Mortar Repair, and remove	NAD and DE	В				I	2 000
247		repair existing scaffolding fixing.				fixings	MR and RF	R					2.000
		Repair portland stone coping, also										I	1
		repoint under coping for full length										1	
248		of elevation.				Mortar repair and repoint	MR and RR	R					1.000
		Replace 2 no damaged bricks with										I	1
		glazed bricks that match existing										1	1
249		wall.				Replace brick	B:ID	R				2	2.000
								_				1	1
250		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
0.54								_				1	
251		Repair portland stone coping.				Mortar Repair	MR	R					1.000
								_				I	
252		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
252		Repoint above lead flashing full				D	20						
253		length of elevation.				Repoint	RR	R					
254		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	1	1.000
		Repoint above lead flashing full										I	l
255		length of elevation.				Repoint	RR	R					2.000
												I	
256		Repoint entire elevation facet.				Repoint	RR	R					2.000
												I	
257		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
258		Repoint Arch over window.				Repoint	RR	R	1		ļ	ı——	1.000
												I	
259		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R	1		ļ	ı——	12.000
												1	1
260		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					1.000
270		Refix rainwater goods.				Refix rainwater goods.		R					
271		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
												1	1
272		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R				<u>. </u>	4.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
273		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
		Remove cable clips and make											
274		mortar good.				Remove fixings and repoint	RF, RR	R					4.000
275		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
276		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
277		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
278		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
279		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
280		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
281		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
282		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
283		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					6.000
284		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
285		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
286		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
287		Remove cable clips and make mortar good.				Remove fixings and repoint	RF, RR	R					4.000
288		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
289		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					3.000
293		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
298		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
299		Repoint Arch over window plus 1 m2 above.				Repoint	RR	R					2.000
300		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
301		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
302		Repoint Arch over window plus 1 m2 above.				Repoint	RR	R					2.000
303		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
304		Remove fixings and make good.	_			Remove fixings and mortar repair	RF, MR	R					4.000
305		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
306		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
		Remove numerous fixings and						_					
307		make good. Remove numerous fixings and				Remove fixings and mortar repair	RF, MR	R					7.000
308		make good.				Remove fixings and mortar repair	RF, MR	R					11.000
300		Remove numerous fixings and				Nemove mangs and mortal repair	,						11.000
309		make good.				Remove fixings and mortar repair	RF, MR	R					5.000
		Repoint Arch over window plus 1											
310		m2 above.				Repoint	RR	R					2.000
311		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
312		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					6.000
		Repoint Arch over window plus 1					<u> </u>						
313		m2 above.				Repoint	RR	R					2.000
314		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
323		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
324		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
325		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
323		Repoint waii approx 3 mz.				Керопіс	III	В	3.000		1.000		3.000
326		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
327		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
328		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
329		Repoint Arch over window.				9 1	· · · · · · · · · · · · · · · · · · ·						1.000
330		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					3.000
331		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
332		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
333		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
334		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
335		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
336		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					1.000
330		Repoint Arch over window plus 2				nemove namga ana morear repair	111 , 14111						1.000
337		m2 above.				Repoint	RR	R					3.000
338		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					8.000
339		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					7.000
340		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
341		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					10.000
		Remove numerous fixings and											
342		make good.				Remove fixings and mortar repair	RF, MR	R					9.000
343		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
344		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
345		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
346		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					8.000
340		Remove fixings and make good.				Kemove fixings and mortal repair	NF, IVIN	N.					8.000
347		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
348		Repoint Arch over window.				Repoint	RR	R					1.000
349		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
350		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
358		Repoint wall approx 3 m2.				Repoint	RR	R	3.000		1.000	1	3.000
330		Remove cable clips and make				Керопіс	IIII	1	3.000		1.000		3.000
359		mortar good.				Remove fixings and mortar repair	RF, MR	R					2.000
360		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
361		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
		The state of the s				The state of the s	,						
362		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
363		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
364		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
365		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
366		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
367		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
368		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
369		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
370		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					9.000
371		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					8.000
371		Replace 2 no damaged bricks with				Remove fixings and morear repair	101 , 14110						0.000
		glazed bricks that match existing											
372		wall.				Replace brick	B:ID	R				2	2.000
373		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					9.000
374		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	1	1.000
375		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					9.000
376		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
377		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					6.000
378		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
379		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
380		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					3.000
380		nemove fixings and make good.				Remove fixings and mortal repair	IXI , IVIIX	IX.					3.000
381		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
382		Repair redundant scaffold fixing.				Remove fixings and mortar repair	RF, MR	R					1.000
		Return period lead pipe to pristine				Return period lead pipe to							
383		condition.				pristine condition.	200	R	2.000		4.000	4	2.000
384		Repoint wall approx 2 m2. Replace damaged bricks with				Repoint	RR	R	2.000		1.000	1	2.000
		glazed bricks that match existing											
385		wall.				Replace brick	B:ID	R					2.000
386		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
387		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
395		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
396		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
397		Repoint wall approx 4 m2.				Repoint	RR	R	4.000		1.000	1	4.000
398		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
399		Repoint wall approx 2 m2.				Repoint	RR	R	2.000		1.000	1	2.000
400		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
401		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
402		Repoint Arch over window.				Repoint	RR	R					1.000
403		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
404		Repoint wall approx 6 m2.				Repoint	RR	R	6.000		1.000	1	6.000
405		Repoint wall approx 5 m2.				Repoint	RR	R	5.000		1.000	1	5.000
406		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
407		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
408		Repoint Arch over window.				Repoint	RR	R					1.000
						·							
409		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					8.000
410		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					2.000
411		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					10.000
412		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000
413		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					5.000
414		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					6.000
415		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					4.000

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
416		Repoint Arch over window.				Repoint	RR	R					1.000
417		Remove fixings and make good.				Remove fixings and mortar repair	RF, MR	R					3.000
418		Repoint wall approx 1 m2.				Repoint	RR	R	1.000		1.000	1	1.000
Not shown or	n schedule Russell Sq facio	ng Herbrand but marked on wall with	stickers										
435		Mortar repair to 2 no bricks				Mortar repair to 2 no bricks	MR						2.000
435a		Cut and make new brick				Cut and make new brick	B:ID	R					1.000
436		glazed pointing				glazed pointing	RR						2.000
437		pointing over arch				pointing over arch	RR						1.000
438		3 no new bricks				3 no new bricks	B:ID	R					1.000
438a		remove clips and paint splashes				remove clips and paint splashes	MR						3.000
439		remove clips and make good				remove clips and make good	MR						12.000
440		mortar repaior to bricks				mortar repaior to bricks	MR						6.000
441		mortar repair to bricks				mortar repair to bricks	MR						6.000
442		remove and make good fixings				remove and make good fixings	MR						4.000
443		rake out and repoint bricks				rake out and repoint bricks	RR						2.000
444		repoint				repoint	RR						2.000
445		repoint				repoint	RR						2.000
446		repoint				repoint	RR						1.000
447		repoint				repoint	RR						2.000
448		repoint				repoint	RR						2.000
ADD 1		Replace damaged copings											25.000

VO 45 - Recess area to new link bridge

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
500		Pointing below coping				Repoint	RR	R				1	12.700
501		Remove vegetation				Repoint	RR	R				1	1.000
		Remove pie bracket and make				·							
502		good.				Remove fixings and mortar repair	RF, MR	R				1	
		Remove pie bracket and make											
503		good.				Remove fixings and mortar repair	RF, MR	R				1	
		Displaced Brickwork structural											
504		engineer to advise				Repoint Brickwork	RR	R					6.000
505		Repoint Glazed Bricks				Repoint Brickwork	RR	R					4.000
506		Repoint Glazed Bricks				Repoint Brickwork	RR	R					4.000
		Repoint coping and ensure copings											
507		are secure				Repoint copings	RR	R				Inc	
		Remove pipe bracket and make											
508		good.				Remove fixings and mortar repair	RF, MR	R				6	
		Remove pipe bracket and make											
509		good.				Remove fixings and mortar repair	RF, MR	R				5	
510		Repoint brickwork to stack				Repoint	RR	R				Inc elswhere	
511		Repoint brickwork				Repoint & 4 No mortar reapirs	RR	R				4	
512		Replace Flaununching				Flaunching	FL	R				Inc elswhere	
513		Replace Flaunching				Flaunching	FL	R				Inc elswhere	
		Repointing top 7 courses of											
514		chimney stack				Repointing to stack	RR	R				Inc elswhere	
515		Pointing to brickwork				Repoint	RR	R				Inc elswhere	
516		Pointing to Brickwork				Repoint	RR	R				Inc elswhere	
517		Pointing to brickwork				Repoint	RR	R				Inc elswhere	6.000
518		Pointing to brickwork				Repoint	RR	R					6.000
		Remove pipe bracket and make				Remove pipe bracket and make							
519		good.				good inc clean off paint	RF RR	R	0.100	0.100		1	
		Remove old Fixings & make good				Remove old fixings and make							
520		mortar repair				good	RF MR	R	0.075	0.075		18	
		Remove old Fixings & make good				Remove old fixings and make							
521`		mortar repair				good	RF MR	R	0.075	0.075		4	
		Remove old Fixings & make good				Remove old fixings and make							
522		mortar repair				good	RF MR	R	0.05	0.05		2	
		Remove old Fixings & make good				Remove old fixings and make							
523		mortar repair				good	RF MR	R	0.100	0.100		1	
						Brick up window with glazed							
						bricks externally and engineering							
1					1	bricks to inside face bonded into		1	1	ĺ			
524		Remove redundant window			<u> </u>	existing	BI	BI					

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
525		Repair concrete window jamb				Re render	R	R	1.300	0.600		2	
526		Pointing to glazed bricks				Repoint wall	RR	R	1.500	0.000		4	
527		Failed mastic cap				By others	1111					-	
528		Pointing to glazed bricks				Repoint wall	RR	R				2	
529		Reglaze damaged windows				By others	1111						
530		Redecorate window frames				By others							
- 550		reaccorate milacii frames				Remove old fixings and make							
531		Remove old Fixings				good	RF MR	R	0.100	0.100		4	
						Remove redundant pipe and			0.20			-	
						make good wall with Glazed							
532		Remove redundant pipe				bricks	B:ID	BI				5	
		Remove old Fixings & make good				Remove old fixings and make							
533		mortar repair				good	RF MR	R	0.075	0.075		14	
		Remove old Fixings & make good				Remove old fixings and make							
534		mortar repair				good	RF MR	R	0.05	0.05		8	
		Remove old Fixings & make good				Remove old fixings and make						_	
535		mortar repair				good	RF MR	R	0.100	0.100		2	
		Remove old Fixings & make good				Remove old fixings and make							
536		mortar repair				good	RF MR	R	0.05	0.05		5	
		Remove old Fixings & make good				Remove old fixings and make							
537		mortar repair				good	RF MR	R	0.100	0.100		5	
538		Replace soil pipe				Replace 6 No new bricks	B:ID	BI				6	
		Remove old Fixings & make good				Remove old fixings and make							
539		mortar repair				good	RF MR	R	0.05	0.05		2	
						Break back to a sound base re-							
						render incorporating a sound							
						base and apply a masonry paint							
540		Make good render wall				(Paint by others)	RR	R	4.200	1.300	0.500		
						Break back to a sound base re-							
						render incorporating a sound							
541		Make good render wall				base and apply a masonry paint	RR	R	Refer to 540				
542		Repointt arch				Repoit brickwork forming arch	RP	RP			ļ	1	
		Remove old Fixings & make good				Remove old fixings and make		_				_	
543		mortar repair				good	RF MR	R	0.075	0.075		4	
						Clean stone string course as rest							
544		Clean stone string course				of court yard							
						Repoint brickwork below length							
545		Repoint below stone string course				of string course	RR	R				2	
546						Repair coating as main part of							
546		Repar coating				courtyard	DD	-				2	
547		Pointing to glazed bricks				Repoint wall	RR	R				2	
548		Pointing to glazed bricks				Repoint wall	RR	R				4	

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
						Brick up window with glazed							
						bricks externally and engineering							
549		Remove Redundant window				bricks to inside face bonded into existing	ВІ	ВІ					
550		Pointing to glazed bricks				Repoint wall	RR	R				6	
330		Fornting to glazed bricks				Remove redundant pipe and	nn	N N				U	
						make good wall with Glazed							
551		Remove redundant pipe				bricks	B:ID	ВІ				4	
		Remove old Fixings & make good				Remove old fixings and make							
552		mortar repair				good	RF MR	R	0.050	0.050		4	
553		Repir concrete window jambs				Remove and re- render	RR	R	1.000	0.650		2	
554		Redecorate window frames				Redecorate with gloss paint			By Others				
						Ducal hash to a							
						Break back to a sound base re-							
						render incorporating a sound base and apply a masonry paint							
555		Make good render wall				(Paint by others)	RR	R	4.200	1.300	0.500		
556		Pointing to glazed bricks				Repoint wall	RR	R	4.200	1.500	0.500	2	
557		Pointing to glazed bricks				Repoint wall	RR	R				4	
		Remove old Fixings & make good				Remove old fixings and make							
558		mortar repair				good	RF MR	R	0.100	0.100		16	
559		Reglaze damaged windows				By others							
		Remove old Fixings & make good				Remove old fixings and make							
560		mortar repair				good	RF MR	R	0.100	0.100		1	
		Remove old Fixings & make good				Remove old fixings and make		_					
560a 561		mortar repair Pointing to glazed bricks				good Repoint wall	RF MR RR	R R	0.075	0.075		20 4	
201	1	Pointing to glazed bricks				Repoint Wall	KK	K				4	
						Brick up window with glazed							
						bricks externally and engineering							
						bricks to inside face bonded into							
562		Remove Redundant window				existing	ВІ	ВІ					
		Remove old Fixings & make good				Remove old fixings and make							
563		mortar repair				good	RF MR	R	0.075	0.075		20	
564		Redecorate window frames				Redecorate with gloss paint			By Others				
565		Repair concrete window jambs				Remove and re- render	RR	R	1.000	0.650		2	
												_	
566		Repair concrete window jambs				Remove and re- render	RR	R	1.000	0.650		See 560	
567		Pointing to glazed bricks				Repoint wall	RR	R				4	
568		Repointt arch				Repoit brickwork forming arch	RP	RP				1	
		Remove old Fixings & make good				Remove old fixings and make							
569		mortar repair				good	RF MR	R	0.050	0.050		4	

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
570		Repointt arch				Repoit brickwork forming arch	RP	RP				1	
570		Remove old Fixings & make good				Remove old fixings and make	KP.	NP.				1	
571						· ·	RF MR	R	0.050	0.050		2	
5/1	ľ	mortar repair				good	KF IVIK	ĸ	0.050	0.050			
572		Repointt arch				Repoit brickwork forming arch	RP	RP				1	
372		Remove old Fixings & make good				Remove old fixings and make	NF	NF.				1	
573		mortar repair				good	RF MR	R	0.075	0.075		12	
373		Remove old Fixings & make good				Remove old fixings and make	IXI IVIIX	IX.	0.073	0.073		12	
574		mortar repair				good	RF MR	R	0.075	0.075		16	
575		Pointing to glazed bricks				Repoint wall	RR	R	0.073	0.073		4	
3.5		Remove old Fixings & make good				Remove old fixings and make							
576	1	mortar repair				good	RF MR	R	0.075	0.075		20	
3.0		ortal repair				Boom			0.075	0.075			
						Brick up window with glazed							
						bricks externally and engineering							
						bricks to inside face bonded into							
577		Remove Redundant window				existing	ВІ	ВІ					
						Break back to a sound base re-							
						render incorporating a sound							
						base and apply a masonry paint							
578		Make good render wall				(Paint by others)	RR	R	4.200	1.300	0.500		
		0				(1 11, 11 1, 11							
						Break back to a sound base re-							
						render incorporating a sound							
						base and apply a masonry paint							
578a		Make good render wall				(Paint by others)	RR	R	1.200	0.650	0.500		
579		Pointing to glazed bricks				Repoint wall	RR	R				4	
		Ü				,							
580		Repointt arch				Repoit brickwork forming arch	RP	RP				1	
581	i l	Pointing to glazed bricks				Repoint wall	RR	R				1	
582		Pointing to glazed bricks				Repoint wall	RR	R				2	
	į į	Remove old Fixings & make good				Remove old fixings and make							
583]	mortar repair				good	RF MR	R	0.075	0.075		8	
584		Pointing to glazed bricks				Repoint wall	RR	R				2	
		Remove old Fixings & make good				Remove old fixings and make							
585		mortar repair				good	RF MR	R	0.075	0.075		12	
		Remove old Fixings & make good				Remove old fixings and make							
586		mortar repair				good	RF MR	R	0.075	0.075		20	
587]	Pointing to glazed bricks				Repoint wall	RR	R				4	
588		Pointing to glazed bricks				Repoint wall	RR	R				4	
						remocve redundant pipe and							
						make good wall with new glazed							
589		remove redundant pipe			1	bricks	ВІ	ВІ				8	ĺ

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
						Hack of existing and re-new in							
590		Repair concrete window jamb				render	RR	R	1.200	0.650		2	
591		Replace soil pipe				By Others							
592		Redecorate window frames				By Others							
						Break back to a sound base re-							
						render incorporating a sound							
						base and apply a masonry paint							
593		Make good render wall				(Paint by others)	RR	R	1.200	1.300	0.500		
594		Pointing to glazed bricks				Repoint wall	RR	R				4	
		Remove old Fixings & make good				Remove old fixings and make							
595		mortar repair				good	RF MR	R	0.075	0.075		3	<u> </u>
		Remove old Fixings & make good				Remove old fixings and make							
596		mortar repair				good	RF MR	R	0.075	0.075		6	
		Remove old Fixings & make good				Remove old fixings and make							
597		mortar repair				good	RF MR	R	0.075	0.075		4	
		Remove old Fixings & make good				Remove old fixings and make			0.0.0	0.0.0			
598		mortar repair				good	RF MR	R	0.075	0.075		4	
330		Remove old Fixings & make good				Remove old fixings and make			0.075	0.075			
599		mortar repair				good	RF MR	R	0.075	0.075		4	
333		Remove old Fixings & make good				Remove old fixings and make			0.075	0.075			
600		mortar repair				good	RF MR	R	0.075	0.075		6	
- 000		Remove old Fixings & make good				Remove old fixings and make	14114		0.075	0.073		- ŭ	
601		mortar repair				good	RF MR	R	0.075	0.075		10	
001		Remove old Fixings & make good				Remove old fixings and make	14114		0.075	0.073		10	
602		mortar repair				good	RF MR	R	0.075	0.075		6	
002		mortar repair				g000	14114		0.075	0.073		- ŭ	
		Remove old Fixings & make good				Remove old fixings and make						ĺ	1
603		mortar repair				good	RF MR	R	0.500	0.500		2	1
604		Pointing to glazed bricks				Repoint wall	RR	R				2	<u> </u>
												_	
						Brick up window with glazed							
						bricks externally and engineering						ĺ	1
						bricks to inside face bonded into						ĺ	1
605		Remove Redundant window				existing	ВІ	BI					
606		Pointing to glazed bricks				Repoint wall	RR	R				2	
607		Pointing to glazed bricks				Repoint wall	RR	R				2	
608		Redecorate window frames				By Others	••					_	
609		Pointing to glazed bricks				Repoint wall	RR	R				4	
		5 5 1 1				,							
610		Repointt arch				Repoit brickwork forming arch	RP	RP				1	
611		Pointing to glazed bricks				Repoint wall	RR	R				2	
		- 0											
612		Repointt arch				Repoit brickwork forming arch	RP	RP				1	

ITEM	ELEVATION	DESCRIPTION OF WORK AREA	LENGTH	DEPTH	HEIGHT	REPAIR	CODE	RATING	LENGTH	DEPTH	HEIGHT	NO	QTY
		Remove old Fixings & make good				Remove old fixings and make							
613		mortar repair				good	RF MR	R	0.500	0.500		4	
		Remove old Fixings & make good				Remove old fixings and make							
614		mortar repair				good	RF MR	R	0.500	0.500		3	
615		Pointing to glazed bricks				Repoint wall	RR	R				2	