Condition survey and method statement/s

prepared by an accredited conservator to

be approved before the work proceeds.

REV: -A

В

C D DATE: 29/03/16 05/05/16

08/12/16

10/02/17 01/03/17 DETAILS:

ISSUE STATUS: For Planning

RICHARD GRIFFITHS ARCHITECTS

5 Maidstone Mews, 72-76 Borough High Street, London SEI 1GN

T +44 (0) 20 7357 8788 | F+44 (0) 20 7403 7887

E admin@rgarchitects.com | www.rgarchitects.com

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WLGF-01	2 windows; 1 light top hung casement; 2 light side hung casement. Grill to top window	09-06 Service Bedroom (to terrace)	Timber	Timber	Replace the casement like for like within the existing frame and with new laminated glass. Profiles to match existing.	
WLGF-02	2 windows; 1 light top hung casement; 2 light side hung casement. Grill to top window	09-06 Service Bedroom (to terrace)			Replace the casement like for like within the existing frame and with new laminated glass. Profiles to match existing.	
WLGF-03	Consent 2014/7932/P to remove				Remove existing window and replace with door DLGF-22.	
WLGF-04	8 over 8 sash	09-02 Kitchen/Dining (to terrace)			Replace the sash like for like within the existing frame and with new laminated glass. Profiles to match existing.	
WLGF-05	Consent 2014/7932/P to remove				Remove existing window and replace with door DLGF-21.	

Action: REV: DATE: DETAILS:

Condition survey and method statement/s A 05/05/16 prepared by an accredited conservator to B 08/12/16 be approved before the work proceeds. C 10/02/17 D 01/03/17

ISSUE STATUS: For Planning

RICHARD GRIFFITHS ARCHITECTS

5 Maidstone Mews, 72-76 Borough High Street, London SE1 1GN T +44 (0) 20 7357 8788 | F+44 (0) 20 7403 7887

E admin@rgarchitects.com | www.rgarchitects.com

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WLGF-06	3 windows; 2 over 2 sash; 8 over 8 sash: 2 over 2 sash	09-03 Living (to terrace)			Remove existing windows and replace with door DLGF-24.	
WLGF-07	6 over 6 sash, with shutters	09-04 Bedroom			Replace the sash like for like within the existing frame and with new laminated glass. Profiles to match existing. Retain shutters.	
WLGF-08	2 over 4 sash with shutters	09-03 Living			Remove existing window. Adapt opening and reinstate new window with laminated glass, to match WLGF-09.	
WLGF-09	2 over 4 sash Sash with shutters	13-09 LGF Landing			Replace the sash like for like within the existing frame and with new laminated glass. Profiles to match existing. Replace frosted glass with clear.	
WLGF-10	3 over 3 sash, opaque glass	09-11 Pool			No action	

Action: Condition survey and method statement/s

prepared by an accredited conservator to

be approved before the work proceeds.

REV: DATE: - 29/03/16

05/05/16

08/12/16

10/02/17 01/03/17

Α

В

C D DETAILS:

ISSUE STATUS: For Planning **RICHARD GRIFFITHS ARCHITECTS**

5 Maidstone Mews, 72-76 Borough High Street, London SE1 1GN

T +44 (0) 20 7357 8788 | F +44 (0) 20 7403 7887 E admin@rgarchitects.com | www.rgarchitects.com

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WLGF-11	3 over 3 sash	09-11 Pool			No action	
WLGF-12	3 over 3 sash	09-11 Pool			No action	
WLGF-13	New window	09-03 Living			New window to match opening and profile of WLGF-09	
WGF-01	2 windows; 1 light top hung casement, 3 light side hung casement	10-04 Kitchen			Replace the casement like for like within the existing frame and with new laminated glass. Profiles to match existing.	
WGF-02	2 windows; 1 light top hung casement, 6 light fixed window	10-04 Kitchen			Replace the casement like for like within the existing frame and with new laminated glass. Profiles to match existing.	

Condition survey and method statement/s

prepared by an accredited conservator to

be approved before the work proceeds.

REV:

Α

В

C D DATE: 29/03/16

05/05/16

08/12/16

10/02/17 01/03/17 DETAILS:

ISSUE STATUS: For Planning

RICHARD GRIFFITHS ARCHITECTS

5 Maidstone Mews, 72-76 Borough High Street, London SE1 1GN

T +44 (0) 20 7357 8788 | F +44 (0) 20 7403 7887

E admin@rgarchitects.com | www.rgarchitects.com

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WGF-03	2 windows; 1 light top hung casement, 3 light side hung casement	10-04 Kitchen			Replace the casement like for like within the existing frame and with new laminated glass. Profiles to match existing.	
WGF-04	2 windows; 1 light fixed fanlight, 1 light side hung casement	10-06 Lounge			Replace the window like for like within the existing frame and with new laminated glass. Profiles to match existing.	
WGF-05	2 windows; 1 light fixed fanlight, 1 light side hung casement	10-06 Lounge			Replace the window like for like within the existing frame and with new laminated glass. Profiles to match existing.	
WGF-06	3 over 6 sash	10-07 TV Room			Replace the sash like for like within the existing frame and with new laminated glass. Profiles to match existing.	

Action: Condition survey and method statement/s

prepared by an accredited conservator to

be approved before the work proceeds.

REV: DATE: - 29/03/16 A 05/05/16

08/12/16

10/02/17 01/03/17

В

C D DETAILS:

ISSUE STATUS: For Planning

RICHARD GRIFFITHS ARCHITECTS

5 Maidstone Mews, 72-76 Borough High Street, London SE1 1GN

T +44 (0) 20 7357 8788 | F +44 (0) 20 7403 7887 E admin@rgarchitects.com | www.rgarchitects.com

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WGF-07	Arched 6 over 3 sash	10-07 TV Room			Replace the sash like for like within the existing frame and with new laminated glass. Profiles to match existing. Realign window cill.	
WGF-08	8 over 8 sash	10-06 Lounge			Replace the sash like for like within the existing frame and with new laminated glass. Profiles to match existing.	
WGF-09	8 over 8 sash, bottom Sash frosted glass	13-10 GF Landing			Replace the sash like for like within the existing frame and with new laminated glass. Profiles to match existing.	
WGF-10	6 over 6 sash, with shutters	10-03 Guest WC			Replace the sash like for like within the existing frame and with new laminated glass. Profiles to match existing.	

Action: REV: DATE:

Condition survey and method statement/s prepared by an accredited conservator to be approved before the work proceeds.

DATE: 29/03/16 05/05/16

08/12/16

10/02/17 01/03/17 DETAILS:

ISSUE STATUS: For Planning

RICHARD GRIFFITHS ARCHITECTS

5 Maidstone Mews, 72-76 Borough High Street, London SE1 1GN T +44 (0) 20 7357 8788 | F+44 (0) 20 7403 7887

E admin@rgarchitects.com | www.rgarchitects.com

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WGF-11	3 windows; 1 over 1 sash, 2 over 2 sash 1 over 1 sash	10-09 Studio			No action	
WGF-12	Triangular 3 light window, fixed, with diamond leading and coloured glass to side lights on external panes.	10-09 Studio			No action	
WFF-01	2 windows; 1 light top fanlight, 3 light side hung casement	11-04 Master Bathroom			Repair and redecorate existing window, add draught seal.	
WFF-02	2 windows; 2 light top fanlight, 6 light fixed window	11-04 Master Bathroom			Repair and redecorate existing window, add draught seal.	

Action: REV Condition survey and method statement/s

prepared by an accredited conservator to

be approved before the work proceeds.

REV: DATE: - 29/03/16 A 05/05/16

C

11-01 Anti-Chamber

08/12/16

10/02/17

01/03/17

DETAILS:

ISSUE STATUS: For Planning

RICHARD GRIFFITHS ARCHITECTS

5 Maidstone Mews, 72-76 Borough High Street, London SE1 1GN

T +44 (0) 20 7357 8788 | F +44 (0) 20 7403 7887 E admin@rgarchitects.com | www.rgarchitects.com

Richard Griffiths Architects is the trading name of Richard Griffiths Architects Ltd

REPAIRS/ACTIONS **IMAGE EXISTING WINDOW** FRAME **DESCRIPTION** WINDOW LOCATION WINDOW CONSTRUCTION CONSTRUCTION Repair and redecorate existing window, add draught seal. 2 windows; 1 light top fanlight, WFF-03 11-04 Master Bathroom 3 light side hung casement Repair and redecorate existing window, add draught seal. 8 over 8 WFF-04 11-03 Dressing sash Repair and redecorate existing window, add draught seal. 6 over 6 WFF-05 11-03 Dressing sash Repair and redecorate existing window, add draught seal. 6 over 6 WFF-06 11-03 Dressing sash

WFF-07

8 over 8

sash

Repair and redecorate existing window, add draught seal.

Action: Condition survey and method statement/s

prepared by an accredited conservator to

be approved before the work proceeds.

REV: DATE: - 29/03/16

05/05/16

08/12/16

10/02/17 01/03/17

Α

В

C D DETAILS:

ISSUE STATUS: For Planning

RICHARD GRIFFITHS ARCHITECTS

5 Maidstone Mews, 72-76 Borough High Street, London SE1 1GN

T +44 (0) 20 7357 8788 | F +44 (0) 20 7403 7887 E admin@rgarchitects.com | www.rgarchitects.com

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WFF-08	8 over 8 sash	13-11 First Floor Landing			Repair and redecorate existing window, add draught seal.	
WFF-09	8 over 8 sash	13-11 First Floor Landing			Repair and redecorate existing window, add draught seal.	
WFF-10	6 over 6 sash	11-04 Master Bathroom			Repair and redecorate existing window, add draught seal.	

Condition survey and method statement/s

prepared by an accredited conservator to

be approved before the work proceeds.

REV:

Α

В

C D DATE: 29/03/16 05/05/16

08/12/16

10/02/17 01/03/17 DETAILS:

ISSUE STATUS: For Planning

RICHARD GRIFFITHS ARCHITECTS

5 Maidstone Mews, 72-76 Borough High Street, London SEI 1GN

T +44 (0) 20 7357 8788 | F+44 (0) 20 7403 7887

E admin@rgarchitects.com | www.rgarchitects.com

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WSF-01	2 windows; 1 light top fanlight, 3 light side hung casement	12-03 Guest Bedroom 2			Repair and redecorate existing window, add draught seal.	
WSF-02	2 windows; 2 light top fanlight, 6 light fixed window	12-03 Guest Bedroom 2			Repair and redecorate existing window, add draught seal.	
WSF-03	2 windows; 1 light top fanlight, 3 light side hung casement	12-03 Guest Bedroom 2			Repair and redecorate existing window, add draught seal.	
WSF-04	2 windows; 2 light side hung casement, centrally opening	12-04 Guest Lounge			Reconfigure window to balance with WSF-05, and be centred around terrace door. New window to match existing WSF-06 and WSF-07.	

Condition survey and method statement/s

prepared by an accredited conservator to

be approved before the work proceeds.

REV:

Α

В

C D DATE: 29/03/16

05/05/16

08/12/16

10/02/17 01/03/17 DETAILS:

ISSUE STATUS: For Planning **RICHARD GRIFFITHS ARCHITECTS**

5 Maidstone Mews, 72-76 Borough High Street, London SE1 1GN

T +44 (0) 20 7357 8788 | F +44 (0) 20 7403 7887 E admin@rgarchitects.com | www.rgarchitects.com

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WSF-05	3 over 6 sash	12-04 Guest Lounge			Relocate and reconfigure window to balance with WSF-04, and be centred around terrace door. New window to match existing WSF-06 and WSF-07.	
WSF-06	3 over 6 sash	12-05 Guest Bedroom 1			Repair and redecorate existing window, add draught seal.	
WSF-07	3 over 6 sash	12-05 Guest Bedroom 1			Repair and redecorate existing window, add draught seal.	
WSF-08	Arched 4 light window, fixed.	12-05 Guest Bedroom 1 (roof gable)			Repair and redecorate existing window, add draught seal.	
WSF-09	3 over 6 sash	12-06 Guest Bathroom 1			Repair and redecorate existing window, add draught seal.	

Action: REV:

Condition survey and method statement/s prepared by an accredited conservator to be approved before the work proceeds.

DATE: 29/03/16 05/05/16 08/12/16

> 10/02/17 01/03/17

Α

В

C D DETAILS:

ISSUE STATUS: For Planning

RICHARD GRIFFITHS ARCHITECTS

5 Maidstone Mews, 72-76 Borough High Street, London SE1 1GN

T +44 (0) 20 7357 8788 | F +44 (0) 20 7403 7887 E admin@rgarchitects.com | www.rgarchitects.com

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WSF-10	3 over 6 sash	13-12 Second Floor Landing			Repair and redecorate existing window, add draught seal.	
WSF-11	3 over 6 sash	13-12 Second Floor Landing (stair)			Repair and redecorate existing window, add draught seal.	
WSF-12	2 windows; 8 light fixed windows, 8 light side hung casement	12-01 Half Landing	Metal	Timber	Replace with new sash window to match existing profiles and the other windows on the façade.	
WSF-13	6 over 6 sash, bottom sash frosted glass. Vent to top right light.	12-02 Guest Bathroom 2			Repair and redecorate existing window, add draught seal. Remove vent, replace frosted glass with clear.	
WSF-14	Arched 4 light window, fixed.	12-04 Guest Lounge (roof gable)			Repair and redecorate existing window, add draught seal.	
WRL-01	Roof light	10-09 Studio			No action.	

REV: DATE: DETAILS: ISSUE STATUS: Action: RICHARD GRIFFITHS ARCHITECTS 29/03/16 For Planning Condition survey and method statement/s 5 Maidstone Mews, 72-76 Borough High Street, London SEI 1GN Α 05/05/16 prepared by an accredited conservator to T +44 (0) 20 7357 8788 | F +44 (0) 20 7403 7887 08/12/16 E admin@rgarchitects.com | www.rgarchitects.com be approved before the work proceeds. С 10/02/17

EXISTING WINDOW	DESCRIPTION	WINDOW LOCATION	WINDOW CONSTRUCTION	FRAME CONSTRUCTION	REPAIRS/ACTIONS	IMAGE
WRL-01	Roof light	10-09 Studio			No action.	

NOTES:

1. Refer to drawings: Proposed - D100, D101, D102, D103, D104 Demolition - D01, D02, D03, D04, D05 Existing - EX01, EX02, EX03, EX04, EX05

01/03/17