

For structural dimensions and details see Structural Engineers' drawings.


All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

- Paint accumulation removed from plaster cornice using paint-stripping poultice-sheet such as Peel Away or similar. Residual paint carefully removed with fine pick-tools and brush to fully recover cornice moulding detail.
- Ceiling and cornice plasterwork redecorated with one stabilising coat and 2 coats of micro-porous paint, colour off-white.
- Timber framed and plasterboard partition taken down, Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.
- 4. Timber panelling and skirting rubbed down and redecorated
- 5. Marble Chimney piece cleaned and polished



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road имстить Existing Ground Floor Elevation A

1701(-)000 FOR INFORMATION OW 06/03/2017 scale 1 : 20 @ A3

1.0 M ____



For structural dimensions and details see Structural Engineers' drawings.


All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

- Paint accumulation removed from plaster cornice using paint-stripping poultice-sheet such as Peel Away or similar. Residual paint carefully removed with fine pick-tools and brush to fully recover cornice moulding detail.
- Ceiling and cornice plasterwork redecorated with one stabilising coat and 2 coats of micro-porous paint, colour off-white.
- 3. Window and shutter joinery redecorated.
- 4. Timber frame and plasterboard partition taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.
- 5. Timber panelling and skirting rubbed down and redecorated
- 6. Marble Chimney piece cleaned and polished



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

Existing Ground Floor Elevation B

1701(-)001 FOR INFORMATION OW 06/03/2017 scale 1 : 20 @ A3



For structural dimensions and details see Structural Engineers' drawings.


All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

- Paint accumulation removed from plaster cornice using paint-stripping poultice-sheet such as Peel Away or similar. Residual paint carefully removed with fine pick-tools and brush to fully recover cornice moulding
- Ceiling and cornice plasterwork redecorated with one stabilising coat and 2 coats of micro-porous paint, colour off-white.
- 3. Window and shutter joinery redecorated.
- 4. Timber frame and plasterboard partition taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.
- 5. Timber panelling and skirting rubbed down and redecorated
- Former lateral door-opening to Nr 20 Theobalds
 Road to be retained blocked-up. Door frame and
 surround to be retained.




HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

имстить Existing Ground Floor Elevation C 1701(-)002

FOR INFORMATION OW 06/03/2017 SCALE 1 : 20 @ A3



For structural dimensions and details see Structural Engineers' drawings.

All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.


All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

Modern timber frame / plasterboard faced partition to be demolished to reveal original cast iron balustrade.

Balustrade redecorated in black paint, handrail refurbished.

3. Stairwell walls and joinery to be redecorated




HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

Existing Ground Floor Elevation D 1.0 M _J

1701(-)003 FOR INFORMATION OW 06/03/2017 SCALE 1 : 20 @ A3



For structural dimensions and details see Structural Engineers' drawings.


All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

- Paint accumulation removed from plaster cornice using paint-stripping poultice-sheet such as Peel Away or similar. Residual paint carefully removed with fine pick-tools and brush to fully recover cornice moulding
- Ceiling and cornice plasterwork redecorated with one stabilising coat and 2 coats of micro-porous paint, colour off-white.
- Timber framed and plasterboard partition taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.
- 4. Timber panelling and skirting rubbed down and redecorated
- 5. Marble Chimney piece cleaned and polished




HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road Existing First Floor Elevation A

1701(-)010 FOR INFORMATION OW 06/03/2017 Scale 1 : 20 @ A3

1.0 M J



For structural dimensions and details see Structural Engineers' drawings.


All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

- Paint accumulation removed from plaster cornice using paint-stripping poultice-sheet such as Peel Away or similar. Residual paint carefully removed with fine pick-tools and brush to fully recover cornice moulding
- Ceiling and cornice plasterwork redecorated with one stabilising coat and 2 coats of micro-porous paint, colour off-white.
- 3. Window and shutter joinery redecorated.
- 4. Timber frame and plasterboard partition taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.
- 5. Timber panelling and skirting rubbed down and redecorated
- 6. Marble Chimney piece cleaned and polished



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

Existing First Floor Elevation B

1701(-)011 FOR INFORMATION OW 06/03/2017 1 : 20 @ A3



For structural dimensions and details see Structural Engineers' drawings.


All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

- Paint accumulation removed from plaster cornice using paint-stripping poultice-sheet such as Peel Away or similar. Residual paint carefully removed with fine pick-tools and brush to fully recover cornice moulding detail.
- Ceiling and cornice plasterwork redecorated with one stabilising coat and 2 coats of micro-porous paint, colour off-white.
- 3. Window and shutter joinery redecorated.
- 4. Timber frame and plasterboard partition taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.
- 5. Timber panelling, door and skirting rubbed down and redecorated




HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road Existing First Floor Elevation C

1701(-)012 FOR INFORMATION OW 06/03/2017 scale 1 : 20 @ A3

1.0 M J



For structural dimensions and details see Structural Engineers' drawings.

All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.


All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

Modern timber frame / plasterboard faced partition to be demolished to reveal original cast iron balustrade.

Balustrade redecorated in black paint, handrail refurbished.

3. Stairwell walls and joinery to be redecorated




HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

Existing First Floor Elevation D

1701(-)013 FOR INFORMATION OW 06/03/2017 SCALE 1 : 20 @ A3

1.0 M _J



For structural dimensions and details see Structural Engineers' drawings.


All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

- Paint accumulation removed from plaster cornice using paint-stripping poultice-sheet such as Peel Away or similar. Residual paint carefully removed with fine pick-tools and brush to fully recover cornice moulding detail.
- Ceiling and cornice plasterwork redecorated with one stabilising coat and 2 coats of micro-porous paint, colour off-white.
- 3. Window and shutter joinery redecorated.
- 4. Timber frame and plasterboard partition taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.
- 5. Timber panelling and skirting rubbed down and redecorated



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

Existing First Floor Elevation E 1701(-)014 FOR INFORMATION

1.0 M OW 06/03/2017 1 : 20 @ A3

Do not scale this drawing.

For structural dimensions and details see Structural Engineers' drawings.

All dimensions to be checked on site proir to


commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

Timber frame and plasterboard partition taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.

Existing walls, ceilings and joinery made good, rubbed down and redecorated




HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road Existing Second Floor Elevation A

1701(-)020

1.0 M FOR INFORMATION OW 06/03/2017 1 : 20 @ A3



For structural dimensions and details see Structural Engineers' drawings.


All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

- Timber frame and plasterboard partitions taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.
- Existing walls, ceilings and joinery made good, rubbed down and redecorated
- 3. Marble Chimney piece cleaned and polished



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

OW 06/03/2017 1 : 20 @ A3

22 Theobalds Road

Existing Second Floor Elevation B 1701(-)021 FOR INFORMATION

1.0 M _

Do not scale this drawing. Engineers' drawings. All dimensions to be checked on site proir to drawings. reported to the Architect. Consultant's Information. 1 1 1.0 M OW 06/03/2017 1 : 20 @ A3

For structural dimensions and details see Structural


commencement of any works or preperation of any shop

All errors in co-ordinates, levels and dimensions, are to be

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other

Timber frame and plasterboard partitions taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.

Existing walls, ceilings and joinery made good, rubbed down and redecorated



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

Existing Second Floor Elevation C 1701(-)022 FOR INFORMATION

3 3 STAIR TO THIRD FLOOR 1

Do not scale this drawing.

For structural dimensions and details see Structural Engineers' drawings.

All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.


All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

Modern timber frame / plasterboard faced partition to be demolished to reveal original cast iron balustrade.

Balustrade redecorated in black paint, handrail refurbished.

3. Stairwell walls and joinery to be redecorated




HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

1.0 M ____

22 Theobalds Road Existing Second Floor Elevation D

1701(-)023 FOR INFORMATION OW 06/03/2017 scale 1 : 20 @ A3



For structural dimensions and details see Structural

Engineers' drawings. All dimensions to be checked on site proir to


commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

Timber frame and plasterboard partitions taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.

Existing walls, ceilings and joinery made good, rubbed down and redecorated



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

Existing Second Floor Elevation E 1701(-)024 1.0 M

FOR INFORMATION OW 06/03/2017 1 : 20 @ A3

Do not scale this drawing. For structural dimensions and details see Structural Engineers' drawings. All dimensions to be checked on site proir to


commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

Timber frame and plasterboard partitions taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.

Existing walls, ceilings and joinery made good, rubbed down and redecorated



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

Existing Attic Floor Elevation A

PROJECT NUMBER 1702

DRAWING NUMBER 1701(-)030

1.0 M _

FOR INFORMATION OW 06/03/2017 scale 1 : 20 @ A3

Do not scale this drawing. For structural dimensions and details see Structural

reported to the Architect.


Engineers' drawings. All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings. All errors in co-ordinates, levels and dimensions, are to be

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

Timber frame and plasterboard partitions taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.

Existing walls, ceilings and joinery made good, rubbed down and redecorated



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

PROJECT NUMBER DRAWING NUMBER 1701 (-)031 FOR INFORMATION OW 06/03/2017 scale 1 : 20 @ A3

1.0 M ____

Do not scale this drawing. For structural dimensions and details see Structural


Engineers' drawings.

All dimensions to be checked on site proir to commencement of any works or preperation of any shop

drawings. All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

- Timber frame and plasterboard partitions taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces.
- Sash windows overhauled. Neoprene draft-stripping fitted to staff beads and sashes.
- 3. Existing walls, ceilings and joinery made good, rubbed down and redecorated



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

22 Theobalds Road

PROJECT NUMBER DRAWING NUMBER 1701 (-)032 FOR INFORMATION

OW 06/03/2017 scale 1 : 20 @ A3

Do not scale this drawing.

For structural dimensions and details see Structural Engineers' drawings.


All dimensions to be checked on site proir to

commencement of any works or preperation of any shop drawings.

All errors in co-ordinates, levels and dimensions, are to be reported to the Architect.

All temporary works to be responsibility of the contractor. This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

- Timber frame and plasterboard partitions taken down. Partition fixing holes to wall and ceiling plaster in filled with plaster of Paris rubbed down smooth and level to the adjacent surfaces
- Sash windows overhauled. Neoprene draft-stripping fitted to staff beads and sashes.
- 3. Existing walls, ceilings and joinery made good, rubbed down and redecorated



HOLISTIC Chartered Building Surveyors &
Historic Building Consultants
5 Blenheim Street, London, W1S 1LD
T: 020 7183 1751
E: mail@holistic.uk.com

OW 06/03/2017 scale 1 : 20 @ A3

22 Theobalds Road

PROJECT NUMBER DRAWING NUMBER 1701 (-)033 FOR INFORMATION