Α

В

С

D

Ε

- Notes
 1. Carefully remove and replace existing door between existing WC and media room, and replace with painted timber door suitable to
- period of house. 2. Carefully remove and replace existing external door between existing WC and light well, and replace with painted hardwood door suitable to period of house
- 3. Ceiling finish: plasterboard lining, with 2-3mm skim coat and paint finish
- 4. Double glazed door 5. Fitted joinery to new utility room. Associated
- service connections required to connect to existing below ground drainage route. Flush timber door
- 7. Full height double glazed fixed windows in timber structure
- 8. Garden wall lined now within new extension to be insulated and lined
- 9. New coir entrance matt 10. New engineered timber floor finish.
- 11. New folding doors to media room
- 12. New GF WC. Services to connect to existing below ground drainage
- 13. New internal partition: timber stud partition lined in plywood and plasterboard, with 2-3mm skim coat. Paint finish.
- 14. New opening in wall from hall to Structural
- Engineer's design 15. New painted plaster soffit around rooflight
- 16. New PPC metal staircase and balustrade
- 17. New replacement walk on roof light glass
- 18. New roof light glass (above)
- 19. New sanitary ware and associated service connections required to connect to existing below ground drainage route
- 20. New shallow timber joinery to entrance lobby
- 21. New skirting in painted timber to match existing 22. New tiled floor finish
- 23. New tiled floor to hall
- 24. New timber decking to garden terrace 25. New timber floor finish to basement
- staircase
- 26. New two storey rear extension
- 27. Painted plaster finish to staircase wall
- 28. Painted plaster wall finish
- 29. Vaults tanked for plant
- 30. Replace existing lighting with new light
- fixture by stair entrance
- 31. Replacement lighting to front light well 32. Replacement painted metal security bars to
- media room windows 33. Staircase including steps and balustrade to be redecorated. New carpet runner to
- staircase
- 34. Timber desk, lining and book cases to study 35. Timber lined wall and book shelves
- 36. Upgrade existing electrical distribution board 37. Timber lined wall
- 38. Painted timber fitted joinery to new entrance hall
- 39. N/A
- 40. Repair and redecorate existing staircase in front lightwell, and railings in paint to match existing.

General Notes


- A. New openings to be created in line with Structural Engineer's design and specification
- B. Allow for new connections to below ground drainage C. Heating and cooling
- Existing poor quality visible external condenser units associated with redundant air conditioning units to be carefully removed from rear elevation.
- Air conditioning to be installed to all bedrooms, with external condenser units positioned discretely in valley of roof, not visible from street level or front the rear of the property
- Air conditioning to be installed to LGF gym, with external condenser unit positioned discretely within external joinery item

beneath external stair. Existing radiators and heating systems to be retained. Master bedroom and bathrooms to be supplied with new wet underfloor heating system installed between existing floor joists. New rooms to basement to be fitted with new flat panel radiators connected to existing hot water heating system.

D. Fire Alarm Existing commercial Chubb fire alarm system including 'break glass' panels to be carefully removed and replaced with discrete domestic fire and smoke alarm system.

1

E. Replace non-original floor finishes throughout lower ground floor




4



PL-05

1 PL-04

2



4

Ground Floor Plan As Proposed Scale 1:50 @ A1 / 1:100 @ A3

2

3

3


0


5

6

5









7

6