Application No:	<b>Consultees Name:</b>	Consultees Addr:	Received:	<b>Comment:</b>	Response:
2017/1784/L	Andrew Farkas	Flat 2 34 Museum Street London WC1A	26/04/2017 16:31:34	OBJEMPER	The alterations started in May 2016 and concluded in February 2017. There is no way these could be described as 'minor'. The flat has been gutted and reconstructed.
					Seymour Three Ltd is a company of which Mr Alex Sargeson is/was a Director. Mr Sargeson is an architect. There is no way that an architect could not have known that planning consent and listed building consent was required. This project appears to have been undertaken with forethought and the intention of avoiding consent prospectively.
					An internal load bearing stud partition wall between the kitchen and the lounge has been removed (details and drawings supplied by Mrs Yeo in her comments). I am concerned that this has compromised the structure and integrity of the building. It is suggested that structural engineers have confirmed that no structural repairs have been undertaken. There is no supporting documentation to this effect.
					The new window in Bedroom 2 is out of keeping with the style of the house. The original sash window has been replaced by full length doors. It is unsympathetic with the design of the building and potentially unsafe.
					I have not been provided with any evidence of acoustic baffling in respect of the flooring. The noise level from movement in Flat 3 raises questions as to whether sound insulation compliant with building regulations has been used.
					In summary, the development is not minor. It is not consistent with the heritage of a Grade 2 listed building. No prospective independent supporting evidence has been provided to indicate the structural integrity of the building has not been compromised. I would request an INDEPENDENT structural survey and confirmation of the flooring insulation.

Printed on: 04/05/2017

09:10:03

Application No:	<b>Consultees Name:</b>	Consultees Addr:	Received:	Comment:	Response:
2017/1784/L	Andrew Farkas	Flat 34 Museum Street London	26/04/2017 16:16:59	COMMNT	The alterations started in May 2016 and concluded in February 2017. There is no way these could be described as 'minor'. The flat has been gutted and reconstructed.
		WC1A 1LH S10 3PQ			Seymour Three Ltd is a company of which Mr Alex Sargeson is/was a Director. Mr Sargeson is an architect. There is no way that an architect could not have known that planning consent and listed building consent was required. This project appears to have been undertaken with forethought and the intention of avoiding consent prospectively.
					An internal load bearing stud partition wall between the kitchen and the lounge has been removed (details and drawings supplied by Mrs Yeo in her comments). I am concerned that this has compromised the structure and integrity of the building. It is suggested that structural engineers have confirmed that no structural repairs have been undertaken. There is no supporting documentation to this effect.
					The new window in Bedroom 2 is out of keeping with the style of the house. The original sash window has been replaced by full length doors. It is unsympathetic with the design of the building and potentially unsafe.
					I have not been provided with any evidence of acoustic baffling in respect of the flooring. The noise level from movement in Flat 3 raises questions as to whether sound insulation compliant with building regulations has been used.
					In summary, the development is not minor. It is not consistent with the heritage of a Grade 2 listed building. No prospective independent supporting evidence has been provided to indicate the structural integrity of the building has not been compromised. I would request an INDEPENDENT structural survey and confirmation of the flooring insulation.

Printed on: 04/05/2017

09:10:03

Application No:	<b>Consultees Name:</b>	Consultees Addr:	Received:	Comment:	Response:
2017/1784/L	Andrew Farkas	Flat 2 34 Museum Street London WC1A	26/04/2017 16:31:18	OBJEMPER	The alterations started in May 2016 and concluded in February 2017. There is no way these could be described as 'minor'. The flat has been gutted and reconstructed.
					Seymour Three Ltd is a company of which Mr Alex Sargeson is/was a Director. Mr Sargeson is an architect. There is no way that an architect could not have known that planning consent and listed building consent was required. This project appears to have been undertaken with forethought and the intention of avoiding consent prospectively.
					An internal load bearing stud partition wall between the kitchen and the lounge has been removed (details and drawings supplied by Mrs Yeo in her comments). I am concerned that this has compromised the structure and integrity of the building. It is suggested that structural engineers have confirmed that no structural repairs have been undertaken. There is no supporting documentation to this effect.
					The new window in Bedroom 2 is out of keeping with the style of the house. The original sash window has been replaced by full length doors. It is unsympathetic with the design of the building and potentially unsafe.
					I have not been provided with any evidence of acoustic baffling in respect of the flooring. The noise level from movement in Flat 3 raises questions as to whether sound insulation compliant with building regulations has been used.
					In summary, the development is not minor. It is not consistent with the heritage of a Grade 2 listed building. No prospective independent supporting evidence has been provided to indicate the structural integrity of the building has not been compromised. I would request an INDEPENDENT structural survey and confirmation of the flooring insulation.

Printed on: 04/05/2017

09:10:03

						4/05/2017	09:10:03
Application No:	<b>Consultees Name:</b>	Consultees Addr:	Received:	<b>Comment:</b>	Response:		
2017/1784/L	Maggie Yeo	Flat 1, 34 Museum Street London WC1A 1LH	26/04/2017 20:09:07	COMMNT	im writing to confirm our objection to the retrospective listed and planning consent two mains areas of concern, firstly the fenestrations (marked C) and referred to ut the Heritage statement by Montagu Evans. Essentially, the original sash casemer has been replace with a pair of patio style french doors at the highest, third floor louiding. These new doors look out onto an area where all of the buildings of a sir retain their original look sash windows and are in keeping. Referring to documen application showing the pre-existing window and replacement doors, i would com these new, high level doors open out into the courtyard, this is not made clear froidetail, and ref. to a "glass balustrade" is shown to the outside of the external elev. This is misleading. It is clear from these drawings that this balustrade stops well be pre-existing windowsill height without a handrail or intermediate bars and leaves a gap at low level to access the door shoot bolts.  The new opening ntroduces a significant risk of falling from height and compromis privacy of neighbouring dwellings.  Strictly, reference to the condition of the pre-existing window and framework is no however all other windows and frames installed at the same time as the pre existic assement remain in good, serviceable condition, save for problems caused by the works when all windows to the rear elevation were "painted shut" the broken wind the 3rd floor level in the common stairwell was damaged after the existing owners occupation. No exposed hinges are shown on the drawing details, (photo to be separately) the installed doors have been fixed with (internal) brass hinges fitted knuckles and pins are visible externally. The photograph will also show the poor c installation, with unfinished render, poor painted timber and local downpipes wich over-painted in white masonry paint, at odds with all other downpipes and rainwal which are in black. All of these works were carried out via ladder access with sca for Health & Safety, workmanship or preservation of orig	ander 1.6 in ent window level of the imilar age int 9 of the inment that om the plan vation detail. below the a sizeable ises the ot relevant, ting-window ese recent dow pane at s had taken ent I so that the quality of in have been ater goods ant regard dow", the e original two es to those of mullion. In the ion. In ign, ign, ign, ign, ign, ign, ign, ign	d
					f 00.14 00 t 140.0 t D 110t t 1 t 1 t 1 t 1		

Page 47 of 77

from 33 Museum Street and 48 Great Russell Street in order to help preserve the historical significance of this building, despite previous internal updating. In 1993 it was considered the buildings importance warranted this much attention to original design details as quoted by

Printed on: 04/05/2017 09:10:03

Application No: Consultees Name: Consultees Addr: Received: Comment: Response:

Montagu Evans "the architect William Finch Hill"

My second concern is the removal of the internal wall between the kitchen and the lounge, numbered point 5 in the Montagu Evans Planning Heritage Design and Access Statement. A previous planning application to remove this partition and create an open plan space identical to that which has now been created was submitted to London Borugh of Camden in 1990. Planning permisson was denied.

This is a LOAD BEARING stud partition wall that was incorporated in its current form in the subsequent planning application approved in October 1993. We have provided you with a copy of the drawing ref:-9327/01 prepared by David Salter Consulting Engineers which clearly demonstrates this. I am very concerned that the structural integrity of this Grade 2 listed Heritage Asset may have been compromised by the removal of this partition; no supporting documents or structural calculations have been provided to demonstrate that the roof remains adequately supported or to ensure the facade, facing Great Russell Street, is not at risk of localised failure.

Finally, regarding the raised floor that was removed and we are advised that a new laminate floor with acoustic baffle has been fitted, we do not have a proper independent report detailing this and its suitability.

Clearly, time and effort has been invested in producing these Retrospective Applications, however the Montagu Evans Planning Heritage Design and Access Statement and many of the documents referred to therein do not support their contention that the alterations which have been made to the fenestration are in keeping or that they are minor.

The same is true in respect of the internal changes, in particular the structural partition which has been removed. The Application includes historical plans showing an open-plan layout(ref.Montagu EvansPlanning & Heritage Statement & Design & Access Statement Fig. 4,5,& 6 respectively) which formed part of the aforementioned 1990 Planning Application. Each of these drawings has been annotated by Montagu Evans, referring to the as "1990 Plan". This is misleading, as the last of these chronologically (fig. 6) is clearly stamped PLANS NOT APPROVED ON BEHALF OF THE COUNCIL 17 JULY 1990, and the third floor has never previously existed in the current open-plan layout. There is insufficient evidence to confirm that the alterations conform with current Building Regulations or that they are safe. I am also concerned that the owners and their contractors have failed to comply with the requirements of The Construction (Design & Management) Regulations 2015.

The current owners purchased Flat 3, 34 Museum Street, in February 2016, commencing their extensive renovaton programme shortly afterwards. Upon completion of the work almost exactly one year later, the property was re-marketed for sale at a significantly higher purchase price and it is now clear that the property was purchased solely as an investment opportunity. Generally speaking, while other residents may suffer disruption during such works (we certainly have), usually all parties benefit in the longer term from maintenance and improvements if they have been carried out correctly, with appropriate consent. As this clearly has not happened i am very concerned about the potential future consequences if the flat is to be sold without addressing these important issues and effecting appropriate rectification.