

Mandie Gold  
Goldschmidt & Howland  
1197 Finchley Road  
London  
NW11 0AA

Re 36 Ainger Road

Having searched through my store of drawings I confirm that the drawing of 36 Ainger Road contains an error. The error is fundamental to the layout of the building. It is that room 5 does not exist. It would appear that the floor below has been duplicated. I have now amended my drawings to show that room 5 does not exist and that the second floor is one flat.

I thank you for your patience in this matter and hope that you can now move forward.

Yours



John Pullen EHO