

Red Lion Street  
Window Schedule  
7th March 2017

Also refer to photo schedule in planning statement appendix

Date	Rev	Description
26.06.17	P4	Planning revisions

Window	House	Floor	Existing	Proposed	Finish	Glazing bars	Trickle vents	Ironmongery	Drawing ref
W45/10		45 First	UPVC sash	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_61
W45/11		45 First	UPVC sash	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_61
W45/12		45 First	UPVC sash	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_61
W45/13		45 First	Solid timber door (rotten)	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_61
W45/20		45 Second	UPVC sash	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_62
W45/21		45 Second	UPVC sash	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_62
W45/22		45 Second	UPVC sash	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_62
W45/23		45 Second	Timber sash, original	Repair and repaint only	Signal white				030_P_63
W45/30		45 Third	UPVC casement	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_62
W45/31		45 Third	N/A	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_62
W45/32		45 Third	UPVC casement	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_62
W45/33		45 Third	N/A	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_62
W46/01		46 Ground	Solid-core fire door	Replace with glazed hardwood doors as per drawing	Signal white				
W46/10		46 First	Modern timber sash, poor condition	Retain, repair and redecorate existing timber window frames. Install new timber sash with 14mm heritage slimline double glazing with integral 18mm lambs-tongue glazing bars	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_60
W46/11		46 First	Modern timber sash, poor condition	Retain, repair and redecorate existing timber window frames. Install new timber sash with 14mm heritage slimline double glazing with integral 18mm lambs-tongue glazing bars	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_60
W46/12		46 First	Modern timber sash, poor condition	Retain, repair and redecorate existing timber window frames. Install new timber sash with 14mm heritage slimline double glazing with integral 18mm lambs-tongue glazing bars	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_60
W46/13		46 First	Modern timber sash, poor condition	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_61

W46/14	46	First	Modern timber sash, poor condition	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_61
W46/20	46	Second	Modern timber sash, poor condition	Retain, repair and redecorate existing timber window frames. Install new timber sash with 14mm heritage slimline double glazing with integral 18mm lambs-tongue glazing bars	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_60
W46/21	46	Second	Modern timber sash, poor condition	Retain, repair and redecorate existing timber window frames. Install new timber sash with 14mm heritage slimline double glazing with integral 18mm lambs-tongue glazing bars	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_60
W46/22	46	Second	Modern timber sash, poor condition	Retain, repair and redecorate existing timber window frames. Install new timber sash with 14mm heritage slimline double glazing with integral 18mm lambs-tongue glazing bars	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_60
W46/23	46	Second	Modern timber sash, poor condition	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_61
W46/24	46	Second	Modern timber sash, poor condition	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_61
W46/30	46	Third	UPVC casement	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_60
W46/31	46	Third	UPVC casement	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_60
W46/32	46	Third	Modern timber sash, poor condition	4mm Single-glazed box-sash window (e.g. Mumford and Wood Heritage Historic)	Signal white	18mm Lambs tongue, refer to drawings	NO	Brass sash pulley, lifts and hook catch	030_P_61
W46/33	46	Third	Modern timber sash, poor condition	Remove					
W46/34	46	Third	n/a: new window	Conservation rooflights (CR-3 by The Rooflight Company or similar)					030_P_51
W46/35	46	Third	n/a: new window	Conservation rooflights (CR-3 by The Rooflight Company or similar)					030_P_51