



Date 17.0	1.17	Drawn	RP	Checked	IJ	Scale	1:50		BISSET
Project No.	Originator	Zone	Level	Туре	Role	Number	Suitability	Revision	
BB029	BA	00	00	DR	A	1201	S0	P1	ADAMS




Information Title Propos	sed -	Grou	und	Floor	· Pl	an			
Date 17.01	1.17	Drawn	RP	Checked	IJ	Scale	1:50		BISSET
Project No.	Originator	Zone	Level	Туре	Role	Number	Suitability	Revision	
BB029	BA	00	00	DR	A	1202	S0	P1	ADAMS
The Cube T +44 (0)20	Building, 1 0 7250 044	7 -21 V 40 E	Venlock info@t	k Road, L bissetada	ondo ms.co	n N1 7GT, Un om www.bis	nited King ssetadam	dom s.com	



ninium double glazed dow. Iron grey RAL 7011 der coated finish.	curre plan	h denotes ent floor
	1.500	
		key Hatch denotes proposed new partition for Nr.32 Hatch denotes proposed historical areas to be repair / make good / refurbish
		All the original lath and plaster ceilings, cornices, decorative plasterwork and ceiling roses that may survive to be retained and made good. Conservation paint solvent would be used to peel away historic paint build up to re-expose cornice detailing.
	TIOI	Careful raising of the floorboards, documenting the location and type of fixing of each when removed. Ends not to be broken or cut. To be refixed in place using reclaimed or original iron nails, not screws or stainless steel nails. Note if boards are board end nailed when lifted.
		Historic doors in good condition to be refurbished to original state. Removal of MDF later panels to 4-panelled historic doors. Historical door timber frames to be repaired with spliced in timber, repairs where needed and repainted. New ironmongery to match original.
	3106	Historic external sash windows and original timber shutter boxes and timber architrave surrounding to be refurbished: clean and paint to match original. New ironmongery to match original. Broken glass panes to be replaced. Care to be taken not to damage existing windows.
	3105	Historic skirting to be refurbished. Clean and paint to match original Wienerberger Smeed Dean
	 	traditional London yellow brick. Stretcher bond. Flush mortar. Lintel above window, where cracks have been
		observed repair work of masonry or replacement of lintel may be necessary. New lintels to match historic using lime mortar
		Balcony balustrade to be refurbished. Clean and painted to match existing Historic external sash windows and original timber shutter boxes and timber architrave surrounding to be refurbished: clean and paint to match original. New ironmongery to match original. Broken glass panes to be replaced. Care to be taken not to damage existing windows. New heat reflective roller blinds internally
	3104	Existing down pipe to be retained
ternal sash windows to be d: clean and paint to match or hongery to match original. Bro		
es to be replaced. Care to be t hage existing windows.		2 3 5m
Information Title Proposed - First	t Floor Plai	n


Date 17.01	1.17	Drawn	RP	Checked	IJ	Scale	1:50		R	S	SE'
Project No.	Originator	Zone	Level	Туре	Role	Number	Suitability				
BB029	BA	00	00	DR	Α	1203	S0	P1		D/A	
						n N1 7GT, Un					

T +44 (0)20 7250 0440 | E info@bissetadams.com | www.bissetadams.com




-		

Date 17.01	1.17	Drawn	RP	Checked	IJ	Scale	1:50		BISSE
Project No.	Originator	Zone	Level	Туре	Role	Number	Suitability		
BB029	BA	00	00	DR	A	1204	S0	P1	ADAM
						n N1 7GT, Ur			



		h denotes
	curre plan	ent floor
	Sect 1.500	ion Key
	\bigcirc	
		key Hatch denotes proposed new partition for
		Nr.32 Hatch denotes proposed historical areas to
		be repair / make good / refurbish
		All the original lath and plaster ceilings, cornices, decorative plasterwork and ceiling roses that may survive to be retained and made good. Conservation paint solvent would be used to peel away historic paint build up to re-expose cornice detailing.
		Careful raising of the floorboards, documenting the location and type of fixing of each when removed.
		Ends not to be broken or cut. To be refixed in place using reclaimed or original iron nails, not screws or stainless steel nails. Note if boards are board end nailed when lifted.
		Historic doors in good condition to be refurbished to original state. Removal of MDF later panels to 4-panelled historic doors. Historical door timber frames to be repaired with spliced in timber, repairs where needed and repainted. New ironmongery to match original.
	3106	Historic external sash windows to be refurbished: clean and paint to match original. New ironmongery to match original. Broken glass panes to be replaced. Care to be taken not to damage existing windows.
		Historic skirting to be refurbish. Clean and paint to match original
_	3105	 Aluminium double glazed window. Iron grey RAL 7011 powder coated finish.
	···-	 Wienerberger Smeed Dean traditional London yellow brick. Stretcher bond. Flush
	··—·—·	mortar.
		Wienerberger Smeed Deer traditional
		 Wienerberger Smeed Dean traditional London yellow brick. Stretcher bond. Flush mortar.
	··	
	·	
with ornate ean and paint gery to match		
be replaced. e existing		
;	0 _{0.5} 1	2 3 5m
Information Title Proposed - Th	nird Floor Pla	an

17.01.17RPIJ1:50BISSject No.OriginatorZoneLevelTypeRoleNumberSuitabilityRevisionB029BA0000DRA1205S0P1
B029 BA 00 00 DR A 1205 S0 P1 A DA



Suitability	u.					N
litat	vision				Λ	N
Su	Re	Date	Comments			© copyright BISSET ADAMS a
S	P1.0	[DD/MM/YY	[e.g. Issue for review to Lead Designer]			© copyright BISSET ADAMS a
						Т
				1		C
				1		d
						re
						p
				1		C
	1	1		-	L	

curre plan	tion Key
	key
	Hatch denotes proposed new partition for Nr.32
	Hatch denotes proposed historical areas to be repair / make good / refurbish
	All the original lath and plaster ceilings, cornices, decorative plasterwork and ceiling roses that may survive to be retained and made good. Conservation paint solvent would be used to peel away historic paint build up to re-expose cornice detailing.
Standing Seam metal roofing. Color RAL 7011	Careful raising of the floorboards, documenting the location and type of fixing of each when removed. Ends not to be broken or cut. To be refixed in place using reclaimed or original iron nails, not screws or stainless steel nails. Note if boards are board end nailed when lifted.
A 3101	Historic doors in good condition to be refurbished to original state. Removal of MDF later panels to
Acoustic louvres powdercoated RAL 7011 to Allow for adequate ventilation while maintaining low noise levels from plant	4-panelled historic doors. Historical door timber frames to be repaired with spliced in timber, repairs where needed and repainted. New ironmongery to match original.
Belux type of window, with extend with	Historic external sash windows to be refurbished: clean and paint to match original. New ironmongery to match original. Broken glass panes to be replaced. Care to be taken not to damage existing windows.
vertical elements. Frame to be powdercoated RAL 7011 New heat reflective roller blinds internally	Historic skirting to be refurbish. Clean and paint to match original
Metal balustrade colour RAL 7011 Iron grey RAL 7011 powder coated metal co Matt finish.	oping.
Existing coping to be made good where necessary. Broken roof tiles to be replaced by reclaimed tiles to match existing.	
3104	
0 _{0.5} 1	2 3 5m
Date 17.01.17 Drawn PD Checked	
Project No. Originator Zone Level Type R	IJ1:50RoleNumberSuitabilityRevisionA1206S0P1

The Cube Building, 17 -21 Wenlock Road, London N1 7GT, United Kingdom T +44 (0)20 7250 0440 | E info@bissetadams.com | www.bissetadams.com

Iron grey RAL 7011 powder coated metal coping	
Matt finish.	
Iron grey RAL 7011 powder coated steel frame	
Crittall fixed steel window. Iron grey RAL 7011 powder coated steel finish. Window recessed 200mm from brick facade.	
200mm from brick facade.	
Glazed brick double course feature band with	
Iron arev RAL 7011 powder coated steel frame.	
Iron grey RAL 7011 powder coated steel frame. ————————————————————————————————————	
Crittall fixed steel window. Iron grey RAL 7011	
200mm from brick facade.	
Wienerberger Smeed Dean traditional London yellow brick. ————— Stretcher bond. Flush mortar.	
Iron grey RAL 7011 powder coated steel frame	
Crittall fixed steel window. Iron grey RAL 7011	
Crittall fixed steel window. Iron grey RAL 7011 powder coated steel finish. Window recessed 200mm from brick facade.	
Iron grey RAL 7011 powder coated cantilevered	
steel angles.	
Petrarch reconstituted stone cladding panel. Mid grey	
colour, matt finish.	
Doors to access ramp to match cladding.	
Metal facade system. Proteus HR Zinc ElZinc ————————————————————————————————————	
Rainbow Red finish.	
Proposed Ground Floor Plan	Warburg Institute
1.50	

				-		
lity	UO					
Suitability	Revision				Λ	
Su	Re	Date	Comments		AI	
SC	P1.0	21/07/17	Issue for planning		/ \	© copyrigh
L	I	1		L		1

Notes



This drawing is the property of Bisset Adams Ltd.

Copyright is reserved by Bisset Adams Ltd. and the drawing is issued on condition that it is not copied, reproduced, retained or disclosed to any unauthorised person, either wholly or in part, without written consent.

32Torrington Square Bloomsbury London WC1E7HX Birbeck University of London




The Cube Building, 17 -21 Wenlock Road, London N1 7GT, United Kingdom T +44 (0)20 7250 0440 | E info@bissetadams.com | www.bissetadams.com

Type Role Number

Originator Zone Level

BB029 BA 00 00 DR A 2101

Project No.




The Cube Building, 17 -21 Wenlock Road, London N1 7GT, United Kingdom T +44 (0)20 7250 0440 | E info@bissetadams.com | www.bissetadams.com


Site Plan 1.500			
The Sci	Shade hool of ne Art	Refer to Wilder Associates landscape design for planting details Acoustic louvres powdercoated RAL 7011 to Allow for adequate ventilation while maintaining low noise levels from plant Metal balustrade colour RAL 7011 Aluminium gutter RAL 7011 Standing Seam metal roofing. Color RAL 7011 Belux type of window, with extend with vertical elements. Frame to be powdercoated RAL 7011	V
	Wienerberger Smeed	d Dean traditional London yellow brick.	
		azed window. Iron grey RAL 7011 powder	
Second Floor Level 33.710	coated finish.		
	Wienerberger Smeed Stretcher bond. Flush	d Dean traditional London yellow brick. ———	
First Floor Level 30.670	Aluminium double gla coated finish.	azed window. Iron grey RAL 7011 powder	
	Aluminum soffit RAL	7011	
Ground Floor Level 26.400	lron grey RAL 7011 p Matt finish.	oowder coated metal coping.	
	Wienerberger Smeed	Existing Wall Top Level 27.07	
	brick. Stretcher bond	. Flush mortar.	
	Broxap Galvanized s cycle shelter	teel sheffield	
Basement Floor Level 23.020	6no. Galvanized stee cycle stands root bas 950x750 Metal facade system ElZinc Rainbow Red	e fixing . Proteus HR Zinc finish.	FFL + 23.215
Proposed Section AA 1.50 0 0.5	5 1 2	FFL + 22.890 3 5m	Notes No d

ita	, Si		
Suita	Revis	Date	Comments
S0	P1.0	[DD/MM/YY]	[e.g. Issue for review to Lead Designer]

A1	© copyright BISSET ADAMS	No d contr all di This
		Copy draw repro pers cons



Information Title Propos	sed -	Sec	tion	AA					
Date 17.01	.17	Drawn	RP	Checked	IJ	Scale	1:50		BISSET
Project No.	Originator	Zone	Level	Туре	Role	Number	Suitability	Revision	
BB029	BA	00	00	DR	Α	3101	S0	P1	ADAMS
The Cube I T +44 (0)20	Building, 1) 7250 04	7 -21 V 40 E	Venlocl info@t	k Road, L bissetada	ondo ms.co	n N1 7GT, Un om www.bis	iited King ssetadam	dom s.com	



Acoustic louvres powdercoated RAL 7011 — to Allow for adequate ventilation while maintaining low noise levels from plant


Obscured blockwork wall between Annex and Warburg Instute.

Aluminum soffit RAL 7011

Wienerberger Smeed Dean traditional London yellow brick. Stretcher bond. Flush mortar.

New low traffic area and footpath ramp to engineers details. Asphaltic concrete finished.


Proposed Section BB 0 0.5 1 2 3 5m Warburg Institute A1 Comments ທີ່ 🕰 Date S0 P1.0 [DD/MM/YY] [e.g. Issue for review to Lead Designer] consent.



Propos	sed -	Sect	tion	BB					
Date 17.01	1.17	Drawn	RP	Checked	IJ	Scale	1:50		BISSE
Project No.	Originator	Zone	Level	Туре	Role	Number	Suitability	Revision	
BB029	BA	00	00	DR	A	3102	S0	P1	ADAM
The Cube T +44 (0)20		7 -21 V 40 E	Venlock info@t	k Road, L bissetada	.ondo ms.co	n N1 7GT, Ur m www.bis	hited King ssetadam	dom Is.com	

Site Plan 1.500	
The Shade School Prine A Institute Control of the School Control o	of
	Historic external sash windows and original timber shutter boxes and timber architrave surrounding to be refurbished: clean and paint to match original. New ironmongery to match original. Broken glass panes to be replaced. Care to be taken not to damage existing windows. New heat reflective roller blinds internally Non-historical single ply membrane to be replaced by new single ply membrane system
	Non-historical copping to be made good where necessary. Broken roof tiles to be replaced by reclaimed tiles to match existing. Cast iron exhaust grill to WC's Repoint, repair, and reuse moisture brickwork where possible, use of lime mortar for pointing. Where brickwork is broken suitable reclaimed replacement
	bricks will be used matching the colour, age and size as the existing. Cast iron exhaust grill to WC's
	Refer to Wilder Associates landscape design for
	Broxap Galvanized steel sheffield cycle shelter 6no. Galvanized steel Sheffield cycle stands root base fixing 950x750
And the second secon	Copyright BISSET ADAMS

YY]	[e.g. Issue for review to Lead Designer]



Copyright is reserved by Bisset Adams Ltd. and the drawing is issued on condition that it is not copied, reproduced, retained or disclosed to any unauthorised person, either wholly or in part, without written

32 Torrington Square Bloomsbury London WC1E7HX

Birbeck University of London

(2)	(1	
35	1010	1630	NOTE Refer to Floor Finishes Plan Reflected Ceiling Plans for finishes
		•	Insulation to underside of soffit
Office			O4 - Eaves 40500 ——————————————————————————————————
FFL + 37.410			03 - 3F 37400
ffice			Historic external sash windows and original timber shutter boxes and timber architrave surrounding to be refurbished: clean and paint to match original. New ironmongery to match original. Broken glass panes to be replaced. Care to be taken not to damage existing windows. New heat reflective roller blinds internally
FFL + 34.340			02 - 2F 34320
ar room			Acoustic insulation in between existing floor boards . Refer to Structure Engineers report for floor make up.
FFL + 30.590		<u> </u>	01 - 1F 30530
			Historic door to be refurbished to original state. Historical door timber frame to be repair with spliced in timber, repairs where needed and repainted blue to match original. New ironmongery to match brass early-mid 19th century original. Torrington Sq
.880			00 - Existing GF 26880
x1. Single wall unt	294		00 - Annex GF New suspended cieling 26000
vt Drahev ut unt (g0orm). t Drahev (g0orm). t Drahev (g0orm). t Drahev (g0orm). t Drahev (g0orm).	00 EEL + 23.95	Storage	0A - Existing 23940
	FFL+23.95	FFL + 23.910	Basement
			00 - Annex 21.730 Basement

Information Title Propos	sed -	Sec	tion	CC				
Date 17.01	1.17	Drawn	RP	Checked	IJ	Scale	1:50	
Project No.	Originator	Zone	Level	Туре	Role	Number	Suitability	Revision
BB029	BA	00	00	DR	Α	3103	S0	P1
The Cube T +44 (0)20	Building, 1 0 7250 04	7 -21 V 40 E	Venlocl info@t	k Road, L bissetada	ondo ms.co	n N1 7GT, Ur om www.bi	ited King ssetadam	dom Is.com