



- The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before


- Where an item is covered by drawings to different scales the larger scale

- Do not scale drawing. Figured dimensions to be worked to in all cases.

proceeding with the works.


drawing is to be worked to.

CDM Regulations 2007



AA1692-2-1-1	1010	A
drawn RFB	checked CC	
scale @ A0 1:500	date 3 OCT 2	2012





EXISTING SITE SECTION A-A