

notes


The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before proceeding with the works.

- Do not scale drawing. Figured dimensions to be worked to in all cases.

 Where an item is covered by drawings to different scales the larger scale drawing is to be worked to.

CDM Regulations 2007

ALL current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environmental Assessment Record.



PRP Architects © 10 Lindsey Street

T +44 (0)20 7653 1200 F +44 (0)20 7653 1201 lon.prp@prparchitects.co.uk

London EC1A 9HP

