



Nick further to our conversation and my letter of objection I am attaching a few photos of the tree in question. You can see the charging lead for the Smart car draped over the wall. The wall and pillar have been in exactly this condition for many years and the state is nothing to do with the tree. You can see the huge lime at No 19 which is hard up against the boundary wall and brick pillars which are in good condition. The wall and pillars at No 13 just need to be repaired. Currently those at No 23 were in a similar state and about the same age and there is no tree in sight.

Best wishes
Jenny Stevens



