

New structure required for loft floor - make allowance for new ceiling linings/making good/retention of ceiling features to second floor ceiling

Existing cupboards stripped out, new timber stair to loft installed with cupboard underneath for washing machine - FD20 fire rated doors and partition construction



Additional works required to this floor consist of:

- Re-wire of all small power
- New downlighters to Bedroom 2
- Additional hall light switch
- 2M high x 3.5 M long high mirror fixed to wall
- Refurbishment of doors to FD20s and new lock cases (2 no doors)
- New sprinkler/mist protection system as required by Building Control

REV B / 28 11 17 / Planning Issue

Do not scale  
 All new structure shown indicatively and subject to SE input  
 This is not a construction drawing.

**Lucy Read Architects**  
 13 Retcar Place N19 5TT lucyread@icloud.com 07779 789 268



7B Ospringe Road, NW5 2JD  
**Proposed Second Floor Plan**  
 1:50 at A3  
 July 24, 2017

**05\_2012 Rev B**