= Existing window openings where internal secondary glazing will be installed. The scope of secondary glazing work is limited to these openings only



Revisions:



High Speed (HS2) Limited 25<sup>th</sup> Floor One Canada Square Canary Wharf London E14 5AB



Costain Skanska Joint Venture The Podium 2<sup>nd</sup> Floor 1 Eversholt Street, Euston London NW1 2DN

## Historic Building Consultants: Ingram Consultancy Limited Holly Cottage Lower Street

Upton Noble Somerset BA4 6BB

T. 01749 850 900

E. enquiries@ingram-consultancy.co.uk www.ingram-consultancy.co.uk

Site Address: 46 Mornington Terrace, London

Drawn by: GA

Drawing No: 2016-005-46MT-EX-EL-01

Drawing Title: External Elevations with Location of Internal Secondary Glazing

<sup>by:</sup> GA

Checked By: GR

<sub>Scale:</sub> NTS @ A3:



Revision: 00