



= Existing window openings where internal secondary glazing will be installed.  
The scope of secondary glazing work is limited to these openings only

Revisions:	<div><p><b>High Speed (HS2) Limited</b> 25<sup>th</sup> Floor One Canada Square Canary Wharf London E14 5AB</p></div>	<div><p><b>Costain Skanska Joint Venture</b> The Podium 2<sup>nd</sup> Floor 1 Eversholt Street, Euston London NW1 2DN</p></div>	<div><p>Historic Building Consultants:</p><p><b>Ingram Consultancy Limited</b> Holly Cottage Lower Street Upton Noble Somerset BA4 6BB</p><p>T. 01749 850 900</p><p>E. <a href="mailto:enquiries@ingram-consultancy.co.uk">enquiries@ingram-consultancy.co.uk</a> <a href="http://www.ingram-consultancy.co.uk">www.ingram-consultancy.co.uk</a></p></div>	<div><p>Site Address: The Crown &amp; Anchor, 137 Drummond Street, London</p><p>Drawing Title: External Elevations with Location of Internal Secondary Glazing</p><div><div>Drawn by: GA</div><div>by: GA</div><div>Checked By: GR</div></div><p>Drawing No: <b>2016-005-137DS-EX-EL-01</b></p></div> <div><div>Scale: NTS @ A3:</div><div>Revision: <b>00</b></div></div>
------------	---	---	--	--