					17/07/2018	09:10:03
Application No: 2018/2442/P	Consultees Name: Sarah Tyacke for Nicholas Tyacke	Received: 16/07/2018 15:10:40	Comment: COMMEMA IL	Response: Camden Planning Application: 2018/2442/P Address: 1 Spencer Rise, London NW5 1AR Proposal: Excavation of Single Story Basement The first point to make about this planning application is that nos. 1a, 1b and 1c Spencer Rise are nineteenth-century historic in-fills, between no. 6 York Rise and no. 1 Spencer Rise. In the 1970s 6 Yowas demolished, having been allowed to fall into decay. Following this, for some five years the site rer vacant. Despite 1a Spencer Rise being propped up by raking shores, significant movement of the part occurred during the interim. The present building at 6 York Rise comprises two flats and a maisonette brick-faced, it is essentially a ferro-concrete construction. In the late 1980s cracks appeared in the part between 1a and 1b Spencer Rise. Clay shrinkage was diagnosed as part of the problem, although the of unnatural rigidity introduced by the new building at 6 York Rise cannot be ruled out. In the event, it decided not to underpin the party wall between 1a and 1b Spencer Rise, but simply to make good the less severe cracking has continued to occur, particularly where the main buildings adjoin the rear exte Spencer Rise, as the name implies, is built on a hill slope at the bottom of which stand nos. 1, 1c, 1b a (in that order). Given the relatively recent history of movement and cracking, the proposed developme Spencer Rise is very worrying. Not only will the construction of a presumably concrete basement intro further unnatural rigidity but yet more drying out of the underlying clay is bound to occur. Cracking and movement of the adjacent houses will be the likely result. There are also serious issues concerning se and drainage more generally, as well as the mains water supplies. Existing ground plans are likely to I inaccurate. Sewers and drains run under the terrace houses concerned, from back to front and some appear to be interconnected. Furthermore in the case of 1a Spencer Rise the mains water supply runs the house from front to back, and this may not be untypical.	fork Rise emained rty wall e; albeit arty wall e effects was e damage; ensions. and 1a ent at 1 oduce d ewerage be highly would as under delicate rsely	09.10:03