

Application No:	Consultees Name:	Received:	Comment:	Response:
2018/3131/P	Jo Hurford	30/07/2018 13:42:41	OBJ	<p>There is insufficient space for these stands on Drummond Street. It seems very large in the diagram which means it is taking away extra open space from an area already badly affected by losing space due to the HS2 works. I am concerned the stands appear to directly abut the neighbouring building, instead of there being a gap between them and the neighbouring building this could be a trip hazard for people entering the flats beside the spice shop.</p>
