

# BUILDING SERVICES MECHANICAL & ELECTRICAL CONSULTANCY

Planning Condition 17 – Report with photographic evidence

On

**Centrepoint Restaurant** 

For Keytask Management

**July 2018** 

## INDEX

Introduction	Page 3
Report	Page 5
Conclusion	Page 6
Appendices Drawing L1975M003 Drawing L1975M004	Page 7 Page 8

#### INTRODUCTION

Report as requested by:

Helena Tsiantes Jansson Keytask Management Ltd The Garden Room 6 Quarry Street Guildford Surrey GU1 3UR

The following report concerns the Centrepoint Restaurant; Condition 17, Plant Noise Attenuation. Photographic evidence has been included.

Our report is based on the following:

- The requirement of condition 17 of Planning Permission reference 2017/0994/P
- The document "Centre Point Restaurant Plant Noise Assessment Report 16/0163/R1" as issued by Cole Jarman, dated 7 March 2018 and approved under application ref 2017/6957/P.
- Drawings also approved under application reference 2017/6957/P: L1975M003 L1975M004

#### **REPORT**

The following mitigation measures have been installed by the contractors:

#### 1. Ductwork Silencers

As per paragraph 4.2.1. of the above mentioned document, "Atmospheric side silencers are required on all air handling units and the extract fans in order to meet plant noise limits"

All Air handling units and extract fans are provided with atmospheric side attenuation as required. Refer to pictures below:

Photo.1.1. Atmospheric side attenuator installed on AHU 1 See Drawing L1975M003



Photo.1.2 Atmospheric side attenuator installed on AHU 2 See Drawing L1975M003



Photo.1.3. Atmospheric side attenuator installed on AHU 3 See Drawing L1975M003



Photo.1.4. Atmospheric side attenuator installed on AHU 4 See Drawing L1975M004



Photo.1.5. Atmospheric side attenuator installed on Extract fan - See Drawing L1975M004



#### 2. Existing louvres

As per paragraph 4.2.3. of the above maintained document

"The landlord louvres must be also covered up, with openings only where air handling unit plant equipment is ducted directly to the louvre"

All existing landlord louvres have been covered with metal sheet and insulation board as required.

Photo.2.1. Existing louvers covered. Opening left for ductwork connection




Photo.2.2. Existing louvers covered. Opening left for ductwork connection




### CONCLUSIONS

We can confirm that the mitigation measures identified as required within the approved 'Plant Noise Assessment' dated 7 March 2018, have been installed as per the requirements of Condition 17 of Planning Permission, reference 2017/0994/P.







**Contact us** 

Reach us at: LONDON BELFAST

Phone: +44 (0) 1372 253207 +44 (0) 2828 277123

Address: Global House Unit 10

Ashley Avenue 10 Redlands Cres

Epsom Larne
Surrey Co Antrim
KT18 5AD BT40 1FF

Email: janice@lehding.co.uk

# WWW.LEHDING.CO.UK