


DOTTED LINE OF EXISTING SINGLE BRICK WALL BELOW, SUPPORTING LOWER PART OF STAIR. THE WALL RETURNS AROUND THE BIN STORE TO FORM AN ENCLOSED SPACE UNDER THE STAIR WHICH IS SEVERELY DAMP

EXISTING BRICK PARTY WALL SUFFERS FROM DAMP DUE TO MOISTURE INGRESS AT CRACKED COPING STONE



notes

- PLEASE NOTE ALL VERY FEW OF THE ORIGINAL YORK STONE TREADS AND RISERS REMAIN. MOST HAVE BEEN REPLACED BY CONCRETE TREADS AND RISERS AT SOME TIME IN THE PAST. THOSE THAT DO REMAIN HAVE SEVERELY DETERIORATED, THE STONE IS DELAMINATING AND HAS LOST BETWEEN 1/3 AND 1/2 OF ITS ORIGINAL THICKNESS. ALSO IN THESE ORIGINAL STONE TREADS, WHERE THE BALUSTRADE IS LEADED IN, CORNERS HAVE BEEN REPLACED BY CONCRETE.

HYLE LLP
48B GRAFTON ROAD, LONDON NW5 3DY

project name and address
LIGHTWELL STAIR RENOVATION
17 Regents Park Terrace, NW1 7ED

date	rev	description	dwn

drawing title
**STREET LEVEL
LIGHTWELL AND VAULT AREA
PLAN AS EXISTING**

scale	size	drawn	passed	date
1:25	A2	MGB	-	27/07/2018

drawing number	rev
RPT(L)11	-

1
RPT(L)11
STREET LEVEL PLAN OF LIGHTWELL AND VAULT AREA - AS EXISTING