

MAIN LANDING F01 MISSING BALUSTERS TO BE REPLACED TO MATCH EXISTING. FIRST FLOOR LOWER LEVEL - 19 - MISSING BALUSTERS TO BE REPLACED TO MATCH EXISTING. Painted softwood panel moulding LANDING - 10 10 - LANDING Painted softwood MISSING PORTION OF HANDRAIL **ENTRANCE HALL G01** EXISTING STAIRS, BULUSTERS, BALUSTRADE AND POSTS TO BE STRIPPED / SANDED RESTORED AND RE-PAINTED TO MATCH ORIGINAL CONDITION. MISSING BALUSTERS AND PORTIONS OF HANDRAIL TO BE REPLACED TO MATCH EXISTING. REPLACEMENTS TO BE KEPT TO A MINIMUM. CHECK ALL EXISTING DIMENTIONSOF STAIRS & BALUSTRADING ON SITE PRIOR TO CARYING OUT ANY WORKS. 1 - COMODE STEP EXISTING RISERS TO BE MEASURED ON SITE. TREAD FLOOR FINISHED TO BE PACKED TO FFL 136.140 0 - GROUND FLOOR PROVIDE EQUAL RISERS WITHIN EACH FLIGHT.

EXISTING GROUND TO FIRST FLOOR STAIRCASE & BALLUSTRADING RESTORATION PLAN

EXISTING GROUND TO FIRST FLOOR STAIRCASE & BALLUSTRADING RESTORATION ELEVATION 1/3

TENDER © CLIVE CHAPMAN ARCHITECTS. SURVEY INFORMATION IS USED UNDER SEPARATE COPYRIGHT LICENCE. REFER TO EXISTING SURVEY DRAWINGS / TITLE BLOCK FOR SURVEYORS DETAILS. CLIVE CHAPMAN FOR TYPICAL DETAILS SEE DRAWING HH-800 & HH-801 HEATH HOUSE, HAMPSTEAD, NW3 7ET FOR ELEVATIONS SEE DRAING HH-814 Amendments form preliminary drawings to include updates to mouldings profiles as per Conservation Officer meeting 20.06.2018 EXISTING GROUND-FIRST FLOOR STAIRCASE REFURB PLAN & ELEVATION TWICKENHAM MIDDX FOR INTERNAL ELEVATIONS REFER TO HH-337, 371 AND ROOM FINISHES SCHEDULE HH-1004 TELEPHONE 020 8891 4837 HH-813 T2 1:10 @ A1 29.01.2018 EMAIL INFO@CCAR.CO.UK WEBSITE WWW.CCAR.CO.UK