

<b>Application No:</b>	<b>Consultees Name:</b>	<b>Received:</b>	<b>Comment:</b>	<b>Response:</b>
2018/5308/L	Philip Kemp	16/11/2018 22:51:20	OBJEMPER	Like most of the houses in Jeffreys Street this is a Grade II listed building, with timber sash windows front and back. Any windows that are replaced - even at the back of the building - should still be of wood.
2018/5308/L	Stevens	13/11/2018 23:14:36	OBJ	The need to replace single glazed widows is clear. Why has the applicant chosen to replace only the front elevation windows in timber. To conserve the character of this grade 2 property, surely timber windows and doors to the rear of the property (visible from Jeffreys Place) are also needed. The request to insert UPVC frames seems degrading to the appearance of this grade 2 terrace and the Jeffreys St conservation area