


ny conflicting information found on the drawing must be reported for clarification

Under the 'control of asbestos regulations 2012' for buildings constructed before 2000, the building owner / tenant is legally obliged to manage the asbestos content within the premises. This is accomplished with an asbestos survey which will identify & make recommendations on how to manage any asbestos found. This specialist survey is not within the remit of Ampersand Associates Ltd & the client is strongly advised to check if there is already a suitable report available. If not, a "Management" asbestos survey should be instigated by the client to cover the entire building, with a further "Refurbishment & Demolition' survey being carried out, suprieng carried upon the previous previous carried LIASs commands. These surveys, and the previous carried LIASs commands. These surveys are to be made readily available not to any operations commencing.

All drawings produced adopt the principles of prevention in accordance with CDM2015 regulations. Hazards where foreseen have been considered and either designed out or managed where feasible. Any and all associated 3rd party drawings and designs must also take into account the CDM2015 principles of prevention as part of their production



Ordnance Survey (c) Crown Copyright 2018. All rights reserved. Licence number 100022432



ampersand

e: ampeampersand saroitate.com

commercial architectural design. and then some

Shaftesbury Properties Ltd 14-16 Camden High Street London NW1 0JH

Block Plan

7747\_BP