

Application No:	Consultees Name:	Received:	Comment:	Response:
2018/5338/P	David Brown	14/12/2018 17:30:32	PETITION E	<p>[REDACTED] participated in maintenance of the properties I have found that the rear extensions to both 8 and 10 have suffered subsidence and movement on no less than two occasions over 10 years, resulting in large gaps up to 30mm wide mostly visible in the first and second floors between the main body of the building and the rear extensions. As a Builder of 20 years experience I would be concerned that the properties would suffer further undesired movement given the level of works being proposed.</p>
