



TP2

London School of Hygiene & Tropical Medicine

Tavistock Place



LEGEND (ALL CHANGES TO ALL LEVELS)

- | | | | | | | | |
|--|--|--|---|--|--|--|---|
| <ul style="list-style-type: none"> ▲01 Stair 2 omitted, and glazed entrance enclosure enlarged ▲02 Window added ▲03 New steps to base of external spiral stair ▲04 Stair 3 roof and gable end arrangement revised. ▲05 Level 3 accommodation mansarded ▲06 Roof light size, height and position adjusted, and smoke vents added. ▲07 Louvres omitted. ▲08 Roof light size, height and position adjusted. | <ul style="list-style-type: none"> ▲09 External ramp adjusted, and railings added. ▲10 West stair core glazing fenestration adjusted to suit amended stair landing levels. ▲11 External paving levels in courtyard raised to achieve required paving falls. ▲12 Low brick plinth added to base of external walls to TP2. ▲13 Brick plinth added to base of existing buildings within courtyard. ▲14 New steps and landing outside room G1. ▲15 Bin store enlarged and repositioned. ▲16 Gallery passageway to TP2: finishes revised. ▲17 Gallery passageway; entrance gates design revised. | <ul style="list-style-type: none"> ▲18 Window on north elevation of TP2 reduced in length. ▲19 Revised turn-table size and position ▲20 Entrance ramp gradient and levels adjusted. ▲21 External levels adjusted ▲22 TP1 west door ramp omitted ▲23 Fall restraint added ▲24 Gates removed ▲25 Maintenance access door added ▲26 Parapet revised ▲27 Roof/wall shape adjusted ▲28 TP1 reception relocated | <ul style="list-style-type: none"> ▲29 Revised door design ▲30 Modifications to windows, doors and facades facing into courtyard. ▲31 Gate details revised ▲32 Revised proposal for bike storage replacing existing bike racks in Dairy shed. ▲33 Gate retained and modified ▲34 Bike canopy detail revised (typical condition highlighted) ▲35 Sub-station doors revised ▲36 Steps adjusted ▲37 Cladding changed to brass finish ▲38 Wall mounted planters revised (typical condition highlighted) ▲39 Steel posts added to boundary wall (typical condition highlighted) | <ul style="list-style-type: none"> ▲40 Height of glazed entrance roof increased to suit required pitch. ▲41 Glazed entrance roof and canopy revised ▲42 New roof guarding to existing flat roof ▲43 Screening fins and cladding added ▲44 Louvres added ▲45 Ramp omitted ▲46 Door removed and infilled ▲47 Access hatch adjusted. ▲48 Depth of green/blue roof build-up adjusted. ▲49 Blue roof incorporated into green roof and gravel margins added. ▲50 Cladding build-up adjusted | <ul style="list-style-type: none"> ▲51 Orientation of brass seams adjusted ▲52 Roof gutters revised. ▲53 Means of escape revisited and exit door added to TP1 ▲54 Spiral staircase landings added at each floor ▲55 Door modified ▲56 Basement louvers to external metal staircase landings ▲57 Revised proposal for mean of escape in TP1 ▲58 Revised proposal for window and door ▲59 Revised proposal for door to be left as current ▲60 Gate to be removed ▲61 Capping width adjusted and roof planters shown indicatively. | <ul style="list-style-type: none"> ▲62 Door to be replaced ▲63 Revised proposal for the entrance ▲64 Gates and Entrance door in TP1 to be replaced ▲65 Existing stair to be demolished ▲66 Existing window and door to be replaced ▲67 New reconfiguration for new spiral stair and WC ▲68 Staircase partially demolished ▲69 Level adjusted ▲70 Lift pit adjusted ▲71 Level updated ▲72 Red line extended to include South Crescent Mews | <ul style="list-style-type: none"> ▲73 Red line extended to include new ramp and frontage ▲74 Ladder added ▲75 Works to Mews paving/kerbs added ▲76 Minor adjustment to ridge, and eaves line, (not affecting ridge level noted on consented drawings). |
|--|--|--|---|--|--|--|---|

0m 2 4 6 8 10 20m