

DO NOT SCALE FROM THIS DRAWNING, CONTRACTOR TO OHECK ALL DIMENSIONS ON SITE.

ANY DISCREPANCIES TO BE REPORTED TO THE ARCHITECT IMMEDIATELY.

PLANNING

PLANNING

PLANNING

Inaccuracies. All existing locations to be confirmed on site.

Levels of slates have been revised to reflect Stering survey Jan 2018. Slab level varies, and dimensions reflect an averaged level. All levels to be confirmed on site.

Level of slates have been revised in surfaced colors to be determined on site as required, and based on H+H Report Fire Resistance of Existing Structural Elements' done January 2018.

- All services still to be confirmed by services sub-contractor including structural opening sizes and positions and to be coordinated with site constraints' or existing structural structural confirmed by services sub-contractor in existing structural structural variety of the structural structural structural confirmed by services sub-contractor design structural.

- For all worst be the listed No. 21 refer to thaveing 561-15010 and 651-15050.

- All scannor farsceres sizing and jointing TBC by sub-contractor and manufacturer. Set back of curtain walling windows from face of façade to be agreed with sub-contractor designs of segreed with sub-contractor designs of segreed with sub-contractor or activative manufacturer sizes of segreed with sub-contractor or activative manufacturer sizes of

REV DATE DESCRIPTION

To C1 04.06.18 Issued for Construction. Updated to agreed VE items, client changes; post-soft strip survey lasted to 2 18.06.19 Issued for Construction and Planning

P1 19.06.19 Issued for Planning

[§] The Honourable Society of Gray's Inn 19-21 High Holborn	Curtain Wall Jamb at Brickwork				
MICA	MK DEAWN	***651	**40122		² P1
123 Camden High Street London NW1 7JR T: 020 7284 1727 info@micaarchitects.com www.micaarchitects.com F: 020 7267 7826	онеомер МЕ	3cyre® 1:5	A3	8/17/17	19.06.19