0 0 0 0 0 0

NCR 5886 NCR 5886 CAE

ATM

Notice

Remove Remove security camera.

Fill redundant fixing and cable

holes with lime mortar to match

the stone as closely as possible

Remove tablet sign and external ATM. Remove

the stained plywood panel

through which the ATM is

fitted. Install new plywood

panel without aperture, to be stain finished to match existing.

Remove external light make good to redundant_

fixing and cable holes using wood filler.

Low Level Position

Remove 3 sets of individual letters

signs and metal back panels. To both elevations.

landing

Remove hanging projecting sign and bracket. Fill redundant fixing holes with lime mortar

to match the brickwork and stonework as

closely as possible.

PROJECT ADDRESS	SCALE
Brand - Lloyds TSB Hampstead Rosslyn Hill 40 Rosslyn Hill	A1 - 1:50 A3 - 1:100
LONDOŇ NW3 1NL	DATE
DRAWING DESCRIPTION	14/06/19
Ground Floor Proposed Plan	DRAWN BY TJ/MJ
DRAWING NUMBER 50205300-AREX-00-0110	REVISION