



Proposed Helifix Repair
Front Elevation
 (Part of)

Legend	
○	Helifix remedial ties. Helifix standard detail/spec RF01.
×	Helifix bowties. Helifix standard detail/spec RB04.
Balcony Epoxy resin inject 2No. transverse cracks through balcony slab. Fosroc nitokit epoxy or similar approved, strictly in accordance with manufactures recommendations and specification. Waterproofing top layer to be specified by Sika and installed in accordance with their recommendations and specification.	



Location Plan
 Scale 1:250

Project
STRUCTURAL DEFECTS
 Flat B
 50 ALBERT STREET
 LONDON
 NW1 7NR

Amendments
 A 2019.06.14 Helifix specification updated.

Scale 1:50, 1:1250
 Drawing No 17/076-02A

Date OCT 2018



Whymark & Moulton
 Chartered Surveyors &
 Building Engineers

14 Cornard Road, Sudbury,
 Suffolk. CO10 2XA
 Tele: 01787 371371

