| Application No: | Consultees Name: | Received: | Comment: | Printed on: 22/01/2020 09:10:12 Response: |
|-----------------|------------------------------------|---------------------|----------|---|
| 2019/5547/P | Edward & Angela Lyndon-Stanford | 12/01/2020 22:41:13 | OBJ | We object to the proposal. The house in question (No. 8) and the neighbouring No. 10 are both semi-detached and form a harmonious symmetrical pair, in the original style of a number of houses on the West side of Tanza Road. The proposed construction would spoil the look of No. 8 and of the No. 8 and No. 10 pair, completely unbalancing the construction of the pair and forming an awkward arrangement. Furthermore, the proposed dormer windows are over-large and out of proportion to the building of No. 8. Though it is a minor matter, the side elevation drawing of the present construction shows two chimney stacks - the left-hand (West) one is not there. In addition, the detailing on the side wall of the dormer window on the street/east side is not clear. Edward and Angela Lyndon-Stanford, owners of No. 2 Tanza Road. |
| 2019/5547/P | Harriett Brand | 10/01/2020 15:53:14 | INT | I am a resident and neighbour at 12 Tanza Road and I believe the application for dormer windows should be denied as this part of the road has a lovely aspect, consistent and in keeping with the conservation area. The roofline is beautiful down the hill and I can only see a jarring roofline were this building to be the exception. |