

Application No:	Consultees Name:	Received:	Comment:	Response:
2019/5948/P	Stephen Carter	16/01/2020 09:00:29	OBJ	I am concerned about noise from the proposed air conditioning units on the side of the lift shaft which will impact the top floor of 2 and 3 Hanway Place in particular including my flat. As 2 and 3 Hanway Place are not air-conditioned noise will have an even bigger impact in the summer when windows are opened. Should instead the units be placed on the roof facing upwards so noise goes up and what guarantees are there on noise output.
