

Application No:	Consultees Name:	Received:	Comment:	Response:
2020/4455/P	susan Rose	04/12/2020 14:39:14	COMMNT	The bond of all new brickwork must match that of the existing. The new side window my possibly cause overlooking and this must be taken into account
