

iron stacks, retained & painted & provided with birdguard Existing parapet retained, repaired where necessary & re-painted where previously painted Mastic sealant New metal weathering cravat fixed to stack with watertight joints & painted to match stack Code 6 lead flashing 150 min. Code 6 lead flashing Treated timber former Existing brickwork Mastic sealant

Detail 1- main roof, sunpipe rooflight section

05-10-20 Project title revised B 29-10-20 Project title revised

05-02-21 Detail I omitted

D 05-03-21 Detail I re- instated for sunpipe rooflight

Detail 2- main roof, head of stack

Retained existing or new cast

client scale date JONATHAN & 1: 5 @ A3 11-09-20 NATHALIE ESFANDI drawn checked property MPP 55 CUMBERLAND TERRACE LONDON NW1 4HJ project

PROPOSED ALTERATIONS

drawing

MAIN ROOF- DETAILS AS PROPOSED SERVICE PENETRATIONS

drawing no. 11188-10 revision

D



16 Watermark Way Foxholes Business Park Hertford Hertfordshire SGI3 7TZ 01992 300 301