SubsNetuk

Drainage Investigation Report

For Subsidence Management Services

Client

Risk Address: 34 Laurier Road, London, NW5 1SJ

Visit Date: 29th October 2020


Client Reference:

Our Reference:

Report Date: 2nd November 2020

Report Content: Front Page

Site Plan Drain Overview Photographs Quote



Classification: General



Drainage Overview



Following the receipt of your instruction, we attended site to carry out a CCTV survey.

On arrival we found there is a manhole which we were unabel to lift as it has screw thread fittings to raise it.

We also noted there is a gully in a basement area. To get to this requires access down steeply sloping ground. Due to the wet weather conditions at the time of our visit we were unable to access this area.

A revisit will need to be arranged with the correct lifting equipment to raise the manhole. We would also recommend an additional engineer is on site to assist with getting the equipment safely to the works area.

Address:

34 Laurier Road, London, NW5 1SJ

Classification: General

