

Hestur Limited

Photographs 1.

Examples of damp penetration affecting fabric of structure within lower basement (damp is extensive throughout lower ground floor – see specialist contractor proposals)



Hestur Limited

(photographs 1 contd)

