



SPRATLEY & PARTNERS 7 CENTENARY BUSINESS PARK, STATION ROAD, HENLEY-ON-THAMES, OXFORDSHIRE RG9 1DS . 01491 411277 ISSUED ONLY FOR THE PURPOSE INDICATED. THIS DRAWING TO BE READ IN CONJUNCTION WITH ALL CONSULTANTS INFORMATION. ALL DIMENSIONS TO BE CHECKED ON SITE. THIS DRAWING IS COPYRIGHT. REV. ISSUED DESCRIPTION DRAWN CHECKED - -- -

PROJECT DESCRIPTION 46-47 BS PROPOSED HOLBORN LINKS FORTH FLOOR RCP PROJECT 5 20-22 SP & 46-47 BS

EDR

PLANNING

Key

CW

DATE SCALE AT A1
JULY '21 1:50

CEILING FINISHES KEY:

CORNICE KEY

Existing Cornice

CO-02 New Plaster Cornice

CR-02 New Ceiling Rose

New pendant light.

□□□ New wall light.

Bulkhead light.

New recessed spotlight.

Recessed emergency spotlight.

CEILING ROSE KEY:

FITTINGS KEY:

CO-01

Ceiling Finish Type 01 - Existing Ceiling
Existing plasterboard ceiling retained and repaired ready for redecoration.
Any damaged or missing areas of ceiling to be replaced to match existing.

Ceiling Finish Type 03 - New MR Plasterboard New moisture resistant plasterboard under suspended metal frame.

Ceiling Finish Type 04 - Existing Bulkheads
Existing bulkheads / structural openings retained and repaired as required ready to receive decoration. Any areas of damaged plaster or beading to be removed and reinstated.

Existing cornice retained, stripped back and redecorated. Any cracking to be made good and for any new or damaged cornice to be replaced to match existing in size, material and

Ceiling Finish Type 02 - New Plasterboard New plasterboard and skim ceiling bellow timber joists.

Ceiling Finish Type 05 - Rendered Vaults New tanking membrane over rendered and decorated.

Ceiling Finish Type 06 - New Plasterboard Fourth New plasterboard and skim ceiling bellow timber joists.

New cornice to match existing within building.

CR-01 Existing Ceiling Rose Retained
Existing ceiling rose retained, prepared and redecorated to match ceiling. Existing paint to be fully stripped back before redecorating.
Any redundant fixing locations and cracking to be made good.

Lighting shown for reference only, refer to MEP information for details.

New plaster ceiling roses to match existing. New ceiling rose decorated to match ceiling.

NOTES:

1. Existing vents in-filled in line with new ceiling buildup. 2. New cornice installed to match existing locally.

5. New service risers to be sized to miss existing cornices.

9. Waterproofing extending to ceiling within RM.22.LG.05. 10. Refer to structural engineers information for structural details.

8. New concealed fire curtain to opening head.

6. Existing coal shoots in-filled. 7. New reveals to lift opening.

3. Refer to internal elevations for details on new reveal treatment.

Existing landing boxing and lobby entrance reveal retained, stripped back and redecorated.

DRAWING NO PL.1395 REV A



